



SUBJECT

Speed Limit Information Does Not Work

MODEL

F02 (7 Series Sedan, Long Wheelbase)

SITUATION

Speed limit information (SLI) is not displayed in the Kombi or the Head-Up Display (HUD). This only affects the specific VINs (vehicle identification numbers) listed below.

CAUSE

The vehicle was built incorrectly (without option 8TH).

CORRECTION

Adapt a new VO (vehicle order) which includes option 8TH (SLI) for the vehicle.

INFORMATION

VIN list:

WBAYG0C55EDZ04798	WBAYG0C52EDZ04807	WBAYG0C51EDZ04815	WBAYG0C50EDZ04823
WBAYG0C57EDZ04799	WBAYG0C54EDZ04808	WBAYG0C53EDZ04816	WBAYG0C52EDZ04824
WBAYG0C51EDZ04801	WBAYG0C56EDZ04809	WBAYG0C55EDZ04817	WBAYG0C54EDZ04825
WBAYG0C53EDZ04802	WBAYG0C52EDZ04810	WBAYG0C57EDZ04818	WBAYG0C56EDZ04826
WBAYG0C55EDZ04803	WBAYG0C54EDZ04811	WBAYG0C59EDZ04819	WBAYG0C58EDZ04827
WBAYG0C57EDZ04804	WBAYG0C56EDZ04812	WBAYG0C55EDZ04820	WBAYG0C5XEDZ04828
WBAYG0C59EDZ04805	WBAYG0C58EDZ04813	WBAYG0C57EDZ04821	
WBAYG0C50EDZ04806	WBAYG0C5XEDZ04814	WBAYG0C59EDZ04822	

PROCEDURE

Do not replace parts!

1. Verify that the vehicle being repaired is listed in the table above. If it is, go to step 3.
2. If the VIN is not listed in the table above, this SIB does not apply.
 - Continue diagnosis using ISTA.
3. Submit a PuMA case requesting the following:
 - A modified VO with option 8TH
4. Adapt the VO to the vehicle using ISTA/P.
 - Select the complete vehicle coding.
5. Once the VO adaption session is completed, select "Continue."

6. ISTA/P will generate a new measures plan.

- Download the repair-enabling code to activate the function.

Note that ISTA/P will automatically reprogram and code all programmable control modules that do not have the latest software.

For information on programming and coding with ISTA/P, refer to CenterNet / Aftersales Portal / Service / Workshop Technology / Vehicle Programming.

7. Allow the vehicle to sleep for 5 minutes.

8. Verify the function is activated via the iDrive for either the Kombi, HUD (Head-up Display), or both.

9. Perform a test drive and verify the system is functional.

- The speed limit is displayed in the Kombi or HUD.

WARRANTY INFORMATION

Covered under the terms of the BMW New Vehicle/SAV Limited Warranty.

Defect Code:	85 10 01 47 BV	
Labor Operation:	Labor Allowance:	Description:
00 00 006	Refer to KSD2	Performing “vehicle test” (with vehicle diagnosis system – checking faults)
and		
61 21 528	Refer to KSD2	Connect an approved battery charger/power supply (indicated in KSD2 as “Charging battery”)
and		
61 00 730	Refer to KSD2	Programming/encoding control unit(s)

Labor operation code 00 00 006 is a Main labor operation. If you are using a Main labor code for another repair, use the Plus code labor operation 00 00 556 instead.

Refer to KSD2 for the corresponding flat rate unit (FRU) allowance. Enter the Chassis Number, which consists of the last 7 digits of the Vehicle Identification Number (VIN). Click on the “Search” button, and then enter the applicable flat rate labor operation in the FR code field.

If control module(s) fail to reprogram or initializations are required, the additional work must be claimed using separate labor operations found in KSD2 under the defect code listed above.

Other Repairs (vehicles on the VIN list which have already had the new VO installed)

If performing ISTA diagnostics and related test plans results in other eligible and covered work, claim this work with the applicable defect code and/or labor operations listed in KSD2.