

This Service Information bulletin supersedes SI B31 01 12 dated August 2013.

NEW designates changes to this revision

SUBJECT Clicking Noise from Front Axle

MODEL

F01, F02 (7 Series Sedan)

F04 (ActiveHybrid 7)

F07 (5 Series Gran Turismo)

F10 (5 Series Sedan)

F12 (6 Series Convertible)

F13 (6 Series Coupe)

F15 (X5)

SITUATION

Clicking noises are heard from the front axle area while maneuvering at low speeds (e.g., parking lot maneuvers).

CAUSE

Movement between the contact surfaces of the wheel bearing and swivel bearing (knuckle)

PROCEDURE

Confirm the noise is coming from the front wheel bearing area and remove the front wheel bearing. Use repair kit P/N 83 19 2 298 825 to clean up the mating surfaces of the wheel bearing and the swivel bearing (steering knuckle).

The repair procedure can be found in ISTA/D: Function structure/05 Non-electrical diagnosis-NED/02 Chassis and suspension/01 Interference noise/Front axle interference noise – ABL Front axle interference noises.

PARTS INFORMATION

| Part Number | Description | Quantity |
|-----------------|-------------|----------|
| 83 19 2 298 825 | Repair kit | 1 or 2 |

NEW WARRANTY INFORMATION

Covered under the terms of the BMW New Vehicle/SAV Limited Warranty.

| Defect Code: 31 21 00 39 00 | |
|-----------------------------|--|
|-----------------------------|--|

Repairing One Side

https://www.bmwtis.net/tiscode/cgi-bin/bulletin.aspx?sie_path=/tsb/bulletins/htm_store/16180.3.B310112.... 6/8/2014

| Labor Operation: | Labor Allowance: | Description: |
|------------------|------------------|--|
| 31 21 180 | Refer to KSD | Replacing bearing of front wheel |
| and | | |
| 31 99 000 | 3 FRU | Work time to treat mating surface of wheel bearing/swivel bearing (one side) |

Or

Repairing Both Sides

| Labor Operation: | Labor Allowance: | Description: |
|------------------|------------------|--|
| 31 21 181 | Refer to KSD | Replacing bearing of both front wheels |
| and | | |
| 31 99 000 | 6 FRU | Work time to treat mating surface of wheel bearing/swivel bearing (both sides) |

Labor operation codes 31 21 180 and 31 21 181 are Main labor operations. If you are using a Main labor code for another repair, use the Plus code labor operation 31 21 578 or 31 231 584 instead.

When the front brake caliper/brake disc is removed, use 31 21 579 or 31 21 583. When the front wheel is removed, use 31 21 580 or 31 21 581.

Refer to KSD2 for the corresponding flat rate unit (FRU) allowance. Enter the Chassis Number, which consists of the last 7 digits of the Vehicle Identification Number (VIN). Click on the "Search" button, and then enter the applicable flat rate labor operation in the FR code field.

Even though work time labor operation code 31 99 000 ends in "000," it is not considered a Main labor operation. Also, since the "work time" FRU allowances to be claimed are specified, a separate punch time is not required.

ATTACHMENTS

View PDF attachment **<u>B310112 Repair Instructions</u>**.

[Copyright ©2014 BMW of North America, Inc.]