


SUBJECT
Erroneous Check Control Message: Tire Pressure Check Failed
MODEL

F56 (Hardtop 2-Door)

Produced from SOP through 02/2014

SITUATION

After pressing the Start/Stop button, Check Control message “Tire pressure check failed” appears briefly, as well as the corresponding light in the instrument cluster.

These displays disappear after a few seconds.

CAUSE

Software in the BDC (Body Domain Controller)

CORRECTION

Run the diagnostics with ISTA/D. Work through the corresponding test module. Program and code the vehicle with ISTA/P 2.52.1 or a more recent version.

- F56 – New Integration Level F056-14-03-501

WARRANTY INFORMATION

Covered under the terms of the MINI New Passenger Car Limited Warranty or the MINI NEXT Certified Pre-Owned Limited Warranty.

Defect Code:	61 38 27 02 00	
Labor Operation:	Labor Allowance:	Description:
00 00 006	Refer to KSD	Performing “vehicle test” (with vehicle diagnosis system – checking faults)
and		
61 21 528	Refer to KSD	Connect an approved battery charger/power supply (indicated in KSD2 as “Charging battery”)
and		
61 00 730	Refer to KSD	Programming/encoding control unit(s)

Labor operation code 00 00 006 is a Main labor operation. If you are using a Main labor code for another repair, use the Plus code labor operation 00 00 556 instead.

Refer to KSD2 for the corresponding flat rate unit (FRU) allowance. Enter the Chassis Number, which consists of the last 7 digits of the Vehicle Identification Number (VIN). Click on the “Search” button, and then enter the applicable flat rate labor operation in the FR code field.

If control module(s) fail to reprogram or initializations are required, the additional work must be claimed using separate labor operations found in KSD2 under the defect code listed above.

[Copyright ©2014 BMW of North America, Inc.]