

This Service Information bulletin supersedes SI B11 03 14 dated April 2014.

NEW designates changes to this revision

SUBJECT Diesel Intake Carbon Cleaning

MODEL E90 (3 Series Sedan)

With M57Y engine (335d)

SITUATION

The Service Engine Soon light is on and the engine may run roughly.

Possible Fault Codes stored:

- 3FF1 air mass sensor
- 4595 rough controller Cylinder 6
- 459B rough controller Cylinder 5
- 4592 rough controller Cylinder 4
- 4596 rough controller Cylinder 3
- 4593 rough controller Cylinder 2
- 459C rough controller Cylinder 1

CAUSE

Based on the above stored "Fault Code" profile, there is excessive carbon buildup in the intake system.

PROCEDURE

The intake valves in both the swirl and tangential ports will be cleaned, including chemical cleaning of the intake manifold.

NEW The fuel injector zero-mass adaptation values in the DDE must be cleared after the carbon-cleaning procedure is completed, and prior to test driving the vehicle.

NEW Refer to the "Clearing the Zero-mass Adaptations" at the end of the carbon-cleaning procedure.

See the PDF attachment B110314 Preliminary Work.pdf for removal of the intake manifold and valve cover.

Important!

Wear safety goggles and protective gloves.

When working on the oil, coolant or fuel circuit, you must protect the alternator from contamination. Cover the alternator with suitable materials.

Failure to comply with this procedure may result in alternator malfunction.

It is essential to adhere to conditions of absolute cleanliness when carrying out repair work on the fuel system.

- Do not allow any dirt particles or foreign bodies to get into the system.
- Use only fluff-free cloths.
- Remove all traces of dirt contamination before dismantling lines or separate components.
- Seal all fuel system openings with protective caps.

Recycling:

Catch and dispose of escaping fuel.

Observe country-specific waste disposal regulations.

This procedure supersedes Repair Instruction RA 1112800, "Cleaning cylinder head intake channels and intake plenum (E90US, M57T2)" found in ISTA/D.







Use only 20/30 SAE or 0.45-0.80mm walnut shells which can be sourced locally or through one of the following distributors:

MARCO® Corporate - 800 252 7848 Ext. 284 - marcousa.com/index.cfm

Trinity Tool Company - 800 587 4626 - trinco.com

McMASTER-CARR® - mcmaster.com







CLEANING THE INTAKE MANIFOLD Note:

Unless it is necessary for another reason, replacing the intake manifold is not required when performing this procedure.







Recommended procedure for Manifold Cleaning

Send the intake manifold and swirl flaps to an engine machine shop or equivalent automotive parts repair/reconditioning (i.e., radiator repair shop) facility for ultrasonic cleaning or a suitable, mild solvent parts cleaning "hot tank" process. Ensure that all ports, swirl and tangential flaps are toughly cleaned.





CARBON BLASTING CYLINDER HEAD















Remove locking pin 11 6 080 from the flywheel and continue to the next cylinder for cleaning.

Reassemble the cleaned intake manifold and manifold components, and install the EGR valve and throttle valve onto the intake.

Install the valve cover and intake manifold and check the vehicle after repairs for leaks (air or fuel). Connect to ISTA/D and clear faults. Test drive vehicle and recheck for fault codes and repair/correct as necessary.

NEW Clearing the Zero-mass Adaptations

Submit a PuMA Case titled "M57Y Zero-mass Adaptation."

- 1. Set the vehicle up for an IRAP session.
- 2. The IRAP team will flash the DDE with a temporary dataset and reset the zero-mass (NMK) values.
- 3. When instructed by the IRAP team: Turn KL-15 off / engine is started briefly / engine is turned off / switch to KL-0 and let the vehicle go to sleep.

The vehicle must then be programmed with the latest version of ISTA/P to install the latest working DDE software.

The DDE may need to be manually added to the measures plan.

- 4. Start the engine and let it warm up (max. ten minutes). Drive the car safely and manually select gear 3 or 4. Accelerate from 1500 to 2500 rpm release the throttle and let the vehicle coast down to idle speed. Repeat this 10 times.
- 5. Reconnect to ISTA to send FASTA and clear the fault memory.

Test drive vehicle and recheck for fault codes and repair/correct as necessary.

PARTS INFORMATION

Note:

Unless it is necessary for another reason, replacing the intake manifold is not required when performing this procedure.

Part Number	Description	Quantity
13 62 7 796 699	O-ring, camshaft position sensor	1
11 12 7 796 378	Valve cover gasket	1
11 61 7 790 198	Gasket, intake	6
11 61 2 246 945	Gasket, intake	6
11 61 2 245 439	Gasket, EGR valve to intake	1
13 62 7 792 261	Grommet, pressure sensor	1
13 54 7 792 098	O-ring, throttle to EGR valve	1
13 53 7 794 553	O-ring, leakage lines	6
13 53 7 787 236	O-ring, injector	6
13 53 2 247 156	Washer, injector	6
13 51 2 248 189	Washer, fuel return line	2
07 14 6 963 730	Torx bolt M10 X 16-10.9	2
07 14 6 954 965	ASA Bolt with circlip M12 x 1.5 x 39	1

WARRANTY INFORMATION

Covered under the terms of the BMW New Vehicle/SAV Limited Warranty or the BMW Certified Pre-Owned Program.

Defect Code:	11 12 03 76 00	
Labor Operation:	Labor Allowance:	Description:
00 00 006	Refer to KSD2	Performing "vehicle test" (with vehicle diagnosis system – checking faults)
and		
61 21 528	Refer to KSD2	Connect an approved battery charger/power supply(indicated in KSD2 as "Charging battery")

Page	16	of	17
------	----	----	----

and		
11 12 601	Refer to KSD	Removing and installing/sealing the cylinder head cover (includes removing and installing the intake manifold)
and		
11 99 000	NEW 38 FRU	Work time for disassembling, assembling the intake manifold and cleaning the applicable removed parts. Also included is carbon-cleaning the valves of the 6 cylinders.

Labor operation code 00 00 006 is a Main labor operation. If you are using a Main labor code for another repair, use the Plus code labor operation 00 00 556 instead.

NEW If the microfilter casing is already removed to perform another repair, use the associated labor operation 11 12 614 instead of 11 12 601.

NEW And:

NEW Zero-Mass Adaptation

NEW Labor Operation:	Labor Allowance:	Description:
61 00 730	Refer to KSD2	Programming/encoding control unit(s)
and		
13 00 003	3 FRU	Checking function of the Digital Diesel Electronics (Work time to perform Procedure step #5)
and		
61 00 980	Refer to KSD2	Continue vehicle test and performing Quick delete (Procedure step #6)
and		
13 99 000	3 FRU	End vehicle test and test drive to check the status of the SES light (Work time to perform Procedure step #7)

NEW Refer to KSD2 for the corresponding flat rate unit (FRU) allowance. Enter the Chassis Number, which consists of the last 7 digits of the Vehicle Identification Number (VIN). Click on the "Search" button, and then enter the applicable flat rate labor operation in the FR code field.

If a control module or component was working properly and/or had no related faults stored prior to vehicle programming and it fails to program correctly or requires initialization, this additional work must be claimed with separate labor operations under the defect code listed above; refer to KSD2.

NEW Repairs to control modules and components with preexisting conditions are not eligible to be claimed under

the defect code listed in this bulletin.

Even though work time labor operation codes 11 99 000 and 13 99 000 both end in "000," they are not considered a Main labor operations. Also, since the "work time" FRU allowances to be claimed are specified, separate punch times are not required.

Sublet - Cleaning the Intake Manifold

Sublet Code 3	Sublet amount; see below	Reimbursement for third-party repair
---------------	--------------------------	--------------------------------------

Invoice this eligible sublet work on the repair order at the actual cost charged with no handling or markup. The sublet amount must also include any discounts or allowances. Itemize the sublet amount in the claim comment section.

ATTACHMENTS

View PDF attachment B110314_1174_Vacuum_System_Arrangement_(M57T2TOP_SCR).

View PDF attachment **B110314 Preliminary Work**.

View PDF attachment **B110314_BMW_Group_Carbon_Blaster**.

[Copyright ©2014 BMW of North America, Inc.]