

Wind noises at front door above 70 MPH.

Topic number	LI72.00-P-058634
Version	1
Design group	72.00 General
Date	03-04-2014
Validity	MODEL 222
Reason for change	
Reason for block	

Complaint:

Wind noises at the front door above 70 MPH.

Cause:

The main seal has insufficient contact with the body in the rear and/or upper area, see Figure 1.

Attachments	
File	Designation
Bild 1.jpg	Figure 1

Remedy:

Adjust front door inwards with aid of lock striker until the optimum setting is achieved, see Figure 2.

Note: If necessary, the front door must be adjusted inwards by loosening the hinges on the door.

After adjusting the front door, the rear door must be adjusted to match the front door.

Attachments	
File	Designation
Bild 2.jpg	Figure 2

Symptoms

Body / Door/Flap / Door / Door / Inaccurate fit

Work units

Op. no.	Operation text	Time	Damage code	Note
			72A01 51	Left front door
			72N01 51	Right front door
			73A01 51	Left rear door
			73A01 51	Right rear door

WIS-References			
Document number	Title	Note	Allocation
AR72.10-P-0550LF	Adjust front door		Remedy
AR72.12-P-0650LF	Adjust rear door		Remedy

Validity		
Vehicle	Engine	Transmission
S (222)	*	*

Full model designation breakdown		
Vehicle	Engine	Transmission
222.004	651.921	724.208
222.032	642.861	722.903
222.032	642.861	725.011
222.033	642.867	722.966
222.057	276.960	724.206
222.057	276.960	725.011
222.077	157.985	722.931
222.082	278.929	722.909
222.082	278.929	725.011
222.085	278.929	722.967
222.085	278.929	725.041
222.104	651.921	724.208
222.123	642.861	722.903
222.123	642.861	725.011
222.132	642.861	722.903
222.132	642.861	725.011
222.133	642.867	722.966
222.157	276.960	724.206
222.157	276.960	725.011
222.162	276.824	722.904
222.162	276.824	725.011
222.165	276.824	722.904
222.165	276.824	725.011
222.176	277.980	722.932
222.177	157.985	722.931
222.178	157.985	722.971
222.179	279.980	722.932
222.182	278.929	722.909
222.182	278.929	725.011
222.185	278.929	722.967

XENTRY

222.185	278.929	725.041
---------	---------	---------