

SERVICE CAMPAIGN BULLETIN

CAMPAIGN REF: 02T
TITLE : IRIS Software Update to Platform 8.1 Federal Markets Only
DOCUMENT # : 11 M 075
AFFECTED VEHICLES : 650S Coupe and Spider

SITUATION : Quality Engineering at McLaren Automotive have released a new software platform for the McLaren 650S.

The most noticeable customer benefits of this software are:

- Reverse camera picture frozen.

PROCEDURE : It is necessary to update the software on all vehicles within your Aftersales car parc, both when carrying out Pre-Delivery Inspections (PDI) and at the next service centre visit.

MODULE	NEW SOFTWARE PART NUMBERS
Head Unit / IRIS (HU)	11M2910CP.24 Rest of World

IRIS AIS APPLICATION SOFTWARE UPDATE


Care Point: Software will be supplied via WeTransfer to dealers.

1. Press the Settings button on the IRIS console.



Care Point: Software update requires the vehicle to be in ignition state 5.

Care Point: The USB drive must be engaged with the gold contact points facing downwards.

2. Insert the Application Software USB drive into the USB socket.
3. Select About (1).




4. Select Update Product (2) and then Update by USB Stick (3).




5. The following screen will be displayed (4). Select OK (5) for the loading operation to start.




6. The following screen will be displayed (6) and the system will reboot.



7. Once the system has been rebooted the following screen will be displayed (7).




8. Once the installation has finished the following screen will be displayed (8) and the system will reboot.




9. Press the Settings button on the IRIS console.

Care Point: Performing Factory Data Reset will delete the stored radio stations and paired phones.

10. Select Advanced Settings (9).



11. Select Privacy (10) in order to access the Factory Data Reset.



12. Select Factory Data Reset.

13. Place the vehicle into a sleep mode, and then establish the vehicle back into ignition state 5.

Please contact your Regional Aftersales Manager should you have any questions relating to the information contained in this bulletin.

WARRANTY INFORMATION

DESCRIPTION	RESOLUTION CODE	TOTAL REPAIR TIME
Module Platform Update to 8.1	M0M40143A33B4R07	0.20 hours

PARTS INFORMATION

PART DESCRIPTION	PART NUMBER	QUANTITY	ORDER PROCESS
N/A	N/A	N/A	N/A