

2014 Rogue Push Button Ignition Switch  
Quality Hold Update: Dealer Service Action

Reference: PC300  
Date: June 20, 2014



Innovation  
that excites

Attention: Dealer Principal, Sales, Service & Parts Managers

**\*\*\*\*\*Dealer Announcement\*\*\*\*\***

On June 18<sup>th</sup>, Nissan issued a quality hold on specific 2014 Rogue vehicles in dealer inventory and provided instructions to replace the push button ignition switch on vehicles identified in SERVICE COMM with I.D. PC300. The affected vehicles are either currently in dealer inventory or assigned and in transit to the dealer.

The original VIN list provided with the initial announcement contained 29 vehicles that are not equipped with push-button ignition. **These 29 vehicles are exempt from the repair and are no longer subject to the quality hold.**

There are now 136 affected vehicles remaining in dealer inventory or assigned and in transit to dealers. Service departments can complete an inquiry on SERVICE COMM – **I.D. PC300** - to determine if a vehicle is subject to this dealer inventory service action.

As a courtesy, posted with this announcement is a list of affected dealer inventory VINs by region, district, and Dealer Code. Vehicles removed from this action are also shown on the **vehicles removed** tab. The incorrectly identified vehicles will be turned off in SERVICE COMM on 6/20/14 and no further dealer action is required. Updated parts shipment and order numbers are also included.

**IMPORTANT: Dealers must not sell any affected 2014 Rogue vehicles in dealer inventory subject to this service action until the push button ignition switch has been replaced.**

**Thank you for your prompt attention to this matter and we apologize for the inconvenience.**

**NISSAN NORTH AMERICA, INC.**  
Aftersales DIVISION