

# NISSAN BULLETIN 2015 Altima and 2014 Sentra OCS Dealer Service Action

Reference: PC324, PM462 Date: December 15, 2014

Attention: Dealer Principal, Sales, Service & Parts Managers

#### \*\*\*\*\* Dealer Announcement \*\*\*\*\*

Nissan is conducting a Dealer Inventory Service Action to replace the Occupant Classification System (OCS) Control Unit on **41** certain specific 2015 Nissan Altima and 2014 Sentra vehicles currently in dealer inventory.

Due to a manufacturing issue at the OCS supplier that has since been corrected, a very small population of some of the control modules may have been manufactured out of specification. The OCS control module will need to be replaced in these vehicles to ensure correct OCS operation.

#### \*\*\*\*\* What Dealer Should Do \*\*\*\*\*

To ensure customer satisfaction, dealers are asked to perform the following repair procedure prior to sale. Once repaired, vehicles can be sold without further action.

- 1. Verify the subject vehicle is affected by this service Action using SERVICE COMM I.D.
  - PC324 2015 Altima
    - PM462 2014 Sentra
- 2. Locate the vehicle in inventory and perform the attached procedure.
- 3. File the warranty claim and release the vehicle for sale.

**NOTE:** Parts have already been sent to your dealership for this action. If replacement parts are needed, order one of the following:

- 98856-9HN0A (Altima)
- 98856-9AM0A (Sentra)

#### \*\*\*\*\* Vehicle Identification – Dealer Inventory \*\*\*\*\*

**22 2015 Nissan Altima and 19 2014 Sentra vehicles** subject to this Dealer Service Action can be identified through two methods:

- SERVICE COMM <u>Beginning December 16<sup>th</sup></u>, dealer service departments can complete an inquiry on SERVICE COMM to determine if a vehicle is subject to this Dealer Inspection.
  - PC324 2015 Altima
  - **PM462 2014 Sentra**
- **VIN List** As a courtesy, posted with this announcement is a list of affected dealer inventory VINs by region, district, and Dealer Code.

#### \*\*\*\*\* Dealer Responsibility \*\*\*\*\*

It is the dealer's responsibility to check SERVICE COMM for the status on each vehicle which is currently in inventory. Nissan requests dealers to perform this repair on any vehicles in their inventory before they are retailed to ensure customer satisfaction.

#### \*\*\*\*\* Repair Procedure \*\*\*\*\*

This inspection procedure will be available on ASIST and NNAnet.com.

- ASIST Go to "Tech Support Info" on the left column of the ASIST opening page. Under "Tech Support Info", select "Inventory Vehicle Actions". A new window will open where you may access the technical procedures.
- NNAnet.com Beginning Tuesday, December 15<sup>th</sup>, this procedure can be found on NNAnet.com under My Documents in the following categories:
  - Sales>Campaigns>
  - Parts>Campaigns>
  - Service>Campaigns>

NISSAN NORTH AMERICA, INC.

Aftersales DIVISION

#### PC324 - Altima (L33) OCS Control Unit SERVICE PROCEDURE

**CAUTION:** Handle interior trim carefully to avoid damage. Work with clean hands and clean tools to avoid dirt and stains. Use protective covers as needed.

**WARNING:** This procedure involves working under the passenger seat. The metal seat frame has sharp edges.

NOTE: Make sure to follow this procedure exactly as specified (<u>including</u> <u>torque specifications</u>) to ensure proper operation of the Occupant Classification System.

1. WARNING: The Ignition must be turned off and remain off during replacement of the Occupant Classification (OCS) Control Unit.

The following are **VERY IMPORTANT** to prevent unexpected air bag deployment.

- Remove the ignition key / Intelligent Key from the cabin of the vehicle and set aside, away from the vehicle. This will prevent accidentally turning the ignition ON.
- Make sure the ignition remains OFF until after the procedure is complete.
- Wait for all control units to "power down" (at least 3 minute) after the ignition is turned OFF.
- 2. Move passenger seat to full forward position.
- 3. Remove the passenger seat rear retaining bolts.



Figure 1

4. Move passenger seat to full back position.



- 5. Remove the passenger seat track slide covers (if applicable).
  - Release the four pawls on each front slide cover as shown in Figures 2 and 3.





Figure 3



Figure 4

6. Remove the passenger seat front retaining bolts.

- 7. Locate passenger seat OCS Control Unit.
  - Lift the front of the passenger seat to rock it back.
  - The OCS Control Unit is on the forward edge of the passenger seat (Figure 5).
  - Be careful to not over-extend the passenger seat harness.



Figure 5



Figure 6

- 8. Unplug the OCS Control Unit connector.
- 9. Remove OCS Control Unit from passenger seat.
  - Remove two retaining screws.

**Note:** The removed OCS Control Unit will need to be returned through the Nissan Parts Return System.

- 10. Install a <u>NEW</u> OCS Control Unit to passenger seat.
  - Install two retaining screws.
  - Install the OCS control unit connector.
- 11. Reinstall passenger seat to floor in reverse order of removal.
  - Be careful to not damage the passenger seat harness during seat installation.
  - Torque passenger seat bolts to: 49 N•m (5.0 kg-m, 36 ft-lb)
- 12. Perform Zero Point Reset and check for DTCs; next page.

#### Zero Point Reset / Check for DTCs

- 1. Attach the CONSULT-III plus (C-III plus) VI to the vehicle.
- 2. Prepare the vehicle for Zero Point Reset.
  - Place the vehicle in a level area.
  - Minimize vibrations near the vehicle.
  - Remove any objects on the passenger seat.
  - No occupants in the vehicle including the servicing technician.
  - Close all of the vehicle doors.
  - Do not touch the vehicle during zero point reset.
- 3. Place the CONSULT PC outside the vehicle and away from the vehicle.
- 4. Turn the ignition ON and start C-III plus.
- 5. Wait for the plus VI to be recognized.
  - The serial number will display when the VI is recognized.
- 6. Select Diagnosis (One System).

is ed Connection Status			
100000000		Diagnosis Menu	Ste
Serial No.	Status	Diagnosis (One	System)
VI 2300727 No	rmal Mode/Wireless connection	Diagnosis (All S	ystems)
Mi -	$\otimes$		
	No connection	C Re/programming	g, Configuration
Select VI/MI		Immobilizer	
Application Setting		Maintenance	

Figure Z1

## 7. Select OCCUPANT DETECTION.

Spanet Party	in ordinan (		
NISSANINFINIT	Re	nut l	X-Dadge
Group	Ail syster	"* Step 7	
SONAR	POP UP HOOD	TOTAL 1 CIU	CHARGERIPD MODULE
LANE CAMERA	AUTO BACK DOOR	OCCUPANY DETECTION	PTC HEATER
ADAPTIVE LIGHT	Diag Data Recorder	BRAKE	TELEWATICS
AUTO SLIDE DOOR RIGHT	4WAS(FRONT)	SIDE RADAR LEFT	ENCH
CAN GATEWAY	E-8U8	ANC	Β¥Τ.
SHIFT	ACCELE PEDAL ACT	MULTIDEPLAY	85W
EVINEY	HV BATTERY	SIDE RADAR RIGHT	AVM

Figure Z2

8. Wait for System Call to complete.

## 9. Select Zero point reset function.

## 10. Select Start.

CONSULT-III plus Ver.25.10 VIN:-	Vehicle : -	Country : U.S.A
Back Stores Stores	Recorded Note 12.	😒 💻 🛋 🕺 🕅
Diagnosis (One System Selection	DCCUPANT DETECTION	
The Work support		
Test Item		
Zero point reset Nunction		
Step	9	
	-	
		Step 10
		Start
	1/1	

Figure Z3

#### 11. Select Next.

CONSULT-III plus Ver.25.10 Ver.CSP18.11 Back Rome Print Screen	VIN -	Vehicle : -		Country : U.S.A
Biagnosis (One System Si System) System Si Work support : Zero point reset function	lection DCCUPAN DETECTIO	IT N		
		Step 11		Next
Current status		Waitir	ng for your operatio	on
Zero point reset current status				
				_
				End

Figure Z4

#### 12. Select Start.

CONSULT-III plus Ver.25.10 Ver.CSP18.11	VIN-	Vehicle : -	0	Country U.S.A
Back Bome Print Screen	Sareen Capture Mode	Recorded nulp	12.1V VI	× = _ X
Diagnosis (One System)	Selection DETER	PANT		
Vork support : Zero point reset funct	on			
Start zero point reset. Check the fo Do not put any object on the pass Do not sit on the passenger seat. The seat back is in the standard p After checking, touch "START".	llowing enger seat. losition.	Step		Start
Current status				
Zero point reset current status			Already perfo	irmed
				End
				Eng

Figure Z5

## NOTE: Zero Point Reset must be performed even if:

- "Current status" indicates "Completed", or
- "Zero point reset current status" indicates "Already performed"

13. Wait for Zero Point Reset to complete.

CONSULT-III plus Ver.CSP18.11 VIN-	Vehicle : - Country : U.S.A.
Back Rome Print Screen Screet Moder	Recorded Nop 12.9V VI MI
Biagnosis (One System Selection DCCUP System)	ANT
fork support : Zero point reset function	1400
Please wait	
Do not touch to passenger seat.	Start
Current status	EXECUTING
Zero point reset current status	
	6
	End

Figure 26

## If Zero Point Reset will not complete:

NOTE: If Zero Point Reset will not complete, it is likely that something in the Service Procedure was not followed exactly as instructed.

- a. Turn the ignition OFF.
- b. Make sure all electrical connectors under the seat are securely connected.
  - Body harness to seat harness.
  - OCS sensors
  - OCS Control Unit.
- c. Try Zero Point Rest again.

14. Make sure that "Current status" is **Completed**.

CONSULT-III plus Ver 25:21 Ver CSP18:11	VIN:- Vehicle : -	Country : U.S.A
Back Bome Print Screen	Housement Recorded Map	🚓 🌇 🗙 🖿 🔜 🔀
Diagonsis (One System Se System) System	ection DCCUPANT DETECTION	
Work support : Zero point reset function		
Zero point reset completed successfully	Ste	p 14
Current status		Completed
Zero point reset current status		Already performed
		End

Figure Z7

## 15. Select **Home** on C-III plus.

## 16. Check for Air Bag DTCs.

Navigate C-III plus to:

## Diagnosis (One System) ⇒ AIR BAG ⇒ Self Diagnostic Results

- No Air Bag DTCs stored go to the next step.
- DTC B00A0 stored (current or past) erase stored code, then go to the next step.
- Other DTCs stored: Refer to ASIST and the Service Manual for additional diagnostic and repair information. Issues other then replacement of the OCS control unit are <u>not coved by this dealer action</u>.

17. Close C-III plus, turn the ignition OFF, and disconnect from the vehicle.

18. Turn the ignition ON and observe the air bag warning light:

• Light should illuminate for 7 seconds and then go out.

**NOTE:** If the Air Bag Warning light does not operate as described above there may be an issue not covered by this dealer action. Refer to ASIST and the Service Manual for additional diagnostic and repair information.

## PARTS INFORMATION

DESCRIPTION	PART #	QUANTITY
Controller Assy-Occupant Sensor (OCS Control Unit)	98856-9HN0A	1

## **CLAIMS INFORMATION**

# Submit a "CM" line claim using the following claims coding:

CAMPAIGN ("CM") I.D.	DESCRIPTION	OP CODE	FRT
PC324	Replace OCS Control Unit	PC3240	0.5 hrs.

#### PM462 - Sentra (B17) OCS Control Unit SERVICE PROCEDURE

**CAUTION:** Handle interior trim carefully to avoid damage. Work with clean hands and clean tools to avoid dirt and stains. Use protective covers as needed.

**WARNING:** This procedure involves working under the passenger seat. The metal seat frame has sharp edges.

NOTE: Make sure to follow this procedure exactly as specified (<u>including</u> <u>torque specifications</u>) to ensure proper operation of the Occupant Classification System.

1. WARNING: The Ignition must be turned off and remain off during replacement of the Occupant Classification (OCS) Control Unit.

The following are **VERY IMPORTANT** to prevent unexpected air bag deployment.

- Remove the ignition key / Intelligent Key from the cabin of the vehicle and set aside, away from the vehicle. This will prevent accidentally turning the ignition ON.
- Make sure the ignition remains OFF until after the procedure is complete.
- Wait for all control units to "power down" (at least 3 minute) after the ignition is turned OFF.
- 2. Move passenger seat to full forward position.
- 3. Remove the passenger seat rear retaining bolts.



Figure 1

- 4. Move passenger seat to full back position.
- 5. Remove the passenger seat front retaining bolts.



Figure 2

- 6. Locate passenger seat OCS Control Unit.
  - Lift the front of the passenger seat to rock it back.
  - The OCS Control Unit is on the forward edge of the passenger seat (Figure 3).
  - Be careful to not over-extend the passenger seat harness.



Figure 3

- 7. Unplug the OCS Control Unit connector.
- 8. Remove OCS Control Unit from passenger seat.
  - Remove two retaining screws.
- **Note:** The removed OCS Control Unit will need to be returned through the Nissan Parts Return System.



Figure 4

- 10. Install a <u>NEW</u> OCS Control Unit to passenger seat.
  - Install two retaining screws.
  - Install the OCS control unit connector.
- 11. Reinstall passenger seat to floor in reverse order of removal.
  - Be careful to not to damage the passenger seat harness during seat installation.
  - When installing the passenger seat, tighten the bolts in order shown in Figure 5.
  - Torque passenger seat bolts to: 40 N•m (4.1 kg-m, **30 ft-lb**)



12. Perform Zero Point Reset and check for DTCs; Next page.

#### Zero Point Reset / Check for DTCs

- 1. Attach the CONSULT-III plus (C-III plus) VI to the vehicle.
- 2. Prepare the vehicle for Zero Point Reset.
  - Place the vehicle in a level area.
  - Minimize vibrations near the vehicle.
  - Remove any objects on the passenger seat.
  - No occupants in the vehicle including the servicing technician.
  - Close all of the vehicle doors.
  - Do not touch the vehicle during zero point reset.
- 3. Place the CONSULT PC outside the vehicle and away from the vehicle.
- 4. Turn the ignition ON and start C-III plus.
- 5. Wait for the plus VI to be recognized.
  - The serial number will display when the VI is recognized.
- 6. Select Diagnosis (One System).

CONSUL	T-III plus Ver.V12.1	2.00 VIN:-	Vehicle : -	Country : U.S.A.
de . Back	finante Print Sc	reen Sureen Mode Rec	erded D 112V	🖬 🕺 🖿 🔜 🔀
is ed Connec	tion Status		Diagnosis Menu	Ste
. –	Serial No.	Status	Diagnosis (O	ne System)
VI	2300727	>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>	Diagnosis (Al	I Systems)
м	•	No connection		ing Configuration
8.0	Select VI/MI	No connection	C Reprogramm	ing, configuration
00			Immobilizer	
Applicat	ion Setting			
(	Sub mode	ABC Language Setting	Maintenance	
	en une planado			
60	(1822)	1		
22	/DR			
641		(B)		

Figure Z1

## 7. Select OCCUPANT DETECTION.

	~		2010/2020
NESSANENPINIT	Re	the	X-Badge
Group	Ail syster	"* Step 7	
SONAR	POP UP HOOD	TOTAL I CAU	CHARGERIPD WOOLLE
LANE CAMERA	AUTO BACK DOOR	OCCUPANT DETECTION	PTC HEATER
ADAPTIVE LIGHT	Diag Data Recorder	DRAVE	TELEMATICS
AUTO SLIDE DOOR RIGHT	4WAS(FRONT)	SIDE RADAR LEFT	ENCH
CAN GATEWAY	E-8U8	AKC .	BYT.
SHET	ACCELE PEDAL ACT	NULTIDISPLAY	BSW
EVILLEY	HV BATTERY	SIDE RADAR RIGHT	AVM

Figure Z2

8. Wait for System Call to complete.

## 9. Select Zero point reset function.

## 10. Select Start.

CONSULT-III plus Ver	25.10 CSP18.11VIN:	Vehicle : -	Country : U.S.A
Back Borns P	fint Screen Sureen Mountament	Recorded Data	🚗 🌇 🗙 🖿 🔜 🔀
Diagnosis (One System)	System Selection	SUPANT	
Work support			
Test Item			
Zero poin	t reset Sunction		
	Step 9		
	· ·		
			Step 10
L		)	Start

Figure Z3

#### 11. Select Next.

CONSULT-III plus Ver.25.10 Ver.CSP18.11 Back Rome Print Screen	VIN-	Vehicle : -		Country : U.S.A
Biagnosis (One System Si System) System Si Work support : Zero point reset function	lection DCCUPAN DETECTIO	AT		
		Step 11		Next
Current status		Waitin	g for your operatio	n
Zero point reset current status				
				_
				End

Figure Z4

#### 12. Select Start.

CONSULT-III plus Ver.25.10 Ver.CSP18.11	VIN:-	Vehicle : -		Country : U.S.A
Back Bone Print Screen	Sureen Cepture	Recorded Data	12.1V VI	x 🖿 📃 🔀
Diagnosis (One System)	n Selection DC	CUPANT TECTION		
Work support : Zero point reset func	tion			
Start zero point reset. Check the f -Do not put any object on the pas- -Do not sit on the passenger seat -The seat back is in the standard After checking, touch "START".	ollowing senger seat. position.	Step	12	Start
Current status				
Zero point reset current status			Already perfo	rmed
1				
				End

Figure Z5

## NOTE: Zero Point Reset must be performed even if:

- "Current status" indicates "Completed", or
- "Zero point reset current status" indicates "Already performed"

13. Wait for Zero Point Reset to complete.

CONSULT-III plus Ver.25.10 VIN-	Vehicle : - Country : U	s.a
Back Rome Print Screen Screen Mousement Notes	Recorded wip 12.3V VI MI	
Diagnosis (One System Selection DC)	CUPANT TECTION	
ork support : Zero point reset function		_
Picase wait		
Do not touch to passenger seat.	St	art
		2
Current status	EXECUTING	
Zero point reset current status		
	r	
	E	nd
	(19)	

Figure 26

## If Zero Point Reset will not complete:

NOTE: If Zero Point Reset will not complete, it is likely that something in the Service Procedure was not followed exactly as instructed.

- a. Turn the ignition OFF.
- b. Make sure all electrical connectors under the seat are securely connected.
  - Body harness to seat harness.
  - OCS sensors
  - OCS Control Unit.
- c. Try Zero Point Rest again.

14. Make sure that "Current status" is **Completed**.

CONSULT-III plus Ver 25.21 Ver CSP18.11	/IN	Vehicle : -	Country : U.S.A.
Back Bome Print Screen	en Moster Recorded	0 Nup 12.3V V	i 💥 🖿 🔚 🔀
Diagnosis (One System Sat	ction CCCUPANT DETECTION		
Work support : Zero point reset function			
Zero point reset completed successfully	6	Step 14	Retry
Current status		•	Completed
Zero point reset current status		Already	performed
			End

Figure Z7

## 15. Select **Home** on C-III plus.

## 16. Check for Air Bag DTCs.

Navigate C-III plus to:

## Diagnosis (One System) ⇒ AIR BAG ⇒ Self Diagnostic Results

- No Air Bag DTCs stored go to the next step.
- DTC B00A0 stored (current or past) erase stored code, then go to the next step.
- Other DTCs stored: Refer to ASIST and the Service Manual for additional diagnostic and repair information. Issues other then replacement of the OCS control unit are <u>not coved by this dealer action</u>.

17. Close C-III plus, turn the ignition OFF, and disconnect from the vehicle.

18. Turn the ignition ON and observe the air bag warning light:

• Light should illuminate for 7 seconds and then go out.

**NOTE:** If the Air Bag Warning light does not operate as described above there may be an issue not covered by this dealer action. Refer to ASIST and the Service Manual for additional diagnostic and repair information.

#### PARTS INFORMATION

DESCRIPTION	PART #	QUANTITY
Controller Assy-Occupant Sensor (OCS Control Unit)	98856-9AM0A	1

#### **CLAIMS INFORMATION**

# Submit a "CM" line claim using the following claims coding:

CAMPAIGN ("CM") I.D.	DESCRIPTION	OP CODE	FRT
PM462	Replace OCS Control Unit	PM4620	0.5 hrs.