

TECHNICAL BULLETIN

LTB00348NAS3

07 MAR 2014



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

This reissue replaces all previous versions. Please destroy all previous versions. Only refer to the electronic version of this Technical Bulletin in TOPIx.

Changes are highlighted in gray

SECTION: 417-01

Water Ingress Through High-Mounted Stop Lamp

AFFECTED VEHICLE RANGE:

LR2 (LF)

Model Year: 2008 Onwards
VIN: 8H000001 Onwards

MARKETS:

NAS

CONDITION SUMMARY:

Situation: Water may enter the vehicle through the high-mounted stop lamp area.

Cause: This may be caused by water passing through the high-mounted stop lamp seal.

Action: Should a customer express this concern, follow the Service Instruction outlined below.

PARTS:

STC50550 PU Sealant Quantity: 1

TOOLS:

No Tools Required

WARRANTY:

 **NOTE:** Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPIx to obtain the latest repair time.

 **NOTE:** DDW requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.


DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Apply sealant to the high-mounted stop lamp	86.41.89/27	0.2	D8	LR014462

 **NOTE:** Normal Warranty policies and procedures apply.

SERVICE INSTRUCTION:

1. Remove the high-mounted stop lamp for access (see TOPIx Workshop Manual, section 417-01).
2. Clean and dry the sealing faces of the high-mounted stop lamp foam seal and the vehicle body.

3. Apply a 3mm bead of PU Sealant STC50550 to the sealing face of the high-mounted stop lamp foam seal.



4.  **CAUTION: Allow 24 hours before power washing the vehicle.**

Install the high-mounted stop lamp (see TOPIx Workshop Manual, section 417-01).