



**NUMBER:** 08-102-14

**GROUP:** Electrical

**DATE:** November 25, 2014

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of Chrysler Group LLC.*

**HELP USING THE wiTECH DIAGNOSTIC APPLICATION FOR FLASHING AN ECU IS AVAILABLE BY SELECTING “HELP” THEN “HELP CONTENTS” AT THE TOP OF THE wiTECH DIAGNOSTIC APPLICATION WINDOW.**

**THE wiTECH SOFTWARE LEVEL MUST BE AT RELEASE 15.02 OR HIGHER TO PERFORM THIS PROCEDURE.**

***SUBJECT:***

Flash: IPC Software Enhancements

***OVERVIEW:***

This bulletin involves upgrading the software in the Instrument Panel Cluster (IPC).

***MODELS:***

2014                      (KL)                      Jeep Cherokee

**NOTE: This bulletin applies to vehicles equipped with 2.4L L4 MULTIAIR engine (sales codes ED6) or 3.2L V6 engine (sales codes EHB).**

***SYMPTOM/CONDITION:***

The customer may experience one or all of the following:

- IPC may display the wrong translations in all languages ( APAC Market excluded).
- “Low Battery Voltage” text message shown erroneously in the EVIC.

***DIAGNOSIS:***

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in TechCONNECT, verify no DTC's are set. If DTCs are present record them on the repair order and repair as necessary before proceeding further with this bulletin.

If the customer describes the symptom perform the repair procedure.

**REPAIR PROCEDURE:**

**NOTE: Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charger voltage to climb above 13.5 volts during the flash process.**

**CAUTION:** The Instrument Panel Cluster (IPC) Electronic Control Module (ECU) has a long FLASH reprogramming completion time. Please verify the following on your Personal Computer (PC) before attempting to update this ECU. PC must be running on AC power supply only. PC hard drive must NOT be set to turn off in a period of time. PC must NOT be scheduled to go into sleep or standby mode. PC screen saver must be turned off. PC monitor must NOT be set to turn off in a period of time.

**NOTE:** Due to the large flash reprogramming file size for the Instrument Panel Cluster (IPC), it is highly recommended that a Wired Ethernet or USB connection be used between the device (micro POD, wiPOD, or StarMOBILE) and the WiTech PC / laptop.

**NOTE:** If this flash process is interrupted/aborted, the flash should be restarted.

1. Reprogram the IPC with the latest software. Using the wiTECH diagnostic application for flashing an ECM is available by selecting "help" then "help contents" at the top of the wiTECH diagnostic application window.
2. Using wiTECH, perform a BCM, Proxy Configuration Alignment. This routine is available under the 'Vehicle Preparations' tab found on the home page of wiTECH.
3. Turn off the ignition, disconnect the wiTECH, open and close the driver's door and let all modules go to sleep.
4. Reconnect the wiTECH and clear any DTCs that may have been set in other modules due to reprogramming.

***POLICY:***

Reimbursable within the provisions of the warranty.

***TIME ALLOWANCE:***

<b>Labor Operation No:</b>	<b>Description</b>	<b>Skill Category</b>	<b>Amount</b>
18-19-47-9M	Module, Instrument Cluster (IPC) - Inspect Software Level Only (0 - Introduction)	6- Electrical and Body Systems	0.2 Hrs.
18-19-47-9N	Module, Instrument Cluster (IPC) - Inspect / Reprogram IPC (Sales Code JAJ only) (0 - Introduction)	6- Electrical and Body Systems	1.0 Hrs.
18-19-47-9P	Module, Instrument Cluster (IPC) - Inspect / Reprogram IPC (Sales Code JAY only) (0 -	6- Electrical and Body Systems	0.2 Hrs.

	Introduction)		
--	---------------	--	--

**NOTE: The expected completion time for the IPC Highline Cluster is 45 minutes and for the IPC Midline Cluster is 10 minutes. Actual flash download times may be affected by vehicle connection and network capabilities.**

***FAILURE CODE:***

FM	Flash Module
----	--------------