

QUALITY DRIVEN® SERVICE

SERVICE BULLETIN

APPLICABILITY:	2013-14MY Legacy & Outback Models with 2.5L FB Engine		02-150-14R 02/07/14
SUBJECT:	Revised Valve Train Parts to Reduce a Warm Engine Tapping Sound from the Left Cylinder Head	REVISED:	03/3/14

INTRODUCTION

This bulletin announces the availability of revised valve train components developed to reduce a tapping sound (sometimes described as "a sewing machine type" sound) which may be heard coming from the left-hand (B2) side of the engine when the engine is warm. This bulletin does **not** address any cold engine or start-up sounds. The changes consist of:

- Design change to the valve rockers
- Camshaft profile change
- 1.65mm longer intake and 2.4mm longer exhaust valve stem lengths

PART INFORMATION

PART NAME		NEW	OLD	
	Part Number	13201AA670	13201AA640	
INTAKE VALVE	Chango	Stem Length:	Stem Length:	
	Change	104.95mm	103.3mm	
	Identification	131 122		
EXHAUST VALVE	Part Number	13202AA750	13202AA670	
	Change	Stem Length:	Stem Length:	
	Change	96.5mm	94.1mm	
	Identification	E3	E2	
	Part Number	13249AA250	13249AA240	
VALVE ROCKER	Change	Change to Roller Portion	n/a	
	Identification	Circular groove added on pivot side	n/a	
INTAKE CAMSHAFT, LEFT	Part Number	13037AA960 13037AA850		
	Change	Cam Profile Change	n/a	
	Identification	38B360 or 38B410	38B250 or 38B300	

Continued...

CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.


Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.

SUBARU OF AMERICA, INC. IS "ISO 14001 COMPLIANT"

The international standard for excellence in Environmental Management Systems. Please recycle or dispose of automotive products in a manner that is friendly to our environment and in accordance with all local, state and federal laws and regulations.

PART NAME		NEW	OLD	
	Part Number	13052AA960	13052AA850	
EXHAUST CAMSHAFT , LEFT	Change	Cam Profile Change	n/a	
	Identification	53B360 or 53B410	53B250 or 53B300	
	Part Number	13296AA090	13296AA051	
PIVOT, ROCKER ARM	NOTE: These revised rocker pivots were incorporated into production October 8, 2012, starting with VIN: Legacy: D*017921 Outback: D*242757			

The illustrations below show additional information about the changes to the valve rockers, camshafts and valves to help readily distinguish them from the previous version parts.



SERVICE PROCEDURE / INFORMATION

If you receive a customer concern of a tapping sound from the B2 cylinder head, confirm it is isolated to the B2 valve train area before proceeding with any repairs. Once verified, order and replace the intake and exhaust camshafts, the 4 intake and 4 exhaust valves, and all 8 rockers. Depending upon the VIN (see part information table) you may also need to replace all 8 rocker pivots. To clarify, if the VIN is BEFORE VIN D*017921 for Legacy or D*242757 for Outback, you will need to replace the rocker pivots. Vehicles built after these VINs already incorporate the new pivots. Refer to the service procedures outlined in the applicable Service Manual for installation.

NOTE: When setting the valve clearances, the intakes should be set to 0.13mm +0.02 / -0.03 and the exhausts set to 0.22mm +/-0.02. These are revised clearance specifications and are not reflected in the Service Manual.

IMPORTANT: Do not mix old and new parts together as it will become impossible to obtain intake valve clearances that are within specification.

TIP: An egg carton makes a perfect organizer tray. Make sure to mark it as necessary (front, intake, exhaust) to eliminate any mixing of parts.

WARRANTY / CLAIM INFORMATION

For vehicles within the Basic New Car Limited and/or Powertrain Warranty, this repair may be claimed using the following information:

LABOR DESCRIPTION	LABOR OPERATION #	FAIL CODE	TRANSMISSION	LABOR TIME
H4 ENGINE R&R FOR CYLINDER HEAD	B293-130	-	M/T	3.4
SERVICING			CVT	3.9
LH CYLINDER HEAD R&R	C293-132			4.9
ALL VALVES REPLACE, ONE CYLINDER HEAD Includes: Valve Seating, R&R of the Springs, Valve Seals & Valve Adjustment	<mark>C293-123</mark>	AER-48	All	<mark>1.6</mark>
VALVE TRAIN NOISE DIAGNOSIS	C243-001			0.3