

Model(s)	Year(s)	Eng. Code(s)	Trans. Code(s)	VIN Range From	VIN Range To
(A5) Jetta Wagon	2009	AII	DSG (02E)	AII	All
(A5) Golf	2009	All	DSG (02E)	All	All
(A5) Jetta Sedan	2009-2010	All	DSG (02E)	All	All
(A6) Jetta SportWagen, Golf Wagon	2010-2012	All	DSG (02E)	All	All
CC	2009-2012	All	DSG (02E)	All	All
Eos	2009-2012	All	DSG (02E)	All	All
Passat	2012	All	DSG (02E)	All	All

Condition

30 14 01 February 6, 2014 **2028714** Supersedes T. B. V301303 dated December 18, 2013 to update required tools list.

DTC P2711 Implausible Transmission Shift Sequence Stored in the Transmission Control Module

ETip:

This Technical Bulletin is for fault code P2711 <u>ONLY</u>, if any other faults appear with this code, perform normal GFF processes and diagnoses.

DTC as described may cause shifting concerns and/or a lack of mobility upon initial startup. For example, the selector is moved to Drive or Reverse and the transmission does not engage the selected gear.

DTC	Description
P2711	Implausible Transmission Shift Sequence

© 2014 Volkswagen Group of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



Technical Background

Debris in the clutch assembly causing too much drag torque from the multiple clutch.

Production Solution

Updated clutch installed as of March 12, 2010.

Service

If the Transmission Control Module has fault code P2711 (only) and more than 19,000 miles, replace the multiple clutch and cover, see Repair Manual Group 30 in ElsaWeb. If more than P2711 is in the Transmission Control Module or the vehicle has less than 19,000 miles, <u>the faults need to be diagnosed using normal GFF</u> <u>processes.</u>

Note:

The clutch should not be replaced without proper diagnoses and/or meeting the mileage requirements.

 $\ensuremath{\textcircled{\text{c}}}$ 2014 Volkswagen Group of America, Inc.

Page 2 of 5



Warranty

To determine if this procedure is covered under Warranty, always refer to the Warranty Policies and Procedures Manual ¹⁾

Model(s)	Ye	ear(s)	Eng. Code(s)	Trans. Code(s)	VIN Range From	VIN Range To
(A5) Jetta Wagon	2009		All	DSG (02E)	All	All
(A5) Golf	2009		All	DSG (02E)	All	All
(A5) Jetta Sedan	2009-2010		All	DSG (02E)	All	All
(A6) Jetta SportWagen, Golf Wagon	2010-2012		All	DSG (02E)	All	All
СС	200	9-2012	All	DSG (02E)	All	All
Eos	200	9-2012	All	DSG (02E)	All	All
Passat	2012		All	DSG (02E)	All	All
			S	AGA Coding		
Claim Type:	l	Use appl	icable Claim Typ	e ¹⁾		
Service Number: Code		HST		Damage Location (Depends on Service No.)		
3838 0010		0010		Use applicable when indicate ElsaWeb (L/R)		
Parts Manufacturer Golf,		Golf, Passat	, CC, Eos	BW	BWS ²⁾	
Jetta, Jetta Wagon, Jett Wago			-	• •	If BWS ²⁾	
Labor Operation and cover	³⁾ : Re	place m	ultiple clutch	30601950 = 110 T	U	
Labor Operation ³⁾ : Remove and Install Transmission		343519XX = Refer to Elsa for your particular model				



Causal Part:	02E 398 (02E 398 029*		
	Diagnostic Ti	ne ⁴⁾		
GFF Time expenditure	01500000 = 20 TU max.	YES		
Road Test	01210004 = 10 TU	YES		
Technical Diagnosis	01320000 = 00 TU max.	NO		
Claim Comment: Input "As	per Technical Bulletin 2028714	" in comment section of Warranty Claim.		
¹⁾ Vehicle may be outside an	y Warranty in which case this	Technical Bulletin is informational only		
²⁾ Code per warranty vendo	code policy.			
³⁾ Labor Time Units (TUs) are subject to change with ELSA updates.				
⁴⁾ Documentation required r	er Warranty Policy Procedure	s Manual.		

Page 4 of 5



Required Parts and Tools

Part Description	Part No:	Quantity	
Multiple Clutch Kit	02E398029*	1	
	(* = latest part number and suffix available in ETKA per the vehicle application)		
Oil Filter	02E305051C	1	
Transmission Fluid	G 052182A2	As required	

Tool Description	Tool No:	
Midtronics Battery Tester/Charger	InCharge 940 (INC-940)	
VAS Diagnostic Tool	VAS 5051B, VAS 5052A, VAS 6150/X & VAS 6160/X with: ODIS Service 2.0.0 or higher with current online updates	
Retaining Pin	T10303	
Dial Gauge Holder	VW 387	

Additional Information

All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.

© 2014 Volkswagen Group of America, Inc.