



Recall Bulletin



PRODUCT SAFETY RECALL

SUBJECT: Overheated Exhaust Components

MODELS: 2015 Cadillac Escalade, Escalade ESV
2014 Chevrolet Silverado 1500
2015 Chevrolet Silverado HD, Suburban, Tahoe
2014 GMC Sierra 1500
2015 GMC Sierra HD, Yukon, Yukon XL
Equipped with 4.3L Engine (LV1/LV3), 5.3L Engine (L83), 6.0L Engine (LC8/L96), or 6.2L Engine (L86)

This bulletin has been revised to include some 2015 model year vehicles. Please discard all copies of bulletin 14008A.

****IMPORTANT****

This recall is to be performed on involved vehicles in dealer inventory immediately.

Until the repair can be performed, do not let the vehicle idle unattended for more than a few minutes, and do not let the vehicle idle in or next to a building or structure.

Vehicles involved in this recall were placed on stop delivery January 10, 2014. Once the service procedure contained in this bulletin has been performed on the vehicle, the vehicle is released from stop delivery and the vehicle can be delivered to the customer.

All involved vehicles that are in dealer inventory must be held and not delivered to customers, dealer traded, or used for demonstration purposes until the repair contained in this bulletin has been performed on the vehicle.

Customers will be advised to contact their dealer to have their vehicle towed to the dealership if their vehicle exhibits the condition, which is the illumination of the Check Engine light and an "Engine Power is Reduced" DIC message.

CONDITION

General Motors has decided that a defect, which relates to motor vehicle safety, exists in **certain** 2014 model year Chevrolet Silverado 1500 and GMC Sierra 1500; and 2015 model year Cadillac Escalade and Escalade ESV; Chevrolet Silverado HD, Suburban, and Tahoe; and GMC Sierra HD, Yukon, and Yukon XL vehicles, equipped with a 4.3L engine (LV1/LV3), 5.3L engine (L83), 6.0L engine (LC8/L96), or 6.2L Engine (L86). When these vehicles are idling in cold temperatures, some of the exhaust components may overheat. If this were to occur, the yellow

Check Engine light will illuminate and the “Engine Power is Reduced” message will appear in the Driver Information Center (DIC). If there is enough heat, it could melt plastic parts in the area, resulting in a possible engine fire.

CORRECTION

Dealers are to reprogram the engine control module to modify the Power Management Mode software in order to prevent the condition.

VEHICLES INVOLVED

All involved vehicles are identified by Vehicle Identification Number on the Investigate Vehicle History screen in GM Global Warranty Management system. Dealership service personnel should always check this site to confirm vehicle involvement prior to beginning any required inspections and/or repairs. It is important to routinely use this tool to verify eligibility because not all similar vehicles may be involved regardless of description or option content.

For dealers with involved vehicles, a listing with involved vehicles containing the complete vehicle identification number, customer name, and address information has been prepared and will be provided to US and Canadian dealers through the GM GlobalConnect Recall Reports, or sent directly to export dealers. Dealers will not have a report available if they have no involved vehicles currently assigned.

The listing may contain customer names and addresses obtained from Motor Vehicle Registration Records. The use of such motor vehicle registration data for any purpose other than follow-up necessary to complete this recall is a violation of law in several states/provinces/countries. Accordingly, you are urged to limit the use of this report to the follow-up necessary to complete this recall.

PART INFORMATION

No parts are required for this recall.

SERVICE PROCEDURE

Note: Carefully read and follow the instructions below.

- Do NOT attempt to order the calibration number from GM Customer Care and Aftersales. The calibration numbers required for this service procedure are programmed into control modules via a Multiple Diagnostic Interface (MDI) with the calibration update. Use **TIS2WEB on or after January 13, 2014**, to obtain the calibration. If you cannot access the calibration, call the Techline Customer Support Center and it will be provided.
- DO NOT program a control module unless directed to by a service procedure or a service bulletin. If the control module is not properly configured with the correct calibration software, the control module will not control all of the vehicle features properly.
- Ensure the programming tool is equipped with the latest software and is securely connected to the data link connector. If there is an interruption during programming, programming failure or control module damage may occur.
- Stable battery voltage is critical during programming. Any fluctuation, spiking, over voltage or loss of voltage will interrupt programming. When required install the *EL-49642* SPS Programming Support Tool to maintain system voltage. If not available, connect a fully

charged 12 V jumper or booster pack disconnected from the AC voltage supply. DO NOT connect a battery charger.

- Turn OFF or disable systems that may put a load on the vehicles battery such as; interior lights, exterior lights (including daytime running lights), HVAC, radio, etc.
- During the programming procedure, follow the SPS prompts for the correct ignition switch position.
- Clear DTCs after programming is complete. Clearing powertrain DTCs will set the Inspection/Maintenance (I/M) system status indicators to NO.
- Note the engine oil life remaining percentage.

To reprogram an existing K20 Engine Control Module, perform the following procedure:

1. Install *EL-49642* SPS programming support tool.
2. Access the Service Programming System (SPS) and follow the on-screen instructions. Refer to Service Programming System (SPS) documentation in SI for programming instructions.

Note: Select *ECM/TCM ECM/TCM Sequential Programming* from the SPS Supported Controllers screen if the vehicle is equipped with a 5.3L (L83) engine. After programming, proceed to step 4.

3. On the SPS Supported Controllers screen, select *K20 Engine Control Module - Programming* and follow the on-screen instructions.
4. Clear DTCs after completing the programming procedure.

Note: If vehicle fails to start during Configuration and Setup, perform the SPS Function Immobilizer Learn and follow the on-screen instructions.

5. Perform the SPS function *K20 Engine Control Module - Configuration & Setup* and follow the on-screen instructions, if available.
6. Clear DTCs after completing the Configuration & Setup procedure.
7. FOR CALIFORNIA VEHICLES Only: Install a Recall Identification Label and complete a "Proof of Correction" certificate upon recall completion.

RECALL IDENTIFICATION LABEL – California Vehicles Only

Place a Recall Identification Label on each vehicle corrected in accordance with the instructions outlined in this Product Recall Bulletin. Each label provides a space to include the recall number and the five-digit dealer code of the dealer performing the recall service. This information may be inserted with a ballpoint pen.

Put the Recall Identification Label on a clean and dry surface of the radiator core support in an area that will be visible to people servicing the vehicle.

When installing the Recall Identification Label, be sure to pull the tab to allow adhesion of the clear protective covering. Additional Recall Identification Labels for US dealers can be obtained from Dealer Support Materials by ordering on the web from DWD Store, www.gmglobalconnect.com, and then click on the DWD Store link. Request Item Number S-1015 when ordering.



COURTESY TRANSPORTATION – For US and Canada

The General Motors Courtesy Transportation program is intended to minimize customer inconvenience when a vehicle requires a repair that is covered by the New Vehicle Limited Warranties. The availability of courtesy transportation to customers whose vehicles are within the warranty coverage period and involved in a product program is very important in maintaining customer satisfaction. Dealers are to ensure that these customers understand that shuttle service or some other form of courtesy transportation is available and will be provided at no charge. Dealers should refer to the General Motors Service Policies and Procedures Manual for Courtesy Transportation guidelines.

WARRANTY TRANSACTION INFORMATION

Submit a transaction using the table below. All transactions should be submitted as a ZFAT transaction type, unless noted otherwise.

Labor Code	Description	Labor Time
9100334	Engine Control Module Reprogramming with SPS	0.4

CUSTOMER NOTIFICATION – For US and Canada

General Motors will notify customers of this recall on their vehicle (see copy of customer letter included with this bulletin).

CUSTOMER NOTIFICATION – For Export

Letters will be sent to known owners of record located within areas covered by the US National Traffic and Motor Vehicle Safety Act. For owners outside these areas, dealers should notify customers using the attached sample letter.

DEALER RECALL RESPONSIBILITY – For US and Export (US States, Territories, and Possessions)

It is a violation of Federal law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by this notification under a sale or lease until the defect or noncompliance is remedied.

The US National Traffic and Motor Vehicle Safety Act provides that each vehicle that is subject to a recall of this type must be adequately repaired within a reasonable time after the customer has tendered it for repair. A failure to repair within sixty days after tender of a vehicle is prima facie evidence of failure to repair within a reasonable time. If the condition is not adequately repaired within a reasonable time, the customer may be entitled to an identical or reasonably equivalent vehicle at no charge or to a refund of the purchase price less a reasonable allowance for depreciation. To avoid having to provide these burdensome remedies, every effort must be made to promptly schedule an appointment with each customer and to repair their vehicle as soon as possible. In the recall notification letters, customers are told how to contact the US National Highway Traffic Safety Administration if the recall is not completed within a reasonable time.

DEALER RECALL RESPONSIBILITY – All

All unsold new vehicles in dealers' possession and subject to this recall must be held and inspected/repaired per the service procedure of this recall bulletin before customers take possession of these vehicles.

Dealers are to service all vehicles subject to this recall at no charge to customers, regardless of mileage, age of vehicle, or ownership, from this time forward.

Customers who have recently purchased vehicles sold from your vehicle inventory, and for which there is no customer information indicated on the dealer listing, are to be contacted by the dealer. Arrangements are to be made to make the required correction according to the instructions contained in this bulletin. A copy of the customer letter is provided in this bulletin for your use in contacting customers. Recall follow-up cards should not be used for this purpose, since the customer may not as yet have received the notification letter.

In summary, whenever a vehicle subject to this recall enters your vehicle inventory, or is in your dealership for service in the future, you must take the steps necessary to be sure the recall correction has been made before selling or releasing the vehicle.



IMPORTANT SAFETY RECALL

Dear General Motors Customer:

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

General Motors has decided that a defect, which relates to motor vehicle safety, exists in certain 2014 model year Chevrolet Silverado and GMC Sierra 1500; and 2015 model year Cadillac Escalade and Escalade ESV; Chevrolet Silverado HD, Suburban, and Tahoe; and GMC Sierra HD, Yukon, and Yukon XL vehicles, equipped with a 4.3L, 5.3L, 6.0L, or 6.2L engine. As a result, GM is conducting a safety recall. We apologize for this inconvenience. However, we are concerned about your safety and continued satisfaction with our products.

IMPORTANT

- Your vehicle is involved in safety recall 14008.
- Schedule an appointment with your GM dealer.
- This service will be performed for you at **no charge**.

Why is your vehicle being recalled?

Some of the exhaust components may overheat, when your vehicle is idling in cold temperatures. If this were to occur, the yellow Check Engine light will illuminate and the “Engine Power is Reduced” message will appear in the Driver Information Center (DIC). If there is enough heat, it could melt plastic parts in the area, resulting in a possible engine fire.

What will we do?

Your GM dealer will reprogram the engine control module to modify the Power Management Mode software in order to prevent this condition. This service will be performed for you at **no charge**. Because of service scheduling requirements, it is likely that your dealer will need your vehicle longer than the actual reprogramming time of approximately 25 minutes.

If your vehicle is within the New Vehicle Limited Warranty, your dealer may provide you with shuttle service or some other form of courtesy transportation while your vehicle is at the dealership for this repair. Please refer to your Owner Manual and your dealer for details on courtesy transportation.

What should you do?

You should contact your GM dealer to arrange a service appointment as soon as possible.

If the Check Engine light illuminates and the “Engine Power is Reduced” message appears in the DIC, turn the vehicle off immediately and call your GM dealer to have your vehicle towed to the dealership.

Until you have had your vehicle serviced, please do not let your vehicle idle.

California Residents: The state of California requires the completion of recalls on emission related parts prior to vehicle registration renewal. In addition, the state requires that every vehicle must pass an emission test (SMOG Check) every two years and before it is sold. Without the completion of this **no-charge** recall, your vehicle may be more likely to fail this test. At the time of the recall completion, your dealer will issue you a "Proof of Correction Certificate". Keep this certificate and, if required, present it to the Department of Motor Vehicles when renewing your registration as proof of recall completion.

Do you have questions?

If you have questions or concerns that your dealer is unable to resolve, please contact the appropriate Customer Assistance Center at the number listed below.

Division	Number	Text Telephones (TTY)
Chevrolet	1-800-222-1020	1-800-833-2438
GMC	1-800-462-8782	1-888-889-2438
Guam	65-6267-1752	
Puerto Rico – English	1-800-496-9992	
Puerto Rico – Español	1-800-496-9993	
Virgin Islands	1-800-496-9994	

If after contacting your dealer and the Customer Assistance Center, you are still not satisfied we have done our best to remedy this condition without charge and within a reasonable time, you may wish to write the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590, or call the toll-free Vehicle Safety Hotline at 1.888.327.4236 (TTY 1.800.424.9153), or go to <http://www.safercar.gov>. The National Highway Traffic Safety Administration Campaign ID Number for this recall is 14V007.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

Jeffrey M. Boyer
 Vice President
 Global Vehicle Safety