



Service Bulletin

File in Section: -

Bulletin No.: PIC5931A

Date: March, 2014

PRELIMINARY INFORMATION

Subject: Outside Air Temperature Reading May Display Inaccurately - Reprogram IPC

Models: 2014 Chevrolet Camaro

This PI was superseded to update repair information. Please discard PIC5931.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

Some customers may notice that the ambient air temperature display may be inaccurate in the vehicle's IPC. Upon further diagnosis, technicians may find that no DTCs are set.

Recommendation/Instructions

This concern is caused by a software anomaly inside the IPC. A new calibration has been developed to correct this issue and is available in TIS2WEB.

Reprogram the vehicle's IPC with the updated calibration. The new calibration number is 23466075 and it is labeled as "New calibration to improve outside air temperature display performance" in TIS2WEB.

Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
2810195	Instrument Cluster Reprogramming with SPS	Use Published Labor Operation Time

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.