CATERPILLAR*

Service Information System

Shutdown SIS

Previous Screen

Welcome: chrismk2

✓ Product: NO EQUIPMENT SELECTED Model: NO EQUIPMENT SELECTED Configuration: NO EQUIPMENT SELECTED

Technical Information Bulletin

High Pressure Turbocharger Troubleshooting Guide for CT660 On Highway Truck **{7000}**

Media Number -TIBU7342-00 **Caterpillar: Confidential Yellow** Publication Date -06/11/2013 Date Updated -06/11/2013

i05534270

High Pressure Turbocharger Troubleshooting Guide for CT660 On Highway Truck (7000)

SMCS - 7000

On Highway Truck:

CT660 (S/N: TGA1-UP; TGD1-UP; TEJ105-UP; TRK1-UP; TKL1-UP; TEP1-UP; TJS1-UP; TGT107-UP; TSW1-UP; TSY1-UP; TGZ1-UP)

Introduction

The problem below has been identified. Use the solution that is identified below.

Problem

High-pressure turbo failures on the CT660 On-Highway Trucks.

Solution

Follow high-pressure turbocharger troubleshooting guide. The troubleshooting guide is effective with the following machines:

	Table 1
Effectivity	

Model	Affected Machines
	S/N:TEJ105-UP
	S/N:TEP1-177,181-205,207,209-220,223-UP
	S/N:TGA1-88,90-194,196-198,200-219,221-233,249-UP
	S/N:TGD1-3,5-9,117-UP
	S/N:TGT107-UP
CT660	S/N:TGZ1-UP
	S/N:TJS1-UP
	S/N:TKL1-161,164-171,174-176,178-587,599-UP
	S/N:TRK1-39,41-48,100-284,286-288,290-600,602-1237,1240-1520,1565-UP
	S/N:TSW1-UP
	S/N:TSY1-UP

High Pressure Turbocharger Service Plan

Follow the procedure below to troubleshoot high-pressure Turbocharger performance issues.

Obtain the following information before starting this procedure:

- VIN number
- Mileage
- Date
- Customer
- Tech Name
- Obtain documentation of pervious service performed
- Detailed description of the problem
- 1. Review Initial Examinations Table 2

Table 2

Initial Examinations	
Check Or Test Procedure	Follow up Check Or Test Procedure

Do fault codes exist? SPN, FMI SPN, FMI	YES - Resolve fault codes NO - Proceed to Step 2
Any Visible Smoke? White or Black?	YES - Proceed to Step 2 NO - Proceed to Step 2
Any external fluid leaks? (Oil or Coolant)	YES - Proceed to Step 2 NO - Proceed to Step 2
External engine damage?	YES - Proceed to Step 2 NO - Proceed to Step 2
Is engine overheating?	YES - Proceed to Step 2 NO - Proceed to Step 2
Is the engine knocking?	YES - Proceed to Step 2 NO - Proceed to Step 2.
Have any parts been replaced to address these issues? Check warranty history.	YES - Proceed to Step 2 NO - Proceed to Step 2

2. Check the Air Management System

Inspect for Boost leaks

Table 3

Were any Boost leaks Detected?	Yes Note any boost leaks before repairing. Proceed to Step 3.	
	No Inspect the inlet high-pressure charge air cooler (HPCAC) Proceed to Step 4.	

- 3. Remove the CAC pipe between the high-pressure turbocharger and high-pressure charge air cooler.
 - Inspect the high-pressure turbo outlet duct for wet oil residue.

Table 4

2,11,21,2	
W 4 -:1 : 1 1-4-4-49	Yes Proceed to Step 5
Was any wet oil residue detected?	No Proceed to Step 4

4. Reference DTC'S noted earlier

Table 5

Yes Proceed to Step 6 Was SPN 190 FMI 0 noted at the top of Inspection Seat No Proceed to Step 8

5. Check the Calibration Scorecard on the service portal to ensure that the latest calibration is installed.

Table 6

Is the ECM Calibration up to date?	Yes Proceed to Step 4
	No Proceed to Step 6

- 6. Inspect by opening the freeze frame data and check the ID 58071 max trip RPM logged for SPN 190 FMI 0.
 - Open DSN. Attach freeze frame data and engine parameters.
 - Refer to Service Magazine, SEPD1677
 - Do not use ID 57531 "Total Engine Maximum Speed"

Table 7

14010 /	
Is the engine RPM between 2600-2999?	Yes Proceed to Step 9
	No Proceed to Step 10

7. Update engine ECM with the latest calibration level

Note: With the new calibration any residual oil will dry up.

- Go To Step 19.
- 8. Remove the turbo center section and inspect.
 - Is there excessive radial or axial end-play (Fin to housing contact.)
 - Is there any visual damage evident.

Table 8

14010 0	
Are either of these conditions present?	Yes Proceed to Step 11
	No Proceed to Step 12

- 9. Replace
 - Remove and Drain CAC.

- Turbo center section.
- All six injectors.
- Close case File.
- Go to Step 19
- 10. For RPM 3000 or higher.
 - Remove oil pan.
 - Check for bent rods and damaged liners.

Table 9 Yes Proceed to Step 15 Is There any damage present?

11. Inspect

Table 10		
Leahann ann ail in ah aintala an in ah a ATE ar	Yes Proceed to Step 14	
Is there any oil in the intake or in the ATF sy	No Proceed to Step 13	

No Proceed to Step 16

- 12. Provide documents or information that supports replacement of the turbo with no damage evident.
 - Pictures
 - Data
 - Go to Step 13
- 13. Replace Turbo center section.
 - Go to Step 19
- 14. Inspect
 - If Turbine housing damaged is noted, open DSN, continue if not damaged.
 - If no damage is noted, replace Turbo Center Section (No approval required for center section only.)
 - Remove the CAC and allow it to drain, then reinstall
 - For the AFT system, open a Tech Service case file and provide pictures of the contamination

- Perform any additional directives as instructed by Tech Services.
- Go to Step 19

15. Perform

- Attach pictures of the damage to the case file
- Repair as directed in case file
- Go to Step 19

16. Review

Table 11

2,000	
What was the ID 58071 Max Trip RPM recorded?	3000 - 3599 Proceed to Step 17
	3600+ Proceed to Step 18

17. Replace

- Remove and drain CAC.
- Turbo Center Section.
- All six Injectors.
- Reset trip report and freeze frame.
- Go to Step 19.

18. Replace

- Remove and drain CAC.
- Turbo Center Section.
- All six Injectors.
- Water Pump
- Reset trip report and freeze frame.
- Go to Step 19.

19. End of Repair

Release Vehicle

Copyright 1993 - 2013 Caterpillar Inc. All Rights Reserved. Private Network For SIS Licensees. Tue Dec 3 13:15:23 CST 2013 chrismk2