Advanced Full Text Search - TIBU7342 - High Pressure Turbocharger Troubleshooting G... Page 1 of 7

<b>CATERPILLAR</b> *	Service Information System	Shutdown SIS
Previous Screen	SB-10054116-6192	
		Welcome: chrismk2
< Product: NO EQUIPM	ENT SELECTED	
Model: NO EQUIPME	NT SELECTED	
Configuration: NO EQ	UIPMENT SELECTED	

Technical Information BulletinHigh Pressure Turbocharger Troubleshooting Guide for CT660 On Highway Truck{7000}Media Number -TIBU7342-01Publication Date -21/02/2014Caterpillar: Confidential Yellow

i05719774

## High Pressure Turbocharger Troubleshooting Guide for CT660 On Highway Truck{7000}

**SMCS -** 7000

On Highway Truck: CT660 (S/N: TGA1-UP; TGD1-UP; TEJ105-UP; TRK1-UP; TKL1-UP; TEP1-UP; TJS1-UP; TGT107-UP; TSW1-UP; TSY1-UP; TGZ1-UP)

## Introduction

The problem below has been identified. Use the solution that is identified below.

# Problem

High-pressure turbo failures on the CT660 On-Highway Trucks.

## **Solution**

Follow high-pressure turbocharger troubleshooting guide. The troubleshooting guide is effective with the following machines:

Table 1

Effectivity

https://sis.cat.com/sisweb/sisweb/techdoc/techdoc\_print\_page.jsp?returnurl=/sisweb/sisweb/... 3/5/2014

Model	Affected Machines
	S/N:TEJ105-UP
	S/N:TEP1-177,181-205,207,209-220,223-UP
	S/N:TGA1-88,90-194,196-198,200-219,221-233,249-UP
	S/N:TGD1-3,5-9,117-UP
	S/N:TGT107-UP
CT660	S/N:TGZ1-UP
	S/N:TJS1-UP
	S/N:TKL1-161,164-171,174-176,178-587,599-UP
	S/N:TRK1-39,41-48,100-284,286-288,290-600,602-1237,1240-1520,1565-UP
	S/N:TSW1-UP
	S/N:TSY1-UP

# **High Pressure Turbocharger Service Plan**

Follow the procedure below to troubleshoot high-pressure Turbocharger performance issues.

Obtain the following information before starting this procedure:

- VIN number
- Mileage
- Date
- Customer
- Tech Name
- Obtain documentation of pervious service performed
- Detailed description of the problem
- 1. Review Initial Examinations Table 2

#### Table 2

Initial Examinations	
Check Or Test Procedure	Follow up Check Or Test Procedure

Do fault codes exist? SPN FMI	YES - Resolve fault codes
SPN	NO - Proceed to Step 2
Any Visible Smale? White or Dleak?	YES - Proceed to Step 2
Any visible shoke? white of black?	<b>NO -</b> Proceed to Step 2
Any optimal flyid looks? (Oil or Coolant)	YES - Proceed to Step 2
Any external fluid leaks? (Off of Coolant)	<b>NO</b> - Proceed to Step 2
Estamal anging damaga?	YES - Proceed to Step 2
	<b>NO -</b> Proceed to Step 2
La angina avarbanting?	YES - Proceed to Step 2
is engine overheating?	<b>NO -</b> Proceed to Step 2
La the engine langeling?	YES - Proceed to Step 2
Is the engine knocking?	<b>NO</b> - Proceed to Step 2.
Have any parts been replaced to address these issues? Check	YES - Proceed to Step 2
warranty history.	<b>NO</b> - Proceed to Step 2

- 2. Check the Air Management System
  - Inspect for Boost leaks

Table 3

Were any Boost leaks Detected? Was any wet oil residue detected?	Yes Note any boost leaks before repairing. Proceed to Step 3.	
	No Inspect the inlet high-pressure charge air cooler (HPCAC) Proceed to Step 4.	

- 3. Remove the CAC pipe between the high-pressure turbocharger and high-pressure charge air cooler.
  - Inspect the high-pressure turbo outlet duct for wet oil residue.

Table 4		
Was any wat ail rasidua dataatad?	Yes Proceed to Step 5	
was any wet on residue detected?	No Proceed to Step 4	

4. Reference DTC'S noted earlier

Table 5

Was SPN 190 FMI 0 noted at the top of Inspection Seat	Yes Proceed to Step 6
	No Proceed to Step 8

5. Check the Calibration Scorecard on the service portal to ensure that the latest calibration is installed.

Table 6		
Is the ECM Calibration up to date?	Yes Proceed to Step 4	
	No Proceed to Step 6	

- 6. Inspect by opening the freeze frame data and check the ID 58071 max trip RPM logged for SPN 190 FMI 0.
  - Open DSN. Attach freeze frame data and engine parameters.
  - Refer to Service Magazine, SEPD1677
  - Do not use ID 57531 "Total Engine Maximum Speed"

Table 7

Is the engine RPM between 2600-2999?	Yes Proceed to Step 9
	No Proceed to Step 10

7. Update engine ECM with the latest calibration level

Note: With the new calibration any residual oil will dry up.

- Go To Step 19.
- 8. Remove the turbo center section and inspect.
  - Is there excessive radial or axial end-play (Fin to housing contact.)
  - Is there any visual damage evident.

Table 8

Are either of these conditions present?	Yes Proceed to Step 11
	No Proceed to Step 12

- 9. Replace
  - Remove and Drain CAC.

- Turbo center section.
- All six injectors.
- Close case File.
- Go to Step 19
- 10. For RPM 3000 or higher.
  - Remove oil pan.
  - Check for bent rods and damaged liners.

Table 9

	Yes Proceed to Step 15	
Is There any damage present?	No Proceed to Step 16	

11. Inspect

Table 10	
Is there are all in the intelse on in the AFT anotom?	Yes Proceed to Step 14
Is there any oil in the intake or in the AFI system?	No Proceed to Step 13

- 12. Provide documents or information that supports replacement of the turbo with no damage evident.
  - Pictures
  - Data
  - Go to Step 13
- 13. Replace Turbo center section.
  - Go to Step 19
- 14. Inspect
  - If Turbine housing damaged is noted, open DSN, continue if not damaged.
  - If no damage is noted, replace Turbo Center Section (No approval required for center section only.)
  - Remove the CAC and allow it to drain, then reinstall
  - For the AFT system, open a Tech Service case file and provide pictures of the contamination

Advanced Full Text Search - TIBU7342 - High Pressure Turbocharger Troubleshooting G... Page 6 of 7

- Perform any additional directives as instructed by Tech Services.
- Go to Step 19
- 15. Perform
  - Attach pictures of the damage to the case file
  - Repair as directed in case file
  - Go to Step 19
- 16. Review

#### Table 11

What was the ID 58071 Max Trip RPM recorded?	<b>3000 - 3599</b> Proceed to Step 17
	<b>3600</b> + Proceed to Step 18

### 17. Replace

- Remove and drain CAC.
- Turbo Center Section.
- All six Injectors.
- Reset trip report and freeze frame.
- Go to Step 19.

### 18. Replace

- Remove and drain CAC.
- Turbo Center Section.
- All six Injectors.
- Water Pump
- Reset trip report and freeze frame.
- Go to Step 19.
- 19. End of Repair
  - Release Vehicle

Copyright 1993 - 2014 Caterpillar Inc. All Rights Reserved. Private Network For SIS Licensees. Wed Mar 5 16:55:00 CST 2014 chrismk2