



Service Bulletin

PRELIMINARY INFORMATION

Subject: Engineering Information – Clutch Pedal Does Not Fully Return After Being Depressed

Models: 2013-2014 Chevrolet Camaro
Equipped with Manual Transmission

Attention: Proceed with this PI ONLY if the customer has commented about this concern AND the PIE number is listed in the Global Warranty Management / Investigate History link (GWM/IVH). If the customer has not commented about this condition or the EI does not show in GWM/IVH, disregard the PI and proceed with diagnostics found in published service information. THIS IS NOT A RECALL — refer to the latest version of Service Bulletin 04-00-89-053 for more details on the use of Engineering Information PIs.

Condition

Important: If the customer did not bring their vehicle in for this concern, DO NOT proceed with this EI. Some customers may comment that the clutch pedal does not fully return to the top after being depressed.

Cause

GM Engineering is attempting to determine the root cause of the above condition. Engineering has a need to gather information on vehicles PRIOR to repair that may exhibit this condition. As a result, this information will be used to "root cause" the customer's concern and develop/validate a field fix.

Instructions

If you encounter a vehicle with the above condition, confirm the following and contact one of the engineers listed below for further instructions.

- Clutch master cylinder reservoir is at proper level.
- No visible leaks including the clutch slave cylinder.
- Clutch pedal return spring is properly positioned.

Contact Information

Engineer Name	Phone Number
Marinko Mustapic	248-520-7565
Dave Howe	248-320-8607

Please include the following information if leaving a message:

- Technician name
- Dealer name and phone number
- Complete VIN and repair order (R.O) number

On the repair order, document the date and time the call was placed (even if the engineer was not reached).

If engineering is unable to return the call within one hour, proceed with diagnosis and repair based on information found in SI.

Warranty Information

If engineer was contacted or required information was provided, use:

Labor Operation	Description	Labor Time
8480058*	Engineering Information – Clutch Pedal Return	0.5 hr

*This is a unique Labor Operation for Bulletin use only. It will not be published in the Labor Time Guide.