### SB-10055228-4900

CATERPILLAR\*

**Service Information System** 

Shutdown SIS

Previous Screen

Welcome: chrismk2

Product: NO EQUIPMENT SELECTED
 Model: NO EQUIPMENT SELECTED
 Configuration: NO EQUIPMENT SELECTED

**Service Letter** 

PRODUCT SUPPORT PROGRAM FOR REPLACING THE RING SUPPORT ASSEMBLY ON CERTAIN

**CT660 ON HIGHWAY TRUCKS** 

Media Number -TEBE0902-00 Publication Date -21/02/2014

Date Updated -21/02/2014

**Caterpillar: Confidential Yellow** 

TEBE0902-00

# **CATERPILLAR®**

## SERVICE LETTER

21Feb2014

U-98 A-69

Before/After

PRODUCT SUPPORT PROGRAM FOR REPLACING THE RING SUPPORT ASSEMBLY ON CERTAIN CT660 ON HIGHWAY TRUCKS

7000 PS44194

NOTE:

This Program must be administered either before or after failure. In either case the decision whether to apply the Program is made by the dealer. When reporting the repair, use "PS44194" as the Part Number and "7755" as the Group Number. If administered before failure, use "56" as the Warranty Claim chrismk2 caterpillar. Confidential Yellow

Description Code and "T" as the SIMS Description code. If administered after failure, use "96" as the Warranty Claim Description Code, and "Z" as the SIMS Description Code.

#### NOTE:

The information supplied in this service letter may not be valid after the termination date of this program. Do not perform the work outlined in this Service Letter after the termination date without first contacting your Caterpillar product analyst.

#### TERMINATION DATE

28Feb2015

#### **PROBLEM**

The existing ring support assembly can fatigue and break after a short time in service on certain CT660 On Highway Trucks.

## **AFFECTED PRODUCT**

Model	Identification Number
******G1	coup 1*****
CT660	TKL00100-00106, 108-122, 124-131, 134-136, 138, 145, 147, 149, 151, 155
	TRK00103, 107-109, 111-115, 119-120, 122-125, 127-128, 130-131, 133, 136-142, 144-148, 150-151, 153, 155-164, 166-168, 171-174, 176-177, 179, 181-182, 184-186, 190-192, 196-198, 200-202, 204, 206-210, 213, 215-218, 222, 224, 230, 232, 234-235, 240, 247-249, 252-253, 255, 257, 261, 263, 265-266, 271, 275-276, 278, 282, 284, 296, 301, 303, 309, 314, 316, 319, 321, 323, 336-338, 351, 357, 359, 376, 390
******G1	coup 2*****
CT660	TGA00001-00086, 88, 90-91, 93-110, 112-116, 119-120, 122, 124-125
	TGD00001-00003, 5-9, 101
	TGT00100-00107

https://sis.cat.com/sisweb/sisweb/techdoc/techdoc\_print\_page.jsp?returnurl=/sisweb/sisweb/... 3/5/2014

Caterpillar: Confidential Yellow

```
TJS00100
TKL00107, 123, 132, 137, 139-141, 143-144, 146, 148,
150, 152-154, 156-160, 164-165, 168-170, 174-176, 178-
183, 188-193, 195-199, 204-206, 208, 210-213, 215-216,
219-220, 224-227, 232-233, 241-243, 255, 257-258, 261,
264-265, 268-269, 274, 277, 282-283, 285, 287, 289-291,
293-295, 298-299, 301, 304, 323, 339, 378, 399, 420,
425, 427, 430, 434-435, 446, 452, 456-457, 461, 463,
465, 471, 478, 502, 543, 545-549, 566, 569-571, 573-
587, 589-592, 594-599
TRK00105-00106, 116-118, 121, 126, 129, 132, 135, 143,
149, 152, 154, 165, 170, 175, 178, 183, 187-189, 193-
194, 199, 205, 211-212, 214, 219-221, 223, 225-229,
231, 233, 236-239, 241-246, 250-251, 254, 258-260, 262,
264, 267-270, 272-274, 277, 279-281, 283, 286-288, 290-
295, 297-300, 302, 304-306, 308, 310-313, 315, 317-318,
320, 322, 324-326, 328, 330, 332-335, 339-344, 346-350,
352-356, 358, 360-375, 377-387, 389, 391-392, 394-411,
413-415, 417-419, 421-422, 424-434, 436-437, 439-442,
444-449, 452-469, 471-477, 479-480, 482-483, 486-491,
493-500, 502, 504, 507-537, 539-549, 551-562, 564-600,
602-611, 613, 615-616, 618, 620-655, 657-664, 666-668,
670-688, 690-710, 712-722, 724-736, 738-744, 746-764,
766-772, 775-779, 781-782, 785-787, 789-816, 818-853,
855-1121, 1123-1237, 1240-1318, 1320-1329, 1331-1336,
1338-1358, 1360-1362, 1367-1368, 1370-1374, 1376-1379,
1381-1458, 1460-1465, 1467-1494, 1496-1515, 1517-1520,
1522-1565
TSY00100
```

### **PARTS NEEDED**

Qty	Part Number	Description			
******Group 1*****					
2	3581161	BOLT-HEX			
1	3928937	SUPPORT			
1	4470832	SUPPORT AS-RING			

In order to allow equitable parts availability to all participating dealers, please limit your initial parts order to not exceed 23% of dealership population. This is an initial order recommendation only, and the ultimate responsibility for ordering the total number of parts needed to satisfy the program lies with the dealer.

In order to allow equitable parts availability to all participating dealers, please limit your initial parts order to not exceed 23% of dealership population. This is an initial order recommendation only, and the ultimate responsibility for ordering the total number of parts needed to satisfy the program lies with the dealer.

### **ACTION REQUIRED**

Some units have a half clamp design for the charge air cooler (CAC) hold down. These units should fall under Group 1 and will require the extra clamp and bolts. All other serial numbers will be Group 2 and will only require the support bracket.

- 1. Remove old bracket and install new ring support assembly.
- 2. Hand tighten new ring support assembly to the engine first.
- 3. Then hand tighten bolts to ring support assembly.
- 4. Tighten to 22 to 24 N.M. (16 to 18 ft. lbs).
- 5. Install hold down clamp. Tighten to 22 to 24 N.M. (16 to 18 ft. lbs).

Note: When the new ring support assembly is installed, there will be more of the fan exposed and the seal will push tighter to the ring. This is normal.




Image1

## **SERVICE CLAIM ALLOWANCES**

Product smu/age	Caterpillar		Dealer Suggested		Customer Suggested	
whichever comes first	Parts %	Labor Hrs%	Parts %	Labor Hrs%	Parts %	Labor Hrs%
*****Group 1*****						
0-250000 miles, 0-36 mo	100.0%	100.0%	0.0%	0.0%	0.0%	0.0%
NOTE: This is a 0.5-hour job for Group 1						

Product smu/age	Caterpillar		Dealer Suggested		Customer Suggested	
whichever comes first	Parts %	Labor Hrs%	Parts %	Labor Hrs%	Parts %	Labor Hrs%
*****Group 2*****						

0-250000 miles, 0-36 mo	100.0%	100.0%	0.0%	0.0%	0.0%	0.0%	
NOTE: This is a 0.5-hour job for Group 2							

#### **PARTS DISPOSITION**

Handle the parts in accordance with your Warranty Bulletin on warranty parts handling.

Copyright 1993 - 2014 Caterpillar Inc. All Rights Reserved. Private Network For SIS Licensees. Wed Mar 5 17:03:03 CST 2014 chrismk2