



# Technical Bulletin

## SB-10056394-3328

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Tiguan	2013-2014	2.0L (CCTA)	All	All	All

### Condition

97 14 03 June 12, 2014 2037108 Supersedes TB V971402 dated May 1, 2014 to avoid confusion and remove pre road test labor operation from warranty table.

MIL ON, DTC P0236 Turbocharger Boost Sensor (A) Circ. Range Performance Stored in ECM Fault Memory

DTC	Description
P0236	Turbocharger Boost Sensor (A) Circ. Range Performance

### Technical Background

Increased resistance at the pins of the T14 connector in the engine wiring harness, causing fault code P0236 Turbocharger Boost Sensor (A) Circ. Range Performance.

### Production Solution

Optimized crimping of the engine wiring harness to avoid circuit faults.

# Technical Bulletin

---

## Service



**Note:**

Read the entire technical bulletin before performing any repairs.

### Wiring Harness and Connector Repairs, General Information



**Note:**

Observe general note for repairs of vehicle electrical system; see Repair Group 97 in Elsa.

DO NOT solder repairs on vehicle electrical system.

DO NOT repair crimp connectors.

After crimping a repair connection, the crimp connection must be heat shrunk using a hot air gun to prevent moisture penetration.



**WARNING:**

The steps above must be completed to ensure safety during repair.

### Procedure

- Switch Ignition OFF.
- Disconnect battery ground (GND) cable, see Repair Manual Group 27 in Elsa.



**WARNING:**

The steps above must be completed to ensure safety during repair.



**Tip:**

Use the applicable repair manual in Elsa in addition to the description below.

# Technical Bulletin

---

- Locate the T14 connector in front of the air box, behind the left front headlight. Wiring repair to be performed on the engine harness side (male pin side) (figure 1).



Figure 1

# Technical Bulletin

---

- Remove the air box to gain access to make the wiring repair (figure 2).



Figure 2

- Locate pins 12, 13 and 14 within the T14 connector.
- Using the VAS 1978 Wiring Harness Repair Kit, remove and replace pins 12, 13 and 14, 23cm (9 in.) behind the wiring harness end connector.

 **Tip:**

Reference SSP 871003 or VAS 1978 Wiring Kit Instruction Booklet for information on how to properly make wiring repairs per Volkswagen specification.



# Technical Bulletin

## Warranty

<b>To determine if this procedure is covered under Warranty, always refer to the Warranty Policies and Procedures Manual <sup>1)</sup></b>					
Model(s)	Year(s)	Eng. Code(s)	Trans. Code(s)	VIN Range From	VIN Range To
Tiguan	2013-2014	2.0L (CCTA)	All	All	All
<b>SAGA Coding</b>					
<b>Claim Type:</b>			<b>Use applicable Claim Type <sup>1)</sup></b>		
<b>Service Number:</b>	<b>Damage Code</b>	<b>HST</b>	<b>Damage Location (Depends on Service No.)</b>		
9752	0024	--	Use applicable when indicated in ElsaWeb (L/R)		
<b>Parts Manufacturer</b>	<b>Tiguan</b>		<b>WVO <sup>2)</sup></b>		
<b>Labor Operation <sup>3)</sup> : Remove and Install Air Box</b>			24251940 = 40 TU		
<b>Labor Operation <sup>3)</sup> : Repair Wiring Harness</b>			97094153 = 50 TU		
<b>Causal Part: Select Labor Operation</b>			97094153		
<b>Diagnostic Time <sup>4)</sup></b>					
<b>GFF Time expenditure</b>	01500000 = 30 TU max.		YES		
<b>Road Test</b>	01210004 = 10 TU		YES		
<b>Technical Diagnosis</b>	01320000 = 00 TU max.		NO		
<b>Claim Comment: Input "As per Technical Bulletin 2037108" in comment section of Warranty Claim.</b>					
<sup>1)</sup> Vehicle may be outside any Warranty in which case this Technical Bulletin is informational only <sup>2)</sup> Code per warranty vendor code policy. <sup>3)</sup> Labor Time Units (TUs) are subject to change with ELSA updates. <sup>4)</sup> Documentation required per Warranty Policies and Procedures Manual.					



# Technical Bulletin

## Required Parts and Tools

No special parts required.

Tool Description	Tool No:
VAS Diagnostic Tool	VAS 5051B, VAS 5052A, VAS 6150/X & VAS 6160/X with: ODIS Service 2.0.0 or higher with current online updates
Strip Pliers	VAS 1978/3
Crimp Pliers	VAS 1978/1-2 and VAS 1978/1-1
Hot Air Gun	VAS 1978/15
Wiring Harness Repair Kit	VAS 1978

Part Description	Part No:	Quantity
Wire with Pins	000 979 020 A	2
Connector with Shrink Tube	000 979 940	3

## Additional Information

All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.