Service Bulletin

Mazda North American Operations Irvine, CA 92618-2922



© 2014 Mazda Motor of America, Inc.

Subject:	Bulletin No:	02-004/14
STEERING WHEEL OFF CENTER WITHOUT DRIFT OR PULL	Last Issued:	11/4/2014
	11.	

BULLETIN NOTE

- This bulletin supersedes the previous bulletins 02-004/13 issued on 08/22/2013 and 04/10/2013, 02-004/12 issued on 09/19/2012 and 02/19/13, 02-005/10 issued on 03/26/10 and 11/05/10. The APPLICABLE MODEL(S)VINS have been revised.
- · Changes are noted below in Red beside the change bar.


APPLICABLE MODEL(S)/VINS

a set all the start set

I.	2011-2014 Mazda2	2013-2016 CX-5	2006-2015 MX-5
L	2004-2015 Mazda3	2007-2012 CX-7	2004-2011 RX-8
I.	2006-2014 Mazda5	2007- <mark>2015</mark> CX-9	2001-2011 Tribute
1	2003-2016 Mazda6	с. <i>п</i> .	

DESCRIPTION

Some customers may complain that the steering wheel is off center more than 3° even when driving straight on a flat road.



Customers having this concern should have their vehicle repaired using the following repair procedure.

Page 1 of 6

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.


Bulletin No: 02-004/14	 1 (**	Last Issued: 11/4/2014	1 2 E d 1
© 2014 Mazda Motor of America, Inc.			And an other second

REPAIR PROCEDURE


- 1. Verify customer concern and make sure there is no drift or pull concern.
 - If the steering is pulling to the right or the left, this procedure does not apply. Refer to MS3 online instructions for troubleshooting.
- 2. Measure the offset using "Measurement of Steering Wheel Offset."
 - If the offset is 3° or less, it is considered normal.
 - If the offset is more than 3°, adjust the steering wheel center using "Adjustment of Steering Wheel Center."
- 3. Verify repair.

Measurement of Steering Wheel Offset

1. Visually align the steering wheel to its center, then apply tape on the steering wheel and the steering column cover.




2. Put an alignment mark on the tape.




Bulletin No: 02-004/14 © 2014 Mazda Motor of America, Inc. Last Issued: 11/4/2014

3. Drive the vehicle and align the steering wheel to its driving center, then put another mark on the tape.




4. Measure the distance between the two lines. The offset can be approximately calculated using 1mm = 1° of offset.



Adjustment of Steering Wheel Center


1. Put an alignment mark over the tie-rod end and tie-rod as shown.



Bulletin No: 02-004/14 © 2014 Mazda Motor of America, Inc. Last Issued: 11/4/2014

2. Remove the boot clamp (A), then loosen the lock nut (B).

· Byels



Rotate the tie-rod to adjust the steering wheel center. Refer to the following charts for rotating direction.
NOTE: Rotate both sides of the tie-rod by the same amount.

- Steering wheel offset direction and tie-rod rotating direction -

FRONT WHEEL DRIVE (Vehicles with steering gear mounted to the rear side of the front axle)

Tie-rod adjust	Tie-rod rotating direction to adjust
Right side	Tighten the tie-rod towards the tie-rod end to decrease the length of the tie-rod.
Left side	Loosen the tie-rod from the tie-rod end to increase the length of the tie-rod.
	ಲಕ್ಷ್ ಮತ್ತು ಕಾರ್ಯಕ್ಷ ಪ್ರಶಸ್ತಿ ಮಾಡಿದ್ದ ಕಾರ್ಯಕ್ಷಿಸಿ. ಕ್ಷೇ ಬಂದಿಕ್ಕೆ ಕಾರ್ಯಕ್ಷ್ ಪ್ರಶಸ್ತಿ ಪ್ರಶಸ್ತಿ ಮಾಡಿದ್ದರೆ ಮಾಡಿದ್ದರೆ ಮಾಡಿದ್ದಾರೆ. ಮಾಡಿದ್ದಾರೆ ಮಾಡಿದ್ದಾರೆ ಮಾಡಿದ್ದಾರೆ ಮಾಡಿ
Right side	Loosen the tie-rod from the tie-rod end to increase the length of the tie-rod.
Left side	Tighten the tie-rod towards the tie-rod end to decrease the length of the tie-rod.
	Right side Left side Right side

Bulletin No: 02-004/14	• *	e Protect	Last Issued: 11/4/2014
© 2014 Mazda Motor of America, Inc.			

REAR WHEEL DRIVE (Vehicles with steering gear mounted to the front side of the front axle)

Steering wheel offset direction	Tie-rod adjust	Tie-rod rotating direction to adjust
Right	Right side	Loosen the tie-rod from the tie-rod end to increase the length of the tie-rod.
	Left side	Tighten the tie-rod towards the tie-rod end to decrease the length of the tie-rod.
ಎ. ಕೆ.ಕೆ. ಕಾರ್ಯಕ ್ಷ Left ಾಗ ಗಡ್ಡಾಗ ಸಂ ಸ ರ್ಕ ಕ	nd C. "Right side	Tighten the tie-rod towards the tie-rod end to decrease the length of the tie-rod.
	Left side	Loosen the tie-rod from the tie-rod end to increase the length of the tie-rod.
		The second se


A: Tie-rod

B: Lock nut C: Tie-rod end

F: Front of vehicle

1: Turn in this direction to loosen the tie-rod from the tie-rod end and increase the length.

2: Turn in this direction to tighten the tie rod towards the tie-rod end and decrease the length.



A A A A A A A A A A A A A A A A A A A	the second se	540
Bulletin No: 02-004/14	Last Issued: 11/4/2014	
© 2014 Mazda Motor of America, Inc.	2 [™] → 2 [™] B [*] = ² ¹ / ₂	

- (Reference) Steering wheel offset and tie-rod rotating angle -

Steering wheel offset to adjust	Tie-rod rotati	ng angle
4 mm (approximately 4°)	150°	. · · · ·
5 mm (approximately 5°)	180° (half turn)	en a a constante da
6 mm (approximately 6°)	210°	11.24
7 mm (approximately 7°)	240°	

4. Tighten the lock nut. Refer to MS3 online instructions for the tightening torque. REAL OF COMPANY

- 5. Straighten the boot, then attach the boot clamp.
- 1.1.4 In the second and all globals usy while deputers in the second secon Second sec 6. Verify repair. New second provide a second second

WARRANTY INFORMATION

NOTE:

This warranty information applies only to verified customer complaints on vehicles eligible for war-. ranty repair.

And the second in the window Website Matter in the CV

Same T & LPS

영안되고, 문안 지수

- This repair will be covered under Mazda's Service Adjustment Warranty term (12 months/12,000 • miles).
- Additional diagnostic time cannot be claimed for this repair. .
- This Service Bulletin cannot be combined with a wheel alignment. .

i i	
Warranty Type	A rosa
Symptom Code	30
Damage Code	9Н
Part Number Main Cause	5555-FE-001
Quantity	0
Operation Number / Labor Hours:	XXF11XAX / 0.4 Hrs.

34 423