# Service Bulletin

Mazda North American Operations Irvine, CA 92618-2922



© 2014 Mazda Motor of America, Inc.

Subject:

CHECK ENGINE LIGHT AND AUTOMATIC TRANSAXLE WARNING LIGHT ON WITH DTC P0842, P0847, P0872 AND/OR P0877 STORED IN TCM MEMORY

**Bulletin No:** 

05-005/14

Last Issued: 04/14/2014

## **BULLETIN NOTE**

- This bulletin supersedes the previous bulletin 05-005/14, issued on 04/09/14, 03/28/14 and 3/25/14. The WARRANTY INFORMATION has been revised.
- Changes are noted below in Red beside the change bar.

# APPLICABLE MODEL(S)/VINS

2012-2014 Mazda3 (with SKYACTIV 6AT) 2013-2015 CX-5 (with SKYACTIV 6AT) 2014-2015 Mazda6 (with SKYACTIV 6AT)

#### DESCRIPTION

Some vehicles may experience the check engine light and automatic transaxle warning light ON with DTC P0842, P0847, P0872 and/or P0877 stored in the TCM memory.

- P0842:00 Oil pressure switch No. 1 (oil pressure switch B) stuck on
- P0847:00 Oil pressure switch No. 2 (oil pressure switch A) stuck on
- P0872:00 Oil pressure switch No. 3 (oil pressure switch A) stuck on
- P0877:00 Oil pressure switch No. 4 (oil pressure switch B) stuck on

The DTC P0780 and/or P1738 may also be stored together.

- P0780:00 Gear shifting malfunction
- P1738:00 Automatic transaxle internal malfunction

This is caused by the oil pressure switch A and/or B at the control valve body temporarily or permanently getting stuck due to contamination entering the passage. To correct the problem, some mass production changes have been implemented to reduce contamination and improve the DTC diagnostic logic.

Customers having this concern should have their vehicle repaired using the following repair procedure.


## REPAIR PROCEDURE

- Verify customer concern.
- 2. Check for DTCs.
  - If any of the DTCs (P0842, P0847, P0872, P0877) is stored in TCM memory, go to step 3.
  - If any other DTCs are present or no DTCs are present, perform troubleshooting according to Workshop Manual.
- 3. Remove the oil pan from the transaxle according to the instructions on MS3 online or the Workshop Manual (section 05-17 CONTROL VALVE BODY REMOVAL/INSTALLATION [FW6AEL, FWAX-EL]).


Page 1 of 8

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ----without permission in writing


4. Remove the oil strainer (A) and the oil strainer O-rings (B) from the transaxle. F=Front of vehicle



- 5. Remove oil pressure switch A.
  - a. At oil pressure switch A, insert a precision flathead screwdriver (B) and move it in the direction of the arrow in the figure to disconnect the oil pressure switch A connector (C).




b. Remove the bolts for oil pressure switch A.




A CONTRACTOR STANFORM STANFORM

- c. Detach the tab shown and remove oil pressure switch A from the control valve body.
  - 1. Using an appropriate tool (such as a fastener remover), push the tab (A) of oil pressure switch A.



CAUTION: If the tab is broken during removal, make sure to remove the broken pieces.




2. Pull out oil pressure switch A by shaking it.


**CAUTION:** When removing oil pressure switch A, be careful not to damage the transaxle fluid temperature (TFT) sensor harness nearby.

6. Remove oil pressure switch B.

a. Insert a precision flathead screwdriver (A) and move it in the direction of the arrow as shown to disconnect the oil pressure switch B connector.




b. Remove oil pressure switch B.



7. Install new oil pressure switches A and B.

Bromage"


- 8. Verify that the tab of each oil pressure switch A and B is attached correctly.
- Install the bolts for oil pressure switches A and B.
   Tightening torque: 9-10 N•m {92-101 khf•cm, 80-88 in•lbf}



Bulletin No: 05-005/14
© 2014 Mazda Motor of America, Inc.

10. Connect the oil pressure switches A and B connectors.

THE HEADER




11. Install the oil strainer with new oil strainer O-rings according to the instructions on MS3 online or the Workshop Manual (section 05-17 CONTROL VALVE BODY REMOVAL/INSTALLATION [FW6AEL, FWAX-EL]).

**NOTE:** If there is a large amount of foreign material at the bottom of the oil pan, replace the oil strainer with a new one.

12. Install the oil pan according to the instructions on MS3 online or the Workshop Manual (section 05-17 CONTROL VALVE BODY REMOVAL/INSTALLATION [FW6AEL, FWAX-EL]).


**CAUTION:** Clean any remaining silicone sealant off the contact surfaces of the transaxle case and oil pan. a. Apply a light coat of silicon sealant to the contact surfaces of the oil pan and transaxle case.



Bulletin No: 05-005/14
© 2014 Mazda Motor of America, Inc.

Last Issued: 04/14/2014

b. Install the oil pan with new bolts before the applied sealant starts to harden.
 Tightening torque: 8-10 N·m {82-101 khf•cm, 71-88 in•lbf}



- 13. Install the removed parts.
- 14. Add ATF according to the instructions on MS3 online or the Workshop Manual (section 05-17 AUTOMATIC TRANSAXLE FLUID (ATF) REPLACEMENT [FW6A-EL] ).
- 15. Connect the negative battery cable.
- 16. Perform the Initial Learning Procedure. Refer to MS3 online instructions or Workshop Manual section 05-17.
- 17. Perform the Mechanical System Test. Refer to MS3 online instructions or Workshop Manual section 05-17.
- 18. For 2012-13 Mazda3, reprogram the TCM to the latest version by using Mazda Modular Diagnostic System (M-MDS) if the vehicle is within the following range.
  - VIN Range: JM1BL\*\*\*\*\*500001 733727 (through September 28, 2012 production)
  - TCM file name: PE08-21-PS1-J or older
  - a. Reboot the IDS to clear memory before reprogramming.
  - b. Using IDS 89.03 or later software, reprogram the PCM to the latest calibration (refer to "Calibration Information" table) by following the "Module Reprogramming" procedure.

#### NOTE:

or in the second

- Always update the IDS tool first, then follow on-screen instructions to download the needed calibration file for PCM reprogramming.
- It is not necessary to remove any fuses or relays during PCM reprogramming when the IDS screen prompts you to do so. You may accidentally stop power to one of the PCM terminals and cause the PCM to be blanked, or you may receive error messages during the IDS reprogramming procedure.
- IDS shows the calibration part numbers after programming the PCM.
- Please be aware that PCM calibration part numbers and file names listed in any Service Bulletin may change due to future releases of IDS software, and additional revisions made to those calibrations for service related concerns.
- When reprogramming a PCM, IDS will always display the "latest" calibration P/N available for that vehicle. If any calibration has been revised/updated to contain new information for a new service concern/issue, it will also contain all previously released calibrations.
- When performing this procedure, we recommend using the "Power Supply" mode in the Battery Management System to keep the vehicle battery up to capacity. If a different charger is used, make sure it does not exceed 20 AMPS. If it exceeds 20 AMPS, it could damage the VCM.

Bulletin No: 05-005/14	Last Issued: 04/14/2014
© 2014 Mazda Motor of America, Inc.	and the supply of the supply o

c. After performing the PCM reprogramming procedure, verify the repair by starting the engine and making sure there are no MIL illumination or abnormal warning lights present. Verify that the TCM file name is PE08-21-PS1-K or later.

## NOTE:

- If any DTCs should remain after performing DTC erase, diagnose the DTCs using MS3 online instructions or Workshop Manual section 01-02.
- After PCM reprogramming, it is no longer necessary to road test the vehicle to "relearn" KAM (Keep Alive Memory).

19. Verify repair.

Co. of Marti

## PART(S) INFORMATION

Part Number	Description	Qty.	Notes
FZ01-21-2C0	Switch A	1	
FZ01-21-2J0	Swtich B	1	
9YA0-10-615A	Bolt	16	Replace part
FZ01-21-031	O-ring	1 1	Replace part
FZ01-21-032	O-ring	1	Replace part
FU31-19-423	Plug	917	Replace part
9956-41-400	Drain Packing	1, 1,,	Replace part
FZ01-21-500	Oil Strainer	a <b>1</b> °	Replace if needed. FZ01-21-031 and FZ01-21-032 (O-rings) are included with this part.

് പെടുന്നു. അവരു പ്രത്യായ അളില്ലെ അവരു അതിന്റെ പ്രത്യായ വാന്ന് വഴിച്ചു. വിവര് വര് വിവര് വര് വര് വര് വര് വര് വര നിന്നു വര്യായ സാവ്യ് പ്രസ്ത്രീയ അതിന്റെ പ്രത്യായിൽ ആവ് വര്യായ പ്രവര്ത്തി വര് വര്യായ വര്യായ വര്യായ വര്യായ വര്യാ പ്രത്യായ പ്രത്യി വര്യായ സ്വ്യാര് വിവര്യായ വര്യായ വര്യായ വര്യായ വര്യായ വര്യായ വര്യായ വര്യായ വര്യായ വര്യായ വര്യാ

പട്ടെക്കുള്ളത് ഒരു അമുള്ള ക്രായത്ത്ത് പ്രവാധത്ത്ത്. ഉദ്വേശങ്ങളായ് പ്രവാശത്ത്വെ വിശ്നാവം വിശ്നാവം വിശ്രാത്ത് ഹോ ഇവര്ട്ടെ അവ്യായത്ത് പ്രവാധ പ്രത്യായില് ഇത് പ്രത്യാത്ത് നിന്നു ആര് പ്രവാധ വിശ്നായില് വിശ്രാത്ത്ത്ത്ത്ത്ത്ത് വിശ

intervante <sup>and</sup> translag in expatrological expansion (in the expension of the expension of

ന്ത് ഒ<sup>രു</sup> ത്രീന് "ടൂത്തും പ്രസ്തമാണ് അത് അഭിക്കാ അവസാനായ അത്രം വരുക്കുന്നത്. എന്നു വരു വരു അവസം എന്നായ അഭിക്കാ നിര് ത്രിക്ക് പ്രത്യാത്യത്ത് വിത്രത്തിൽ ത്രീത്ത് ത്രിത്ത്രം പരുത്തുക്കാന് വരുത്തില് ത്രിത്രയായും എന്നാര് വരുത് ഒരു ത്രിത്രിക്ക് ത്രീത്ത്രം പരത്തില് ത്രീയ്യ് സ്ത്രീത്ത് അവസ്തര് ഇത്തെ വ്യവത്ത് വരുത്തില് അവസ്തര്യം വരുത്തില്

FINANCE MINES NO.

Bulletin No: 05-005/14	Last Issued: 04/14/2014	
© 2014 Mazda Motor of America, Inc.		

# **WARRANTY INFORMATION**

## NOTE:

- This warranty information applies only to verified customer complaints on vehicles eligible for warranty repair.
- This repair will be covered under the following Warranty terms:
  - Powertrain Limited Warranty (CX-5)
  - Powertrain Limited Warranty ACA PZEV Emission Warranty where applicable (2012-13 Mazda3 with Oil Pressure Switch A and B Replacement, 2014 Mazda3 and 2014-15 Mazda6)
  - Federal Emission Warranty (long term) / CA PZEV Emission Warranty where applicable (2012-13 Mazda3 with Oil Pressure Switch A and B Replacement and TCM reprogramming)
- Additional diagnostic time cannot be claimed for this repair.

and the second department	Oil Pressure Switch A and B Replacement	Oil Pressure Switch A and B Replacement and TCM Reprogramming (*)		
Warranty Type	A			
Symptom Code	6X			
Damage Code	we will be the second of the s			
DTC	15P0842; P0847; P0872, or P0877 mos 350 datasen			
Part Number Main Cause	FZ01-21-2C0			
Quantity	1			
Operation Number / Labor Hours:	XXK43ARX / 1.8 Hrs. (1) A 71 edithermore emong servalist conscious 300M2 are rai	31411DE 300001-133121)		

(\*) NOTE: Reprogram the TCM to the newest version only when the TCM file name on the vehicle is PE08-21-PS1-J or older.