Service Bulletin

Mazda North American Operations Irvine, CA 92618-2922



© 2014 Mazda Motor of America, Inc.

Subject:	bject: BLUETOOTH SYSTEM INOPERATIVE		Bulletin No: 09-003/14	
BLUETOOTH SYSTEM INOPERATIVE	LUETOUTH STSTEM INOPERATIVE	Last Issued:	02/07/2014	
Contraction of the second	Constant in president in the state of the			

BULLETIN NOTE

- This bulletin supersedes the previous bulletin 09-003/14, issued on 1/14/2014. The DESCRIPTION, REPAIR
 PROCEDURE, PART(S) and WARRANTY INFORMATION have been revised.
- · Changes are noted below in Red beside the change bar.

APPLICABLE MODEL(S)/VINS

2014 CX-5 vehicles with VINs from JM3 KE ***** 367697 - 403269 (produced June 28, 2013 through October 11, 2013)

2013-2014 CX-9 vehicles with VINs from JM3 TB ***** 424547 - 428289 (produced June 26, 2013 through October 08, 2013)

2014 Mazda6 vehicles with VINs from JM1 GJ ****** 130589 - 151416 (produced July 01, 2013 through October 09, 2013)

DESCRIPTION

Some vehicles may experience one or more of the following Bluetooth® symptoms:

- When the vehicle started, the registered device would not connect with the Bluetooth® system. The Bluetooth, USB or Pandora tab on the audio display would not illuminate (gray out).
- The Bluetooth, USB or Pandora Tab on the audio display would illuminate, but the Bluetooth® system would not operate.
- When the customer presses the "Talk" button on the steering wheel, the audio display momentarily shows a message "Starting up Bluetooth Please wait" then the Bluetooth® unit does not work.

NOTE:

- · Phone Paired The steering wheel pickup button will only answer phone calls.
- Phone Not Paired The steering wheel pickup button will initiate Bluetooth® pairing function.

Diagnostic Support

- · Contact JCI Help Desk at 800-430-0153 from 7am-5pm Pacific Standard Time.
- Part authorization is not required for GJR9-66-DH0B.

Parts Exchange

Contact United Radio - refer to Dealer Assistance Group's "Exchange Central" on MX Connect.
 NOTE: United Radio does not provide technical support.

Customers having this concern should have their vehicle repaired using the following repair procedure.

Page 1 of 3

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

Last Issued: 02/07/2014	en al estadore de la companya de la Companya de la companya de la company
	Last Issued: 02/07/2014

REPAIR PROCEDURE

1

a the determinent of the at

1.74. 015

- 1. Have the symptoms described in the DESCRIPTION section of this bulletin been verified?
 - Yes Proceed to step 2.
 - No This bulletin does not apply. Contact JCI Help Desk at 800-430-0153 from 7am-5pm Pacific Standard Time for technical support or refer to MS3 online or Workshop Manual (section 09-03).
 - CX-5 TROUBLESHOOTING INDEX [Bluetooth SYSTEM (HANDS-FREE TELEPHONE (HF/TEL) SYSTEM)] S(A) = 0.42 = 0.000
 - CX-9 FOREWORD [Bluetooth SYSTEM (HANDS-FREE TELEPHONE (HF/TEL) SYSTEM)]
 - Mazda6 TROUBLESHOOTING INDEX [Bluetooth SYSTEM (HANDS-FREE TELEPHONE (HF/ TEL) SYSTEM)]
- 2. Replace the Bluetooth® unit with an exchange unit. Refer to MS3 online or Workshop Manual (section 09-120):
 - CX-5 Bluetooth UNIT REMOVAL/INSTALLATION
 - CX-9 Bluetooth UNIT REMOVAL/INSTALLATION
 - Mazda6 Bluetooth UNIT REMOVAL/INSTALLATION
- 3. Verify repair.

yana yana katala kat I	· color do anaco
	900: MCV - 11
4 <u>5</u>	-135 - €21-78.5
()∂()∂(Sa) ();	se (°, se estat, se estat, €) es
	1 A d
1. 1999年1月1日第二日第二日(第二日) 1995年1月1日第三日(第二日)	· · · · · · · · · · · · · · · · · · · ·
11.01.746.12 / 16.24M	

Pari autor trattornis not renuted for GLR9-86-DH0R

For in-story, reincres, neulers will be directed to order new parts. Only in story vehicles require installance of a new component and FBM authorization. Prese contact Deals: Anoistance Grour

Bulletin No: 09-003/14	Last Issued: 02/07/2014	1.1
© 2014 Mazda Motor of America, Inc.		

PART(S) INFORMATION

State Provide the State CITER CORRECT STATE STATE STATE AND A STATE ST

Part Number	Description	Qty. 5	Notes
GJR9-66-DH0B	Bluetooth Unit	• 1	Exchange Unit See the DAG Exchange Central website for the most current information.

I

NOTE: they excelled gots to the state of the dest funder reference offer for Batra and a second second

- This warranty information applies only to verified customer complaints on vehicles eligible for warranty repair.
- This repair will be covered under Mazda's New Vehicle Limited Warranty term.
- Additional diagnostic time cannot be claimed for this repair.
- Part authorization is not required for GJR9-66-DH0B.

Warranty Type	A
Symptom Code	61
Damage Code	9W
Part Number Main Cause	GJR9-66-DH0B
Quantity	0
Operation Number / Labor Hours:	CX-5 - XXK2LARX / 0.2 Hrs. CX-9 - XXK2LERX / 0.2 Hrs. Mazda6 - XXK2LCRX / 0.2 Hrs.

For in-stock vehicles, dealers will be directed to order new parts. Only in-stock vehicles require installation of a new component and DSM authorization. Please contact Dealer Assistance Group.