Tony Lawrence

From:

Tony Lawrence

Sent:

Wednesday, May 14, 2014 4:35 PM

To:

All Dirs All Rgns - PT; All Dirs All Rgns - SR

Subject:

MAZDA DEALER NOTICE - SERVICE BULLETIN RELEASE

SERVICE BULLETIN RELEASE - 05/14/2014

2014 INDEX: http://www.mstore2000.com/PDF Files/index05-14-14.pdf

The following Service Bulletin has just been issued.

- For latest MS3 postings, click here: https://portal.mazdausa.com/m173/service/esi/MazdaServiceShop
- For printable PDF files from MStore, click on the link below each TSB title:
- * If the links do not automatically take you directly to the document, cut and paste the link into your internet browser address window and press enter.

NEW BULLETIN

01-012/14 - 2009-2013 MAZDA6 3.7L - MIL ILLUMINATION WITH DTC P1450:00

http://www.mstore2000.com/PDF Files/01-012-14-2908.pdf

- · Please distribute this information to all parts and service personnel.
- If you no longer wish to receive Mazda bulletins, please contact the IT Administrator at your dealership and ask them
 to remove your email address from under the EMDCS application.

Service Bulletin

Mazda North American Operations Irvine, CA 92618-2922



© 2014 Mazda Motor of America, Inc.

ibject: MIL ILLUMINATION WITH DTC P1450:00	Bulletin No:	01-012/14
	Last Issued:	05/14/2014

APPLICABLE MODEL(S)/VINS

2009-2013 Mazda6 3.7L vehicles produced before March 31, 2012

DESCRIPTION

Some vehicles may experience a MIL illumination with a DTC P1450:00 stored in memory.

DTC P1450:00 - Unable to bleed up fuel tank vacuum

This concern may be caused by the purge valve, which has been modified to eliminate this concern.

Customers having this concern should have their vehicle repaired using the following repair procedure.

REPAIR PROCEDURE

- 1. Verify the MIL is illuminated and DTC P1450:00 is stored in memory.
- 2. Replace the purge solenoid valve with the modified part according to the instructions on MS3 online or the Workshop Manual (section 01-16 PURGE SOLENOID VALVE REMOVAL/INSTALLATION).
- 3. Verify the repair.

PART(S) INFORMATION

Part Number	Description	Qty.	Model Year	Spec.
CA07-20-370H	Purge Valve	1	2009-2013	M/T, Calif. A/T, Calif.
				M/T, Fed. / Canada
				A/T, Fed. / Canada

Page 1 of 2

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical—including photocopying and recording and the use of any kind of information storage and retrieval system —without permission in writing.

Bulletin No: 01-012/14	Last Issued: 05/14/2014
© 2014 Mazda Motor of America, Inc.	

WARRANTY INFORMATION

NOTE:

- This warranty information applies only to verified customer complaints on vehicles eligible for warranty repair.
- This repair will be covered under Mazda's New Car Limited Warranty (3/36) or California Emissions Defect Warranty Short Term (3/50).
- · Additional diagnostic time cannot be claimed for this repair.

Warranty Type	A
Symptom Code	6X
Damage Code	9W
Part Number Main Cause	CA07-20-370H
Quantity	1
Operation Number / Labor Hours:	F0621XRX / 1.0 Hrs. (includes time for code look up, clearing and onboard evaporative test)

was three surfain to a first should seed used strat atts of leading or any origin to but the

military and a 2004 confidence of the artists, having you will also as