



NUMBER: 02-003-14

GROUP: Front Suspension

DATE: April 29, 2014

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of Chrysler Group LLC.

SUBJECT:

Vehicle Leads or Drifts To The Right

OVERVIEW:

This bulletin involves an alignment specification change for camber.

MODELS:

2012-2014 WK Grand Cherokee

NOTE: This bulletin applies to SRT8 Badge (Sales Code MTV) vehicles built on or before November 1, 2013 (MDH 1101XX) equipped with 295/45ZR20 BSW All Season Tires (Sales Code TW7).

SYMPTOM/CONDITION:

Customer may describe a lead or drift to the right condition at steady state speeds at 35 MPH and above.

DIAGNOSIS:

If the customer describes the symptom, perform the Repair Procedure.

REPAIR PROCEDURE:

1. Test drive the vehicle on a right crowned road at 50 MPH steady state speed. Position the vehicle in the center of the driving lane between the two lines designating the lane width. While holding the steering wheel with a controlled grip, allow the vehicle to find its own direction (simulating hands free). Record the amount of time it takes for the front right tire to touch the right hand line prior to making a correction to keep the vehicle in the lane. Repeat the procedure driving in the opposite direction (Example: If initial test is performed driving North, repeat the procedure driving South on the same road). Calculate the average time between the two tests. Is the average time for the vehicle to lead/drift to the edge of the lane **greater** or **less** than 5 seconds?
 - a. Average time is **less** than 5 seconds>>> Proceed with the alignment camber specification change Step #2.
 - b. Average time is **greater** than 5 seconds>>> This bulletin does not apply.

2. Align the vehicle using the front wheel camber settings listed in the following specification table. Refer to the detailed service procedures available in DealerCONNECT> TechCONNECT under: Service Info> 02 - Front Suspension> Wheel Alignment.

Left Camber	Right Camber	Cross Camber
-1.30 +/-0.55°	-1.60 +/-0.55°	+0.30 +/-0.55°

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
02-00-01-97	Test Drive Vehicle (2 - Skilled)	4 - Chassis Systems	0.2 Hrs.
02-00-01-98	Test Drive Vehicle And Front Wheel Alignment (2 - Skilled)	4 - Chassis Systems	1.3 Hrs.

FAILURE CODE:

ZZ	Service Action
----	----------------