

**NUMBER:** 02-004-14 REV. B

**GROUP:** Front Suspension

DATE: November 25, 2014

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of Chrysler Group LLC.

THIS BULLETIN SUPERSEDES SERVICE BULLETIN 02-004-14 REV. A, DATED MAY 22, 2014, WHICH SHOULD BE REMOVED FROM YOUR FILES. ALL REVISIONS ARE HIGHLIGHTED WITH \*\*ASTERISKS\*\* AND INCLUDES THE ADDITION OF SRT8 VEHICLES.

# SUBJECT:

Vehicle Leads or Drifts To The Left - Right Hand Drive (RHD)

## **OVERVIEW:**

This bulletin involves an alignment specification change for camber.

### **MODELS:**

2012-2014

(WK)

Jeep Grand Cherokee (International Only)

NOTE: This bulletin applies to Right Hand Drive (RHD) vehicles built on or before February 28, 2014 (MDH 0228XX).

NOTE: \*\*This bulletin applies to Right Hand Drive (RHD) SRT8 Badge (Sales Code MTV) vehicles built on or before June 22, 2014 (MDH 0622XX) equipped with 295/45ZR20 BSW All Season Tires (Sales Code TW7).\*\*

### SYMPTOM/CONDITION:

Customer may describe a lead or drift to the left condition at steady state speeds of 56 KPH (35 MPH) and above.

# **DIAGNOSIS:**

If the customer describes the symptom, perform the Repair Procedure.

# REPAIR PROCEDURE:

- 1. Test drive the vehicle on a left crowned road at 80 KPH (50 MPH) steady state speed. Position the vehicle in the center of the driving lane between the two lines designating the lane width. While holding the steering wheel with a controlled grip, allow the vehicle to find its own direction (simulating hands free). Record the amount of time it takes for the front left tire to touch the left hand line prior to making a correction to keep the vehicle in the lane. Repeat the procedure driving in the opposite direction (Example: If initial test is performed driving North, repeat the procedure driving South on the same road). Calculate the average time between the two tests. Is the average time for the vehicle to lead/drift to the edge of the lane **greater** or **less** than 7 seconds?
  - a. Average time is **less** than 7 seconds>>> Proceed with the alignment camber specification change Step #2.
  - b. Average time is **greater** than 7 seconds>>> This bulletin does not apply.
- Align the vehicle using the front wheel camber settings listed in the following specification table. Refer to the detailed service procedures available in DealerCONNECT> TechCONNECT under: Service Info> 02 - Front Suspension> Wheel Alignment.

| Product Line                        | Left Camber    | Right Camber   | Cross Camber     |
|-------------------------------------|----------------|----------------|------------------|
| Base Suspension (RHD)               | -0.45 +/-0.60° | -0.03 +/-0.60° | -0.40 +/-0.60°   |
| Air Suspension (Aero<br>Mode) (RHD) | -1.07 +/-0.60° | -0.67 +/-0.60° | -0.40 +/-0.60°   |
| **SRT Suspension<br>(RHD)           | -1.60 +/-0.55° | -1.30 +/-0.55° | -0.30 +/-0.55°** |

#### POLICY:

Reimbursable within the provisions of the warranty.

#### TIME ALLOWANCE:

| Labor Operation<br>No: | Description   | Skill Category         | Amount   |
|------------------------|---|------------------------|----------|
| 02-00-01-97            | Test Drive Vehicle (2 - Skilled)                              | 4 - Chassis<br>Systems | 0.2 Hrs. |
| 02-00-01-98            | Test Drive Vehicle And Front Wheel<br>Alignment (2 - Skilled) | 4 - Chassis<br>Systems | 1.3 Hrs. |

### **FAILURE CODE:**

| ZZ | Service Action |
|----|----------------|
|    |                |