



NUMBER: 21-034-14
GROUP: Transmission and Transfer Case
DATE: November 01, 2014

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of Chrysler Group LLC.

HELP USING THE wiTECH DIAGNOSTIC APPLICATION FOR FLASHING AN ECU IS AVAILABLE BY SELECTING “HELP” THEN “HELP CONTENTS” AT THE TOP OF THE wiTECH DIAGNOSTIC APPLICATION WINDOW.

THE wiTECH SOFTWARE LEVEL MUST BE AT 15.02 OR HIGHER TO PERFORM THIS PROCEDURE.

SUBJECT:

Flash: 948TE 9 Speed Shift Enhancements And Quick Learn Enable

OVERVIEW:

This bulletin involves selectively erasing and reprogramming the Transmission Control Module (TCM) with new software.

MODELS:

2015	(KL)	Jeep Cherokee
2015	(UF)	Chrysler 200

NOTE: This bulletin applies to vehicles equipped with the following:

- **KL vehicles equipped with a 2.4L engine (sales code ED6) or 3.2L engine (sales code EHB) and equipped with the 948TE 9 speed transmission (sales code DFH or DFJ) built on or before October 20, 2014 (MDH 1020XX)**
- **UF vehicles equipped with a 2.4L engine (sales code ED6) and equipped with the 948TE 9 speed transmission (sales code DFH) built on or before October 24, 2014 (MDH 1024XX).**

SYMPTOM/CONDITION:

The following TCM calibration update is being released to enable the new wiTECH based “Transmission Quick Learn” procedure to be performed anytime the transmission adaptation memory cells are cleared or when addressing customer concerns of poor shift quality. It is also being released to improve transmission downshift response time during normal driving.

DIAGNOSIS:

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in TechCONNECT, verify all vehicle systems are functioning as designed. If DTCs or other conditions are present, record them on the repair order and repair as necessary before

proceeding further with this bulletin.

If the symptom/condition described above is present, perform the repair procedure.

REPAIR PROCEDURE:

NOTE: Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charging voltage to climb above 13.5 volts during the flash process.

NOTE: If this flash process is interrupted/aborted, the flash should be restarted.

1. Using wiTECH, check the TCM calibration and see if it is up to date. Does the TCM software need to be updated?
 - a. Yes>>> Verify no other applicable published service actions are open regarding TCM programming and proceed to Step #2.
 - b. No>>> This service bulletin does not apply. The TCM already contains all necessary software to perform the "Quick Learn." Refer to the detailed service procedures and labor times in all current published service bulletins available in Service Information regarding the 948TE 9 Speed Quick Learn procedure.
2. Reprogram the TCM with the latest software. Detailed instructions for flashing control modules using the wiTECH Diagnostic Application are available by selecting the "HELP" tab on the upper portion of the wiTECH window, then "HELP CONTENTS." This will open the Welcome to wiTECH Help screen where help topics can be selected.

NOTE: After reprogramming, the following must be performed.

3. Using wiTECH, perform a "PROXI Configuration Alignment" routine.
4. Perform the TCM "VIN Verification" routine.
5. Clear any DTCs that may have been set in any modules due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allow the tech to clear them.

NOTE: This flash will clear the transmission adaptive values which requires the newly enabled "Quick Learn" procedure to be performed. Refer to the detailed service procedures and labor times in all applicable, current, published service bulletins available in Service Information regarding the 948TE 9 Speed Quick Learn procedure.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
18-19-05-Q9	Module, Transmission Control Module- (TCM) - Reprogram (1 - Semi Skilled)	2 - Automatic Transmission	0.3 Hrs.

NOTE: The expected completion time for the flash download portion of this procedure is approximately 3 minutes. Actual flash download times may be effected by vehicle connection and network capabilities.

FAILURE CODE:

FM	Flash Module
----	--------------