

01 MIL on (DTCs for "system rich": P1137, P1127, P1139, P1129)

01 14 73 2031458/5 March 18, 2014. Supersedes Technical Service Bulletin Group 01 number 13-45 dated December 5, 2013 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
S4, S5	2010-12		
A6	2012		
A7	2012	All	3.0 engine
A6 (C6)	2009-11		
Q7	2011-12		

Condition

REVISION HISTORY			
Revision	Date	Purpose	
5	-	Revised header data (Updated engine code)	
4	12/5/2013	Revised header data (Added customer codes; added DTCs)	
3	1/17/2013	Revised <i>Condition</i> (Added DTCs) Revised <i>Warranty</i> (Updated SRTs)	
2	12/17/2012	Revised Required Parts and Tools (Updated parts table)	
1	11/5/2012	Original publication	

MIL on.

- One or more of following DTCs stored in the engine control module (ECM), J623 (address word 01):
 - DTC P113700 (Bank1, mixture adaptation (add) System too rich)
 - DTC P112700 (Bank1, mixture adaptation (mult) System too rich)
 - DTC P113900 (Bank2, mixture adaptation (add) System too rich)
 - DTC P112900 (Bank2, mixture adaptation (mult) System too rich)

© 2014 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

Technical Service Bulletin



Technical Background

Under extreme driving conditions (such as short-distance, stop-and-go driving), high crankcase pressure can cause the DTCs to appear.

The condition can be improved and the DTCs eliminated when the crankcase pressure valve is changed to a lower operating pressure and the ECM software is updated to compensate for new crankcase pressure.

Production Solution

Crankcase pressure reduction starting with model year 2013.

Service

1. Replace crankcase pressure regulating valve using the instructions in Elsa (*Repair Manual >>Engine >> Engine Mechanical >> 17 Lubrication >> Removal and Installation >> Cover with Oil Separator*) with part number **06E103547H.**



Tip: Reuse collected oil.

- 2. Follow all instructions in TSB 2011732, 00 Software Version Management (SVM), operating instructions.
- 3. Update the ECM using SVM action code as listed in the table below if necessary.

Model	Engine	Old Software Part Number	Old Software Version	New Software Part Number	New Software Version	SVM Action Code
A6 2009 – 2011	CCAA	4F1910551A	All	4F1910551D	0050	
S4, S5 Cab 2010 – 2012	ССВА	8K0907551 A&B	All	8K0907551D	0003	
A6 / A7 2012	CGXB	4G0907551A	All	4G0907551A	0007	01A092
Q7 2011 – 2012	CJWB	4L0910551K	0010	4L0910551K	0040	
	CJMC	4L0910551A	0010	4L0910551A	0050	
2011 - 2012	CJWE	4L0910551J	0010	4L0910551J	0040	

© 2014 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

Warranty

Claim Type:	Use applicable claim type. If vehicle is outside any warranty, this Technical Service Bulletin is informational only.				
Service Number:	1050				
Damage Code:	0010				
Labor Operations: Q7:					
	Pressure regulating valve remove + install (reduced for overlap)	1050 9999	80 TU		
	Fuel rail remove + install	2441 2089	70 TU		
	Compressor remove + install	2114 1939	160 TU		
	S4/S5 Cab:				
	Pressure regulating valve remove + install	1050 1941	370 TU		
	A6/A7:				
	Pressure regulating valve remove + install (reduced for overlap)	1050 1999	50 TU		
	Fuel rail remove + install	2441 2091	70 TU		
	Compressor remove + install	2114 1941	160 TU		
	All				
	Fuel bleed	2003 0091	10 TU		
	SVM software update	2470 2599	50 TU		
Diagnostic Time:	GFF	0150 0000	20 TU		
	Road test prior to service procedure	No allowance	0 TU		
	Road test after service procedure	0121 0004	10 TU		
	Technical diagnosis at dealer's discretion (Refer to Section 2.2.1.2 and Audi Warranty Online for DADP allowance details)				
Claim Comment:	As per TSB #2031458/5				

Page 3 of 4

© 2014 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

Technical Service Bulletin





Technical Service Bulletin

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual.* Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Parts Number	Part Description	Quantity
06E103213	Vent Tube	1
06E103547H	Crankcase pressure regulating valve	1
06E998907D	Repair kit	6
N 90316802	O-Ring Seal	1
079129717B	Seal	6
079129717D	Seal	6
G 012A8G1G	Coolant for top off	0.3 quarts

Additional Information

The following Technical Service Bulletin will be necessary to complete this procedure:

• TSB 2011732 00 Software Version Management (SVM), operating instructions.

All parts and service references provided in this TSB (2031458) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.

© 2014 Audi of America, Inc.

Page 4 of 4

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.