

# Technical Service Bulletin



## 20 MIL on (DTC P310B with symptom code 6183) - Repair Authorization

20 14 36 2038113/1 August 14, 2014.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A4	2014	All	CTUB engine
A5	2014	All	CTUB engine
A5 Cabriolet	2014	All	CTUB engine
A6, A7	2014	All	CTUA engine
A8	2014	All	CTUB engine
Q5	2014	All	CTUC and CTUD engines

## Condition

- MIL on.
- **DTC P310B** is stored in the engine control module, J623 (address word 01), with symptom code 6183 (Figure 1).

### DTC memory entry

Number :

P310B00: Low Fuel Pressure regulation Fuel pressure outside specification

Error type 2 :

passive/sporadic

Symptom :

6183

*Figure 1. Log showing DTC.*

## Technical Background

Various parts have been replaced under warranty for the condition noted above, but no issues were identified with these parts. In an effort to gain information on the DTC code listed above, we are asking that you contact the Audi Technical Assistance Center (TAC) before replacing any parts. This will assist us in diagnosing any potential issues with the condition noted above.

## Production Solution

No changes to production have been made, as no issue has been identified.

## Service

Audi of America is requesting your cooperation in supplying us with technical information regarding this condition. Verify the condition.

If the vehicle is within the New Vehicle Limited Warranty, contact a TAC consultant before proceeding. Attach the DTC and diagnostic log to the TAC ticket.

## Warranty

This TSB is informational only and not applicable to any Audi warranty.

## Additional Information

All parts and service references provided in this TSB (2038113) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.