Recall Bulletin

Bulletin No.: 14121A Date: March 2014









PRODUCT SAFETY RECALL

SUBJECT: Transmission Oil Cooler Connection

MODELS: 2014 Chevrolet Silverado Light Duty Regular Cab, Double Cab, Crew Cab

1500 Series

2015 Chevrolet Suburban, Tahoe

2014 GMC Sierra Light Duty Regular Cab, Double Cab, Crew Cab 1500

Series

2015 GMC Yukon, Yukon XL

Equipped with 6-Speed Automatic Transmission (MYC)

It is a violation of Federal law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by this notification under a sale or lease until the defect or noncompliance is remedied.

All involved vehicles that are in dealer inventory must be held and not delivered to customers, dealer traded, or used for demonstration purposes until the repair contained in this bulletin has been performed on the vehicle.

The part description for part number 23135704 has been revised and a Note statement before Step 2.4 has been added. Please discard all copies of bulletin 14121.

CONDITION

General Motors has decided that a defect which relates to motor vehicle safety exists in 2014 MY Chevrolet Silverado Light Duty Regular Cab, Double Cab, Crew Cab 1500 Series and 2015 MY Suburban and Tahoe; GMC 2014 MY Sierra Regular Cab, Double Cab, Crew Cab 1500 Series and 2015 MY Yukon and Yukon XL vehicles equipped with a 6-Speed Automatic Transmission (MYC). The subject vehicles may have a transmission oil cooler line that is not securely seated in the fitting. If the line is not securely seated and transmission oil leaks from the fitting, the oil could contact a hot surface and result in a vehicle fire.

CORRECTION

Dealers are to inspect the connection and repair it, if necessary.

VEHICLES INVOLVED

All involved vehicles are identified by Vehicle Identification Number on the Investigate Vehicle History screen in GM Global Warranty Management system. Dealership service personnel Copyright 2014 General Motors. All Rights Reserved.

should always check this site to confirm vehicle involvement prior to beginning any required inspections and/or repairs. It is important to routinely use this tool to verify eligibility because not all similar vehicles may be involved regardless of description or option content.

For dealers with involved vehicles, a listing with involved vehicles containing the complete vehicle identification number, customer name, and address information has been prepared and will be provided to US and Canadian dealers through the GM GlobalConnect Recall Reports, or sent directly to export dealers. Dealers will not have a report available if they have no involved vehicles currently assigned.

The listing may contain customer names and addresses obtained from Motor Vehicle Registration Records. The use of such motor vehicle registration data for any purpose other than follow-up necessary to complete this recall is a violation of law in several states/provinces/countries. Accordingly, you are urged to limit the use of this report to the follow-up necessary to complete this recall.

PART INFORMATION

Parts required to complete this recall are to be obtained from General Motors Customer Care and Aftersales (GMCC&A). Please refer to your "involved vehicles listing" before ordering parts. Normal orders should be placed on a DRO = Daily Replenishment Order. In an emergency situation, parts should be ordered on a CSO = Customer Special Order.

Important: It is estimated that 10 or fewer involved vehicles will require replacement of the transmission oil cooler lines. Please order parts accordingly.

Part Number	Description	Quantity/Vehicle
23141324	PIPE, TRANS FLUID CLR INL & OTLT	1
23141324	(all V8 and all utility vehicles)	(if req'd)
23135704	PIPE, TRANS FLUID CLR INL & OTLT	1
23133704	(V6 built on or before 7/14/13)	(if req'd)
23141325	PIPE, TRANS FLUID CLR INL & OTLT	1 (if req'd)
23141323	(V6 built on or after 7/15/13)	
88861037 - US	FLUID, A/TRANS(DEXRON 6)	As Needed
19264717 - CN	1 LOID, A/ INANO(DEXIVON 0)	As inceded

SERVICE PROCEDURE


Notice: Ten or fewer vehicles are expected to require replacement of the transmission fluid cooler inlet and outlet pipes.

1. Raise and support the vehicle. Refer to Lifting and Jacking the Vehicle in SI.



3792999


- (1) Transmission Cooler Lines (2) Quick Connect Fittings (3) Thermal Bypass Valve
- 2. Inspect the transmission cooler lines where they connect to the thermal bypass valve.
 - 2.1 Determine if the upper and lower transmission cooler lines are installed correctly by performing a visual inspection of the transmission cooler line connections into the thermal bypass valve.



3793000

Photograph shows a fluid leak at the quick connect fitting (2) of the transmission cooler line (1) and thermal bypass valve (3).

2.2. Inspect the area around the thermal bypass valve (3) and the end of the transmission cooler line (1) for evidence of a fluid leak.




3793301

The transmission cooler line (1) is fully seated into the thermal bypass valve. Notice that a yellow line is NOT present and there is no evidence of a fluid leak.

2.3 Ensure the transmission cooler lines (1) are fully seated into the thermal bypass valve (3).

Note: The yellow band should not be visible above the top of the fitting itself. If it is visible above the top of the fitting, then the pipe is not fully inserted and seated, refer to illustration.

- 2.4 Determine if a yellow mark is present at the end of the transmission cooler line at the quick connect fitting.
 - If a yellow mark is not present, proceed to step 2.5.



3793000

The transmission cooler line (1) is NOT fully seated into the thermal bypass valve. Notice that a yellow line (4) is present and there is evidence of a fluid leak.

Note: The yellow band should not be visible above the top of the fitting itself. If it is visible above the top of the fitting, then the pipe is not fully inserted and seated, refer to illustration.

• If a yellow mark (4) is present, remove and replace the transmission cooler line with a new line. Refer to *Transmission Fluid Cooler Inlet and Outlet Pipe Replacement* in SI.

- 2.5 Using your hands, firmly pull on the ends of the transmission cooler lines to verify a good connection between the transmission cooler lines and the thermal bypass valve, and then perform a visual inspection to verify the connection. Pull the transmission cooler lines toward the front of the vehicle. The transmission cooler line should NOT pull out of the fitting.
 - If the upper and lower transmission cooler lines are installed correctly, no further action is required. Lower the vehicle. Refer to Lifting and Jacking the Vehicle in SI.
 - If an upper or lower transmission cooler line is installed incorrectly, remove and replace the transmission cooler line with a new line. Refer to *Transmission Fluid Cooler Inlet and Outlet Pipe Replacement* in SI.

COURTESY TRANSPORTATION - For US and Canada

The General Motors Courtesy Transportation program is intended to minimize customer inconvenience when a vehicle requires a repair that is covered by the New Vehicle Limited Warranties. The availability of courtesy transportation to customers whose vehicles are within the warranty coverage period and involved in a product program is very important in maintaining customer satisfaction. Dealers are to ensure that these customers understand that shuttle service or some other form of courtesy transportation is available and will be provided at no charge. Dealers should refer to the General Motors Service Policies and Procedures Manual for Courtesy Transportation guidelines.

WARRANTY TRANSACTION INFORMATION

Submit a transaction using the table below. All transactions should be submitted as a ZFAT transaction type, unless noted otherwise.

Note: If replacement of the transmission oil cooler lines is required, submit a warranty transaction under normal warranty, using the published time in the Labor Time Guide

Labor		Labor
Code	Description	Time
9100457	Inspect Transmission Cooler Lines – No Further Action Req'd	0.3

CUSTOMER NOTIFICATION – For US and Canada

General Motors will notify customers of this recall on their vehicle (see copy of customer letter included with this bulletin).

<u>CUSTOMER NOTIFICATION</u> – For Export

Letters will be sent to known owners of record located within areas covered by the US National Traffic and Motor Vehicle Safety Act. For owners outside these areas, dealers should notify customers using the attached sample letter.

<u>DEALER RECALL RESPONSIBILITY</u> – For US and Export (US States, Territories, and Possessions)

It is a violation of Federal law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by this notification under a sale or lease until the defect or noncompliance is remedied.

The US National Traffic and Motor Vehicle Safety Act provides that each vehicle that is subject to a recall of this type must be adequately repaired within a reasonable time after the customer has tendered it for repair. A failure to repair within sixty days after tender of a vehicle is prima facie evidence of failure to repair within a reasonable time. If the condition is not adequately repaired within a reasonable time, the customer may be entitled to an identical or reasonably equivalent vehicle at no charge or to a refund of the purchase price less a reasonable allowance for depreciation. To avoid having to provide these burdensome remedies, every effort must be made to promptly schedule an appointment with each customer and to repair their vehicle as soon as possible. In the recall notification letters, customers are told how to contact the US National Highway Traffic Safety Administration if the recall is not completed within a reasonable time.

<u>DEALER RECALL RESPONSIBILITY</u> – All

All unsold new vehicles in dealers' possession and subject to this recall <u>must</u> be held and inspected/repaired per the service procedure of this recall bulletin <u>before</u> customers take possession of these vehicles.

Dealers are to service all vehicles subject to this recall at no charge to customers, regardless of mileage, age of vehicle, or ownership, from this time forward.

Customers who have recently purchased vehicles sold from your vehicle inventory, and for which there is no customer information indicated on the dealer listing, are to be contacted by the dealer. Arrangements are to be made to make the required correction according to the instructions contained in this bulletin.

In summary, whenever a vehicle subject to this recall enters your vehicle inventory, or is in your dealership for service in the future, you must take the steps necessary to be sure the recall correction has been made before selling or releasing the vehicle.