



# Service Bulletin

File in Section: -

Bulletin No.: PIP4653E

Date: June, 2014

## PRELIMINARY INFORMATION

**Subject:** DTCs P0601 P0603 P0604 P062F or P1621 (Stored In The TCM)

**Models:** 2008-2014 Buick Enclave  
2013-2014 Buick Encore  
2010-2014 Buick Lacrosse  
2011-2014 Buick Regal  
2012-2014 Buick Verano  
2008-2009 Cadillac XLR  
2008-2014 Cadillac CTS, SRX  
2008-2013 Cadillac Escalade EXT  
2008-2015 Cadillac Escalade, Escalade ESV  
2008-2011 Cadillac STS  
2013-2014 Cadillac ATS  
2008-2013 Chevrolet Avalanche  
2008-2014 Chevrolet Corvette  
2008-2015 Chevrolet Silverado, Suburban, Tahoe  
2009-2014 Chevrolet Captiva  
2009-2015 Chevrolet Cheyenne  
2008-2014 Chevrolet Equinox, Malibu  
2009-2014 Chevrolet Traverse  
2010-2014 Chevrolet Camaro  
2010-2014 Chevrolet Caprice  
2010-2014 Chevrolet Express 2011-2014 Chevrolet Cruze  
2011-2014 Chevrolet Orlando  
2012-2014 Chevrolet Impala  
2013-2014 Chevrolet Trax  
2014 Chevrolet SS  
2007-2014 GMC Acadia  
2008-2015 GMC Sierra, Sierra Denali, Yukon, Yukon Denali, Yukon XL, Yukon Denali XL  
2010-2014 GMC Terrain  
2008-2009 Hummer H2  
2008-2009 Pontiac G8  
2008-2009 Pontiac Torrent  
2008-2010 Pontiac G6 2007-2010 Saturn Aura, Outlook  
2008-2010 Saturn Vue  
Equipped with 6T30, 6T40, 6T45, 6T50, 6T70 or 6T75 Automatic Transmission RPO's  
MH2 MH4 MH6 MH7 MH8 MH9 MHC MHH MHJ MHK MNH MY9 or 6L45, 6L50, 6L80 or  
6L90 Automatic Transmission RPO's MYA, MYB, MYC, MYD

This PI was superseded to update recommended field, models and model years. Please discard PIP4653D.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### **Condition/Concern**

Customers may comment on a MIL. Technicians may find DTCs P0601, P0603, P0604, P062F or P1621 stored in the TCM as an active or a history code.

### **Recommendation/Instructions**

**Important:** Some of these DTCs can also be set in the ECM or FPCM. Make sure that you know which module (for example ECM, FPCM or TCM) has set the DTC before attempting to diagnose and repair this condition.

SI diagnostics for these DTCs instruct to reprogram the TCM and recheck for the DTCs. Before reprogramming the TCM use the Tech 2 (certain 2010 thru 2015 models will require the use of GDS2) to verify that the DTC is set in the TCM. If the DTC is set in a module other than the TCM, refer to SI for the appropriate diagnostics.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.