

## **Technical Bulletin**

| Model(s)      | Year(s) | Eng. Code(s)   | Trans.<br>Code(s) | VIN Range From | VIN Range To |
|---------------|---------|----------------|-------------------|----------------|--------------|
| Jetta<br>(A6) | 2011    | 2.0L<br>(CBPA) | Manual            | All            | All          |

### **Condition**

**01 14 03** February 14, 2014 **2026529** Supersedes Technical Bulletin V011328 dated August 13, 2013 to update part number, software version and SVM code.

Update Programming to Eliminate DTC P050A Stored in ECM Fault Memory

| DTC   | Description                                    |  |
|-------|--|--|
| P050A | Cold Start Idle Air Control System Performance |  |

### **Technical Background**

Customers may complain of a MIL ON condition, which is caused by DTC P050A.

**DO NOT** replace any parts for this condition.

The condition as described **does not** affect vehicle performance or operation.

### **Production Solution**

Improved software was introduced in production.

# Ope Auto

## **Technical Bulletin**

#### **Service**

#### **Update Programming Procedure:**



To Update-Programming using SVM, **review and follow** instructions in **Technical Bulletin Instance 2014603** "Software Version Management".

The SVM Process must be completed in its entirety so the database receives the update confirmation response. A warranty claim may not be reimbursed if there is no confirmation response to support the claim.



#### Note:

Prior to launching the VAS-PC and ODIS service diagnostic applications and starting control module update process, confirm tester screen saver and power settings in accordance with Special Tools and Equipment - Service Information Circular # VVT-12-02. Failure to do so may result in the tester entering power save mode during data transfer, and subsequent control module failure.

When using a VAS 6150/5051B or VAS 5052A tester in conjunction with a VAS 5054A wireless transmitter head for a flash procedure, please connect a USB cable between the transmitter head and the tester. Failure to do so may lead to errors during the flash procedure.

VAS tools must only be used with their power adapters plugged in. Under no circumstances should they be used on battery power alone during the programming procedure.

<u>Critical Warning:</u> The Midtronics Battery Charger <u>must</u> be connected to the vehicle battery for the duration of the programming, to ensure the battery state of charge remains above 12.5 volts during the update process. If the battery drops below 12.5 volts, the programming could fail which may result in damage to the control module. Control modules damaged by inadequate voltage will not be covered under the warranty policy. The technician should verify the vehicle voltage prior to starting the update process, and should monitor the voltage for the duration of the update.

Update the Engine Control Module using the SVM action code as listed in the table below:

| Model | Engine | Old Software Part<br>No. | Old<br>Software<br>Version | New Software Part<br>No. New | Software<br>Version (or<br>higher) | SVM<br>Action<br>Code |
|-------|--------|--------------------------|----------------------------|------------------------------|------------------------------------|-----------------------|
| Jetta | 2.0L   | 06G 906 055 B            |                            | 06G 906 055 AD               | <mark>1302</mark>                  |                       |
| (A6)  | (CBPA) | 06G 906 055 C            | All                        | 06G 906 055 AE               | <mark>1302</mark>                  | <mark>3989</mark>     |

# Dos Auto

## **Technical Bulletin**

The procedure can be found in GFF under Functions/ Component Selection, Software Version Management, Adapting Software.



Upon completion of software update, verify Cruise Control function (if originally equipped) is activated via GFF Function Test Plan 01 – Activate/Deactivate Cruise Control System.



Radiator Fan(s) may cycle ON high speed during the Update Process! There is a risk that personal injury may result if contact is made with spinning fan blades.

Keep hands and all objects away from Radiator Fan(s) during Update Process!



The SVM Process must be completed in its entirety so the database receives the update confirmation response. A warranty claim may not be reimbursed if there is no confirmation response to support the claim or action is carried out that is not explicitly stated in the Technical Bulletin.

Ensure attached ECM/TCM Tuning Form has been completed and signed by customer as required in SVM Technical Bulletin Instance 2014603.

### **Warranty**

| To determine if the Procedures Manua |        | is cover       | red under      | Warraı                       | nty, always refer                              | to the Warranty Pol                      | icies and    |
|--------------------------------------|--------|----------------|----------------|------------------------------|--|--|--------------|
| Model(s)                             | Year(s | Eng. Code(s)   |                | ode(s)                       | Trans. Code(s)                                 | VIN Range From                           | VIN Range To |
| Jetta<br>(A6)                        | 2011   | 2.0L<br>(CBPA) |                | Manual                       | All  | All                                      |              |
| Claim Type:                          |        |                |                | Use applicable Claim Type 1) |  |  |              |
|                                      |        |                | S              | AGA C                        | oding  |  |              |
| Service Number:                      |        |                | Damage<br>Code |                              | нѕт  | Damage Location (Depends on Service No.) |              |
| 2470                                 |        | 0039           |                |                              | Use applicable when indicated in ElsaWeb (L/R) |  |              |

Page 3 of 5 plus attachment



## **Technical Bulletin**

| Parts Manufacturer                                 |                       | 3ME <sup>2)</sup>      |     |  |
|--|-----------------------|------------------------|-----|--|
| Labor Operation <sup>3)</sup> : Update Programming |                       | 24702599 = 30 TU       |     |  |
| Labor Operation 3): Charge Batte                   | ry                    | 27068950 = 10 TU       |     |  |
| Causal Part: Select Labor Operat                   | ion                   | 24702599               |     |  |
|  | Diagnost              | tic Time <sup>4)</sup> |     |  |
| GFF Time expenditure                               | 01500000 = 30 TU max. |                        | YES |  |
| Road Test  | 01210002 = 00 TU      |                        | NO  |  |
|  | 01210004 = 00 TU      |                        |     |  |
| Technical Diagnosis                                | 01320000 = 00 TU max. |                        | NO  |  |

Claim Comment: Input "As per Technical Bulletin 2026529" in comment section of Warranty Claim.

### **Required Parts and Tools**

No Special Parts required.

| Tool Description                  | Tool No:   |
|-----------------------------------|--|
| Midtronics Battery Tester/Charger | InCharge 940 (INC-940)                                   |
| VAS Diagnostic Tool               | VAS 5051B, VAS 5052A, VAS 6150/X & VAS 6160/X with:      |
|                                   | ODIS Service 2.0.0 or higher with current online updates |

<sup>1)</sup> Vehicle may be outside any Warranty in which case this Technical Bulletin is informational only

<sup>&</sup>lt;sup>2)</sup> Code per warranty vendor code policy.

<sup>3)</sup> Labor Time Units (TUs) are subject to change with ELSA updates.

<sup>&</sup>lt;sup>4)</sup> Documentation required per Warranty Policy & Procedures Manual.



## **Technical Bulletin**

### **Additional Information**

All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.



# OWNER INFORMATION ABOUT CONTROL MODULE TUNING\* ACKNOWLEDGEMENT AND AUTHORIZATION FOR REPROGRAMMING (REFLASHING) OF CONTROL MODULE(S)

| *) "TUNING" is described as the addition of or modification of any cor<br>Volkswagen vehicle to perform outside the normal parameters and sp<br>Volkswagen Group of America / Volkswagen Group Canada.                            |                           |
|---|---------------------------|
| Date:   |                           |
| Dealer Number:  |                           |
| Vehicle Identification Number:  |                           |
| Repair Order Number:  |                           |
|   | Dealer stamp              |
| I, owner or driver of the above identified  |                           |
| "Tuning" as described above (especially power increasing modifiperformed on my vehicle.   |                           |
| Tuning" as described above has been performed on my vehicle and were modified or installed:   | the following components  |
| TUNING was performed by (Please provide Company name and telepho to contact them):  | ne number, if you wish us |
| I understand that if my Control Module is determined to have been tuned the tuning of the Control Module (including adverse emissions conseque by VWGoA / VGC warranties.   |                           |
| I am permitting an authorized Volkswagen Dealer to reflash (update) my doing so, I understand that this process will automatically overwrite (d delete any tuning program that was previously installed on the Control M vehicle. | estroy) and permanently   |
| By signing below, I fully acknowledge and understand that the tuning pro<br>and VWGoA / VGC, will not be liable in any way for the loss of tuning da  |                           |
| Signature   | of Customer               |