



Service Bulletin

File in Section: -

Bulletin No.: PIP5165B

Date: June, 2014

PRELIMINARY INFORMATION

Subject: Oil dripping Out Of The Air Filter Box

Models: 2014 Chevrolet Corvette
6.2L LT1 with Option Z51 Dry Sump Engine W/Manual or Auto Trans

This PI was superseded to change the wording for the condition/concern.
Please discard PIP5165A.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

If the oil is not properly check and is over filled, this will force oil out of the PCV into the induction system.

The second possible cause if the customer drives aggressively with low miles on the car it is possible to push oil through the PCV system.

Recommendation/Instructions

No internal repairs are required.

Properly check the oil level prior any repairs.

Please follow oil level check procedure found in the Owner's Manual or SI.

If the oil level is found to be over filled, please make sure the service consultant reviews the oil check procedure with the owner.

Change the oil and filter.

Remove the air cleaner assembly.

Clean any oil out of the filter housing and duct.

Remove the MAF clean off any oil.

Make sure that there is no residual oil in the PVC lines.

Install a new air filter in the air box.

Reinstall the air box assembly.

Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
4020390	Air Cleaner Assembly Replacement	Use Published Labor Operation Time

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.