

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Golf/GTI	2015	All	All	All	All

## Condition

87 14 10 September 25, 2014 2038368

### Air Conditioning Does Not Cool and or Compressor is Noisy

One or more of the following conditions are exhibited:

- The air conditioning does not cool, or the cooling performance is very weak.
- The air conditioning system cools, but the compressor is noisy. The noise is characterized as a grinding or groaning noise.
- Either symptom may be intermittent.
- No DTCs are stored.

## **Technical Background**

The condition may be caused by a faulty A/C compressor regulator valve (N280). The internal components of the valve can be obstructed and incapable of full function. This loss of refrigerant regulation from N280 can cause noise from the air conditioning compressor and/or affect the HVAC cooling.

## **Production Solution**

Final production countermeasures pending.



## Service

Since either symptom may be intermittent, the diagnostic process can affect the reproducibility of the condition. Begin the diagnosis by isolating the cause before performing the basic checks.

#### Cases of noise:

When diagnosing cases of noise, use chassis ears or a technician's stethoscope to make sure that the root cause of the noise is from the air conditioning compressor. The noise can change or may be absent depending on the setting on the HVAC control unit. In many cases, the noise is more pronounced with the system switched OFF.

#### Cases of low or no cooling performance:

Perform the following diagnostic steps:

- 1. Connect a manifold gauge set to monitor the refrigerant circuit pressures.
- 2. With the engine at idle, switch the climate control unit to full cold and full fan.
- 3. Using the diagnostic tester, monitor the measuring value for the air conditioner compressor regulating value N280 signal. The actual and specified values will be plausible and will show a normal regulating range of current for cooling request (0.600 A 0.680 A). However, there will be equalized pressure readings on the high and low sides of the circuit (no pressure generation from the compressor).
- 4. Evacuate the refrigerant circuit to determine the refrigerant volume. The refrigerant volume will likely be in specification. Should the refrigerant volume be too low, investigate a potential refrigerant leak in the circuit. It is not likely that the refrigerant level will be too great since this should store a DTC.
- 5. If the air conditioning compressor is found to be the root cause of either of these conditions, Replace the compressor.

### 1 Note:

The N280 regulating valve is not available as a replacement part apart from the compressor assembly.

© 2014 Volkswagen Group of America, Inc.

Page 2 of 9



Air conditioning compressor replacement:



Figure 1: Sanden compressor identification tag.



Figure 2: Denso compressor identification tag.

- The flushing procedure can be found in Elsa at: Heating, Ventilation & Air Conditioning>>Refrigerant R134a Servicing >>00 General Technical Data>> Refrigerant circuit removing contaminates>>Refrigerant Circuit, Cleaning (Flushing), with Refrigerant R134a. The procedure is also described in Technical Service Bulletin 2019947.
- The correct adapters for the 2015 Golf/GTI can be found in Elsa at: Ventilation & Air Conditioning>>Refrigerant R134a Servicing >>00 General Technical Data>> Refrigerant circuit removing contaminates>>Refrigerant Circuit, Cleaning (Flushing), with Refrigerant R134a >>Adapter for Assembling Flushing Circuit.

## 🕕 Note

This bulletin is specifically for N280 malfunction. The expansion valve can be reinstalled after the flushing procedure.

© 2014 Volkswagen Group of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

The originally installed compressor on the MY 2015 Golf/GTI is manufactured by Sanden (Figure 1). The replacement compressor is manufactured by Denso (Figure 2).

### 🕕 Note:

All MY2015 GTI/Golf have Sanden factory compressors. The replacement compressor is 100% Denso.

It is necessary to flush the system to clean the refrigerant circuit of Sanden PAG. Failure to do so can cause damage to the new compressor.





Figure 3: Compressor manufacturer specific PAG oils.

The replacement compressor will come with the specified type of PAG oil for the compressor (Figure 3). The amount of PAG oil supplied with the replacement compressor may not be the exact amount required to replenish the refrigerant circuit. Drain and measure the PAG oil in the replacement compressor to determine the required amount. If the amount needs to be adjusted, do so using the correct type of PAG oil specified in ETKA. Refer to Elsa for the correct oil capacity for the compressor being installed.

© 2014 Volkswagen Group of America, Inc.

Page 4 of 9



## Warranty

To determine if th Procedures Manu		dure is co	overed under Warr	anty, always refer	to the Wa	arranty Po	olicies and
Model(s)	Yea	ır(s)	Eng. Code(s)	Trans. Code(s)	VIN Range From		VIN Range To
Golf/GTI	20	15	All	All	All		All
SAGA			Coding				
Claim Type: Use applicable Claim Type			<sup>1)</sup>				
Service Number:			Damage Code	HST		Damage Location (Depends on Service No.)	
8734		0010		Use applicable when indicated in Elsa (L/R)			
Parts Man	Parts Manufacturer Go		Goli	/GTI	GTI SYP		′P
Labor Operation <sup>3)</sup> : Refrigerant drain and fill			87031700 = 60 TU				
Labor Operation <sup>3)</sup> : A/C compressor remove and reinstall (1.8/2.0 TSI)			87341970 = 50 TU				
Labor Operation <sup>3)</sup> : A/C compressor remove and reinstall (2.0 TDI)			87701955 = 60 TU				
Labor Operation <sup>3)</sup> : Radiator grill remove and reinstall			66051900 = 20 TU				
Labor Operation <sup>3)</sup> : Receiver drier replace (non-Modine)			87555550 = 30 TU				
Labor Operation <sup>3)</sup> : Receiver drier replace (Modine)			8755552 = 40 TU				
Labor Operation <sup>3)</sup> : Expansion valve remove and reinstall			87701900 = 50 TU				
Labor Operation <sup>3)</sup> : Air conditioner clean			87012999 = 140 T	U			

 $\ensuremath{\textcircled{\text{c}}}$  2014 Volkswagen Group of America, Inc.

Page 5 of 9



Outside Material: A/C Flush Machine filter, Part No. BA1783400103		\$3.51 total per A/C System Flush which accompanies a repair (this amount equals ¼ of the cost of the A/C flush machine filter)	
Causal Part:		5Q0820803F	
	Diagnos	tic Time <sup>4)</sup>	
GFF Time expenditure	01500000 = 20 T	U max.	YES
Road Test	01210002 = 10 T 01210004 = 10 T	-	YES
Technical Diagnosis	01320000 = 20 T	U max.	YES
Claim Comment: Input "As p	er Technical Bulletin 20	38368" in comment	section of Warranty Claim.
<ol> <li>Vehicle may be outside any</li> <li><sup>2)</sup> Code per warranty vendor</li> </ol>		e this Technical Bu	lletin is informational only
<sup>3)</sup> Labor Time Units (TUs) are	subject to change with	ELSA updates.	

<sup>4)</sup> Documentation required per Warranty Policy Procedures Manual.

© 2014 Volkswagen Group of America, Inc.

Page 6 of 9



### **Required Parts and Tools**

Part Description	Part No:	Quantity		
Oil for refrigerant compressor - Denso	G 052300A2	0.2 (Max if required)		
Air conditioner compressor	5Q0820803F	1		
Seal ring	4D0260749B	1		
Seal ring	4E0260749A	1		
Seal ring	8E0260749C	1		
Seal ring	4E0260749B	1		
Drier insert with mounting parts	5Q0298403A	1		

Tool Description	Tool No:
VAS6337/1A	ROB134APF
Robinair A/C Service Unit	

 $\ensuremath{\textcircled{\text{c}}}$  2014 Volkswagen Group of America, Inc.

Page 7 of 9



Air Conditioning Flush Tool	VAS 6337/1A
Refrigerant Circuit Adapter 3	VAS 6338/3
	VAS 6338/12
Refrigerant Circuit Adapter 12	VAS 6338/38

 $\ensuremath{\textcircled{\text{c}}}$  2014 Volkswagen Group of America, Inc.

Page 8 of 9



## **Additional Information**

All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.

© 2014 Volkswagen Group of America, Inc.

Page 9 of 9