



Service Bulletin

File in Section: -

Bulletin No.: PIC6013

Date: July, 2014

PRELIMINARY INFORMATION

Subject: Diagnostic Tip - Adaptive Cruise Temporarily Unavailable

Models: 2013 - 2015 Cadillac XTS, And SRX With RPO PCX
2013 - 2015 Cadillac ATS With RPO Y66
2014 - 2015 Cadillac CTS Sedan (VIN A) With RPO Y66

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

A customer may comment they receive an "ADAPTIVE CRUISE TEMPORARILY UNAVAILABLE" message on the DIC when attempting to activate the cruise

Recommendation/Instructions

If normal diagnostics lead to a concern that can be duplicated, and there are no Diagnostic Trouble Code's please perform the yaw rate sensor learn procedure (Multi Axis Sensor), clear any dtc's that may have been set during programming, and let vehicle go to sleep before evaluating the concern.

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
2880288*	Relearn Multi Axis Sensor (YAW Sensor)	0.3 hr
* This is an unique labor operation for bulletin use only. This will not be published in the Labor Time Guide.		

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.