



Service Bulletin



SERVICE UPDATE

SUBJECT: Service Update for Inventory and Customer Vehicles
Reprogram Engine Control Module
Expires with Base Warranty

MODELS: 2015 Chevrolet Silverado
2015 GMC Sierra
With 6.6L Duramax Diesel Engine (RPO LML)

All involved vehicles that are in dealer inventory must be held and not delivered to customers, dealer traded, or used for demonstration purposes until the repair contained in this bulletin has been performed on the vehicle.

This service update includes vehicles in dealer inventory and customer vehicles that return to the dealership for any reason. This bulletin will expire at the end of the involved vehicle's New Vehicle Limited Warranty period.

PURPOSE

This bulletin provides a service procedure to reprogram the ECM (Engine Control Module) on **certain** 2015 model year Chevrolet Silverado and GMC Sierra trucks equipped with the 6.6L Duramax diesel engine (RPO LML). If a braking event is immediately followed by an aggressive attempt to accelerate on some of these vehicles, especially when driving with one foot on the brake and one foot on the throttle, the customer may experience up to a 5 second lag in acceleration performance due to the Enhanced Electronic Pedal Override being activated ("EEPO intervention") and a subsequent reduced power mode. EEPO intervention is normal, but in this vehicle, the EEPO intervention may be more frequent than desired due to certain calibrations. The dealer will reflash the engine control module with a revised calibration at the next service visit.

This service procedure should be completed as soon as possible on involved vehicles currently in dealer inventory and customer vehicles that return to the dealer for any type of service during the New Vehicle Limited Warranty coverage period.

VEHICLES INVOLVED

All involved vehicles are identified by VIN in the Global Warranty Management System – Investigate Vehicle History Application. Dealership technicians should always check this site to confirm vehicle involvement prior to beginning any required inspections and/or repairs. It is

important to routinely use this tool to verify eligibility because not all similar vehicles may be involved regardless of description or option content.

Customer vehicles that return for service, for any reason, and are still covered under the vehicle's base warranty should also be checked for vehicle eligibility.

PART INFORMATION

No parts required.

SERVICE PROCEDURE

Note: Carefully read and follow the instructions below.

- Do NOT attempt to order the calibration number from GM Customer Care and Aftersales. The calibration numbers required for this service procedure are programmed into control modules via a Multiple Diagnostic Interface (MDI) with the calibration update. If you cannot access the calibration, call the Techline Customer Support Center and it will be provided.
- DO NOT program a control module unless directed to by a service procedure or a service bulletin. If the control module is not properly configured with the correct calibration software, the control module will not control all of the vehicle features properly.
- Ensure the programming tool is equipped with the latest software and is securely connected to the data link connector. If there is an interruption during programming, programming failure or control module damage may occur.
- Stable battery voltage is critical during programming. Any fluctuation, spiking, over voltage or loss of voltage will interrupt programming. When required install the *EL-49642* SPS Programming Support Tool to maintain system voltage. If not available, connect a fully charged 12 V jumper or booster pack disconnected from the AC voltage supply. DO NOT connect a battery charger.
- Turn OFF or disable systems that may put a load on the vehicles battery such as; interior lights, exterior lights (including daytime running lights), HVAC, radio, etc.
- During the programming procedure, follow the SPS prompts for the correct ignition switch position.
- Clear DTCs after programming is complete. Clearing powertrain DTCs will set the Inspection/Maintenance (I/M) system status indicators to NO.
- Note the engine oil life remaining percentage.

To reprogram an existing K20 Engine Control Module, perform the following procedure:

1. Install *EL-49642* SPS programming support tool.
2. Access the Service Programming System (SPS) and follow the on-screen instructions. Refer to Service Programming System (SPS) documentation in SI for programming instructions.
3. On the SPS Supported Controllers screen, select *K20 Engine Control Module - Programming* and follow the on-screen instructions.
4. Clear DTCs after completing the programming procedure.

Note: If vehicle fails to start during Configuration and Setup, perform the SPS Function Immobilizer Learn and follow the on-screen instructions.

5. Perform the SPS function *K20 Engine Control Module - Configuration & Setup* and follow the on-screen instructions, if available.

6. Clear DTCs after completing the Configuration & Setup procedure.

WARRANTY TRANSACTION INFORMATION

Submit a transaction using the table below. All transactions should be submitted as a ZFAT transaction type, unless noted otherwise.

Labor Code	Description	Labor Time
9100808	Engine Control Module Reprogramming with SPS	0.3

DEALER PROGRAM RESPONSIBILITY

Whenever a vehicle subject to this service update enters your vehicle inventory, or is in your facility for service in the future, and the vehicle is still covered under the New Vehicle Limited Warranty, you must take the steps necessary to be sure the service update correction has been made before selling or releasing the vehicle.



GM CUSTOMER CARE AND AFTERSALES
DCS3304
URGENT - DISTRIBUTE IMMEDIATELY

Date: August 19, 2014

Subject: 14466 – Service Update Bulletin
Reprogram Engine Control Module

Models: 2015 Chevrolet Silverado
2015 GMC Sierra
With 6.6L Duramax Diesel Engine (RPO LML)

To: All Chevrolet and GMC Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, New Vehicle Sales Manager,
and Warranty Administrator

General Motors is releasing Service Update Bulletin 14466 today. The total number of U.S. vehicles involved is approximately 26,000. Please see the attached bulletin for details.

Global Warranty Management (GWM)

The "Investigate Vehicle History" (IVH) screen will be updated August 19, 2014.

END OF MESSAGE

GM CUSTOMER CARE AND AFTERSALES