

TECHNICAL BULLETIN
JTB00322NAS1
06 JAN 2014



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Jaguar service facility to determine whether this bulletin applies to a specific vehicle.

SECTION: 412-01

Integrated Control Panel Software Update

AFFECTED VEHICLE RANGE:

F-TYPE (X152)

Model Year: 2014

VIN: K00001-K07299

MARKETS:

NAS

CONDITION SUMMARY:

Situation: The Integrated Control Panel may experience one or more of the following issues:

- The selected temperature display is inoperative/blank;
- The amber status illumination is inoperative; and/or
- The blue halo illumination is inoperative.

Cause: This may be due to a software issue within the Integrated Control Panel.

Action: Should a customer express this concern, follow the Service Instruction outlined below.

PARTS:

No Parts Required

TOOLS:



NOTE: This document is an 'Active Bulletin' that will display a functional programming shortcut if accessed within a diagnostic session using SDD.

SDD with latest DVD and Calibration File; first available on DVD136.00 v.154
Jaguar Land Rover-approved Midtronics battery power supply

WARRANTY:



NOTE: Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPIx to obtain the latest repair time.



NOTE: DDW requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART

Update Integrated Control Panel software	86.99.83	0.2	42	T2R1931
--	-----------------	-----	----	---------



NOTE: Normal Warranty policies and procedures apply.

SERVICE INSTRUCTION:

1.  **CAUTION: A Jaguar Land Rover-approved Midtronics battery power supply must be connected to the vehicle battery during SDD diagnosis / module programming.**



NOTE: SDD must be loaded with DVD136.00 v.154 or later.

Connect the Jaguar Land Rover-approved Midtronics battery power supply to the vehicle battery.



NOTE: The Integrated Control Panel may also be referred to as the Front Controls Interface Module (heating ventilation air conditioning controls).

2. Turn ignition 'ON' (engine not running).
3. Connect the Symptom Driven Diagnostics (SDD) system to the vehicle and begin a new session.
4. Follow the on-screen prompts, allowing SDD to read the VIN and identify the vehicle and initiating the data collect sequence.
5. Select 'Diagnosis' from the Session Type screen.
6. Select the 'Selected Symptoms' tab, and then select one of the following:
 - Electrical - Climate control system - Air conditioning controls **or**
 - Electrical - Lighting - Interior lighting - Locate illumination - Inoperative **or**
 - Electrical - Lighting - Interior lighting - Panel display background illumination - Inoperative
7. Select 'continue'.
8. Select the 'Recommendations' tab, and then select '**Run**' to perform the 'Configure existing module – Front controls interface module (heating ventilation air conditioning controls)' option.
9. Follow all on-screen instructions to complete this task.
10. Exit the current session.
11. Disconnect the SDD and the battery power supply from the vehicle.