

TECHNICAL BULLETIN
LTB00641NAS1
13 FEB 2014



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

SECTION: 415-01

AM/FM Interference

AFFECTED VEHICLE RANGE:

LR2 (LF)

Model Year: 2013 Onwards

VIN: DH321215 Onwards

MARKETS:

NAS

CONDITION SUMMARY:



NOTE: The situation described below affects only the analogue bands; it does not affect HD Radio® digital AM/FM operation.

Situation: Poor radio reception may be present on either the AM or FM analogue radio band.

Cause: This may be caused by radio interference.

Action: Should a customer express concern, follow the Service Instruction outlined below.

PARTS:

LR046783	Filter	Quantity: 1
	Cable ties (to be sourced locally)	Quantity: 2

TOOLS:

Refer to Workshop Manual for any required special tools.

WARRANTY:



NOTE: Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPIx to obtain the latest repair time.



NOTE: DDW requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.


DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Trim panel - D-Pillar - Remove and refit	76.13.73	0.3	42	LR046783
Filter - Modify and install	05.10.20	0.2	42	LR046783




NOTE: Normal Warranty policies and procedures apply.

SERVICE INSTRUCTION:

1. Remove the right-hand D-Pillar trim panel (see TOPIX Workshop Manual, section 501-05).
2. Modify the filter bracket by elongating both holes by 5mm.




3. Remove the existing fixing nuts from the audio system mounting bracket.
 - Install the filter using the fixing nuts from the audio system mounting bracket.
 - Torque: 3.5 Nm



4. Disconnect the radio speaker electrical wiring harness connector (C4ME162).
 - Install the new filter inline, connect one end to the speaker at C4ME162, and connect the fly lead to the main harness.



- 5. Using suitable cables ties, secure the filter wiring harness to the main vehicle harness.



- 6. Install the right-hand D-Pillar trim panel (see TOPIx Workshop Manual, section 501-05).