## Data collection.doc

Reference SSM71738

Models Range Rover Evoque / L538

Title DTC P2610-85

Category Engine

Last modified 26-Feb-2014 00:00:00

Symptom 499000 Basic Engine

Issue:

On a small number of L538 2.0GDTl vehicles DTC P2610-85 is logged causing the check engine indicator to

appear on the IPC.

Cause:

The cause is being investigated and information is

Content required to help establish root cause.

Action:

Information is required from the customer.

In all occurrences of this fault please fill in the attached document detailing the information required and attach it

to an EPQR.



## Information from the customer

If the fault has occurred more than once please fill in one form for each occurrence of the fault.

1.	VIN number
2.	Date of occurrence
3.	Was the fuel fired heater used to heat the car when the fault occurred?
4.	Is an electrical block heater installed?
5.	Was the electrical block heater used when the fault occurred?
6.	If the fuel fired heater was used, how long was it used for before the car was started? Minutes
7.	Was the vehicle parked outside or inside when it was started?
8.	What was the time between when the engine was last running and when the vehicle was started?
	Hours
9.	What was the engine temperature (1 to 5 on the diagram below) when the vehicle was switched off on the last
	drive before the fault occurred?
	$ \begin{array}{cccccccccccccccccccccccccccccccccccc$
10.	How long was the vehicle driven for on the last drive before the fault occurredMinutes
11.	What was the air temperature around the vehicle when it was started, if unsure please provide a range e.g between 0° and -10 ℃ ℃
12.	Was air temperature unusually cold when the fault occurred? (Yes/No)
13.	Did the engine crank more slowly than normal before it started (Yes/No)
14.	After starting the vehicle how long did it take for the fault to occur?minutes
15.	How many times per week is the vehicle used?
16.	How many times per week is the fuel fired heater used?
17	Has the vehicle had this fault before – please indicate the number of times the fault occurred





## **Dealership Actions**

Please scan for fault codes and record these here:
·
Please note if there are communication issues with the BCM this can result in fault P2610-85 please address the CAN communication errors first.
Save the vehicle TraceXML file, from SDD and label as 'Trace 1'
After recording ECU fault codes perform a fault code clear.
Leave the vehicle for 4 hours or more at the same air temperature as when the fault occurred then measure the battery voltage when the car is cranking – record the lowest voltage seen whilst the vehicle is cranking
After starting the vehicle rescan for fault codes and record these here:
Also save this TraceXML and label as 'Trace 2'

Please submit an EPQR and attach the SDD TraceXML files to the EPQR