

	GROUP <b>Chassis</b>	MODEL <b>2016MY Sorento (UMa)</b>
	NUMBER <b>PS390</b>	DATE <b>March 2015</b>



## TECHNICAL OPERATIONS

**SUBJECT:** SORENTO (UMa) – CREAKING NOISE FROM FRONT SUSPENSION

When diagnosing a customer complaint of a creaking or popping noise coming from the front suspension while accelerating or decelerating, inspect the two (2) rearmost sub-frame bolts (A) to verify the correct bolt was installed during assembly. The correct bolt should have a raised hexagonal crown and an irregularly-shaped flange (Fig B). If the incorrect bolt is found to be installed, remove and replace using P/N 62492 C5000.

**Tightening torque: 43.4 ~ 50.6 lb-ft (58.8 ~ 68.6 N·m)**

Additionally, if the vehicle was produced prior to February 25, 2015, inspect the top strut nut (C) for proper torque.

**Tightening torque: 39.8 ~ 54.2 lb-ft (53.9 ~ 73.5 N·m)**

