

2015 Lancer Evolution

In This Issue	2
Vehicle Technical Info	page 1
Training News	Page 3
Techline Information	page 4
MEDIC Information	page 4
Bulletin Review	page 4

Vehicle Technical Info

GROUP 11 - Engine

INTERMITTENT ENGINE STALLING — 2014–15 Outlander. MMNA has begun an investigation into intermittent stalling on affected vehicles. If a customer reports their vehicle stalling when accelerating or decelerating, please collect the following information and contact Techline.

- Throttle input (accelerating or slowing)
- Fuel level at the time of the last event
- Brand and octane rating of the last fill up
- Time and mileage since last fill up
- Vehicle speed at the time of the event
- If a rough idle was noticed prior to the event

GROUP 31 - Wheel & Tire

CHECKING TIRE PRESSURE AT PDI — All models. MMNA would like to remind you that checking tire pressure during PDI is a simple, but very important, step in improving IQS and CSI. This is especially true of the spare tire. It is probably the most overlooked of the tires when it comes to maintaining pressure. Its location and mounting in the trunk requires the tire to be lifted, and turned over to access the valve. Please check the pressure at PDI and all service visits and make sure the spare is properly inflated. A customer having a flat tire has already been

inconvenienced. The inconvenience is made worse if the spare is flat.


Overinflated tires can can create and induce BSR, generate complaints of harsh riding, steering drift or pulling, and cause premature center tread tire wear among other conditions. Under inflated tires can lead to reports of poor fuel economy, poor tire wear, excessive tire noise, premature outside edge tire wear and can lead to tire overheating and cause a tire failure.

The correct tire inflation pressure for each model can be found on the "Tire and Loading Information" label which is usually located on the driver's "B" pillar or driver's door structure.

California dealers are reminded that they are required by law (http://www.arb.ca.gov/regact/2009/tirepres09/tirefinalreg.pdf) to check tire pressure any time a vehicle is "repaired or maintained" at their facility.

GROUP 52A – Interior

SEAT CUSHION COVER LOOSE, RETAINING CLIPS DETACHED — 2013–15 Outlander Sport/RVR. If a customer reports the seat cushion cover (seat bottom) is loose, check under the seat to see if the cover retaining strips are detached. Over time, the white plastic "J hooks" can lose their shape and become detached, causing the cover to loosen. If you find that a loose seat cushion cover is caused by detached cover retaining clips, discuss the possibility of repair with a local upholstery shop to determine if the cover can be securely reattached using "hog rings" or some other suitable retention method. Do not replace the cover unless it cannot be successfully reattached by an upholstery shop.



GROUP 52B - SRS

<u>MEMORY</u> — 2011-15 Outlander Sport/RVR, 2007-15 Outlander, 2008-15 Lancer, Lancer Sportback, Lancer Evolution, 2014 Mirage. The subject DTCs are set when the occupant classification module (OCM) communicates a fault to the SRS-ECU. If you find either B223D or B1558 in SRS-ECU memory, the service manual will tell you to check the for OCM DTCs.

As the code that identifies what you diagnosed and repaired, record the OCM DTC in the "DTC" field on the "Labor" page when submitting a warranty claim. Knowing the root cause of a fault, identified in this case by the OCM DTC, helps MMNA and MMC with their investigations, which helps them quickly develop countermeasures when needed.

GROUP 54 - Chassis Electrical

MODIFICATIONS TO LANE DEPARTURE WARNING (LDW) — 2015 Outlander. In order to improve the customer's experience of using LDW some changes have been made to the following features for the 2015 model year:

- Decreased audible/visual warning time from 10 to 3 seconds
- LDW can be set to remain in the last mode selected (ON or OFF) until manually changed
- Reduced warnings when driving on winding or narrow roads by increasing programmed lane width to 3.0 meters (9.82 ft)

Keep these changes in mind when addressing questions regarding the 2015 Outlander LDW system.

GROUP 60 - Recalls

ATIN-14-SR-011-A: OUTLANDER SPORT FRONT PASSENGER SEAT BELT LAP END ATTACHMENT FASTENER — 2013-15 Outlander Sport/RVR. ATIN-14-SR-011-A was recently sent to dealers and states:

"A safety recall campaign will be released today for the front passenger seat belt lap end attachment fastener on certain 2013 – 2015 Outlander Sport vehicles built July 20, 2012 – July 23, 2014. Do not deliver any affected 2013 – 2015 Outlander Sport vehicles built July 20, 2012 – July 23, 2014 until this recall has been performed. This recall campaign will be conducted in the U.S. and Canada. The Recall Bulletin outlining the repair procedure will be available today on MEDIC and MDL.

Due to a supplier error, the front passenger seat belt lap end attachment fastener may not be torqued to specification. If the tightening torque of the fastener is too low, further loosening of the fastener due to vibrations experienced while driving cannot be excluded. If this occurs, the fastener might not withstand the required loads under all circumstances, potentially resulting in insufficient front passenger occupant restraint during a crash.

Dealers are requested to torque the fastener to specification.

Notification letters will be sent to owners of affected vehicles, requesting they contact their local Authorized Mitsubishi dealership to schedule an appointment to have this recall performed.

Affected new vehicle inventory VINs can be reviewed on the Mitsubishi Dealer Link in the Most Recent: Open Campaign List available under the service section of "e-reports". Dealers must review the Warranty Superscreen to confirm if any vehicles in their new or used vehicle inventories are affected, and conduct this campaign prior to delivering them. When checking for applicability of this campaign (C1416Z), please check for and complete any other open campaigns. Always get the customer's approval before completing a campaign on a customer owned vehicle. "

IMPORTANT

Affected new or used inventory vehicles must be repaired before the vehicle is delivered. Dealers must check their inventory vehicles' VINs on the Warranty Super Screen to verify whether the vehicle is involved in this recall campaign. It is a violation of Federal law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by the notification under a sale or lease until the defect or noncompliance is remedied.

Training News

Technical Training Schedule January - February, 2015

Always check the MDL for schedule updates. Mobile Training does not appear on these calendars. Contact your District Parts & Service Manager for information about mobile training in your area.

East Zone - N.J. Tech Training Center								Ea	East Zone - Atlanta					Tech Training Center					
	Ja	nua	ry			Fe	ebru	ary			Ja	anua	ary			F	ebru	ary	
M	т	W	Th	F	M	т	w	Th	F	M	т	w	Th	F	M	т	w	Th	F
29 H	ЭО	Н	н	2	26	27	28 EN1	29	30 SP3	29 H	ЭО	" H	н	2	26	27	28	29	30
5	6	7	8.	9	2	3	4	5	6	6	6	7	8	9	2	3	4	5	6
	MI	EVTT				MED2	STV3		ES3		MFIT2		\vdash		AT2 A		AT3		
12	13	14	15	16	9	10	11	12	13	12	13	14	15	16	9	10	11	12	13
																	ES3	ME	VTT
19	20	21	22	23	16	17	18	19	20	19	20	-21	22	23	16	17	18	19	20
Н			AED	\vdash	H		E	S3		н			С	VTT	Н			AED	=
26	27	28	29	30	23	24	25	26	27	26	27	28	29	30	23	24	25	26	27

TC-SST

West Zone-Dallas Tech Training Center

California Technical Training Center

	Ja	anua	ary			Fe	ebru	ary			J	anua	ary			F	ebru	ary	
M	T	w	Th	F	M	T	w	Th	F	M	т	w	Th	F	M	т	w	Th	F
29	30	31	1	2	26	27	28	29	30	29	30	31	1	2	26	27	28	29	30
Н	Н	Н	Н				VTT	ME	VTT	Н	H	Н	H						
6	6	7	0	9	2	3	4	5	6	6	6	7	8	9	2	3	4	5	6
											ES3 TC-SS		SST	AED		SP3			
12	13	14	15	16	9	10	11	12	13	12	13	14	15	16	9	10	11	12	13
MED2	STV3		ES2				м	FIT2	_				1		ll .				1
		AT2		AT3		1	1	1	1 -						Ш				
19	20	21	22	23	16	17	18	19	20	19	20	21	22	23	16	17	18	19	20
Н			MTT	\vdash	Н			EN1		Н				1.270	Н				
26	27	28	29	30	23	24	25	26	27	26	27	28	29	30	23	24	26	26	27
	C	VTT	ME	EVTT		TO	C-SST	ME	VTT										

	Days	Code	Prerequisites		Days	Code	Prerequisites
Automatic Transaxles				Manual Transaxles			
40/50 Series Diagnosis & Repair	3	AT2T	ATFT1 or ATFWE or ATFB	Manual Transaxies & Transfer Cases	3	MTT	No Prerequisites
50 Series 5-speed Diagnosis & Repair	1	AT3	AT2T	Twin Clutch Sportronic Shift Transmission	2	TC-SST	AESP, ES1, ES2, STV3,
CVT Diagnosis &Repair	2	CVTT	ATFT1 or ATFWE or ATFB				MED2, MED3, ATFWE, MTT
Brakes				Vehicle Specific			
Antilock Brakes	2	ABS2	ES1	Eclipse Spyder Convertible Top (Top Stack)	1	SP3	No Prerequisites
Electrical Systems			3	2014 Outlander Technology	1	141	ES1, MED2, MED3, STV3
Electrical Systems 2	3	ES2	ES1	Mitsubishi Electric Vehicle Technician Training	2	MEVTT	AESP, ES1, ES2, STV3,
Electrical Systems 3	2	ES3	ES1				MED2, MED3, 120
Engine Performance							
Advanced Emission Diagnosis	3	AED	ES1, STV3, MFIT2	Vehicle Diagnostics			
Engine Technology & Diagnosis	3	EN1	No Prerequisites	Advanced Electronic Service Procedures	S 3	AESP	No Prerequisites
Multiport Fuel Injection	4	MFIT2	ES1, STV3	Advanced Safety & Convenience Features	1	ASCF	ES1, MED2, MED3, STV3
Heating & A/C Systems			· ·	MEDIC II	. 1	MED2	No Prerequisites
Climate Control	2	CC1	MACW, ES1, MED2, MED3, STV3	Scan Tool Viewer (MUT-III)	1	STV3	No Prerequisites

NEWS:

2016 Diamond Pro Certification: With the start of the new year, it's time to think of advancing to the next level of training. MMNA will introduce new and updated training classes later in the year (an updated Manual Trans course is due during the first quarter) and those classes will be required for your 2016 certification. Think about getting scheduled early so you're not scrambling towards the end of the year after others are introduced.

TECHLINE

(800) 446-6064



HOURS:

Monday - Friday

6:30 - 11:30 am & 12:30 - 3:30 pm All times are Pacific Time

NOTE: Techline is closed every THURSDAY from 9:30 – 10:30 A.M (Pacific) for a staff meeting.

TECHLINE WILL BE CLOSED Monday, January 19, 2015 in observance of Martin Luther King Day

MEDIC Information

MEDIC Hotline (800) 846-7575

Call the MEDIC Hotline for <u>ALL MEDIC & Scan Tool hardware or software issues.</u> Call TECHLINE for vehicle technical issues. As of 12/17/14: Total Hits - 6386 Reflash Database: N14081 MEDIC 3 Version - 3.2 MEDIC 3 Update - 306 MUT-III Version - 31.01 Raider Scan Tool Version - 6.0

77

Bulletin Review

The following information was recently released:

Number	Title	Vehicles	Subject
SR-14-012	Lancer Front Air Bag Inflator – Safety Recall Campaign	2004-05 Lancer	Instructs dealers to remove the front passenger's airbag and replace the inflator.
TSB-14-00-019	2015 Lancer Evolution Service Manual Information – SMR	2015 Lancer Evolution	Use this TSB in combination with the 2014 Lancer Evolution service manual for complete service information for 2015 models.
TSB-14-00-020	Updated Coding List - SMR	2012–13 Lancer Evolution	Updates the "Service reminder schedule table" in the Variant Coding list
TSB-14-16-001REV	Squeak Noise from Engine Accessory Drive Belt- REVISED	2012-14 Lancer, Lancer Sportback, Outlander Sport, Outlander (4 cyl.)	Provides a field fix for a noise caused by the drive belt and alternator pulley.
TSB-14-37-006	Key Interlock Naming Corrected - SMR	2014-15 Mirage, Outlander, 2011-15 Outlander Sport	Changes mention of "steering lock" to "shift interlock."
TSB-14-42B-004	Updated Foaming Materials Locations – BRM Revision	2013–15 Outlander Sport	New insulation foaming locations added to the body repair manual
TSB-14-54-014	Service Reminder Menu Set Procedure	2012–15 Lancer Evolution	Updates the service reminder set procedure Schedule Table in the service manual.



© 2015 Mitsubishi Motors North America, Inc.

The information contained in this bulletin is subject to change. For the latest version of this document, go to the Mitsubishi Dealer Link, MEDIC, or the Mitsubishi Service Information website (www.mitsubishitechinfo.com)