
Reference	SSM72257
Models	Range Rover / L405
	Range Rover Sport / L494
Title	Differential Axle Tube Assembly Leak/Noise
Category	Driveline
Last modified	23-Apr-2015 00:00:00
Symptom	509000 Axle Concerns
Attachments	Front Axle Serial Number Points.pdf
	Half shaft information.pdf
	Needle Roller Bearing.pdf
Content	lssue:
	1) Oil leaking from the front differential axle tube assembly.
	2) Noise evident from the front axle tube assembly.
	<u>Cause:</u>
	Currently under investigation.
	Action:
	If oil leaking is the issue found, please remove the axle tube assembly and confirm if the needle roller bearing is present, please refer to
	the attached file named needle roller bearing.
	If a noise concern is evident please take a clear photo inside the axle tube prior to removal and replacement and raise a Quality Report
	EPQR. A photo of the label and bearing journal on the half shaft is also requested, refer to attached file named half shaft information for
	examples showing detail required.
	Please retain the old axle tube assembly so that it can be returned to the supplier via PRR.
	When raising the Quality Report EPQR please make sure the serial number of the front differential is always quoted. Please refer to
	attached file named Front Axle Serial Number Points which details locations of the serial number.
	Part number of the axle tube assembly - LR052323
	Technicians - Please rate this SSM and provide comments so that future communications can be improved.
	1 Book Book information provided. The SSM does not help me reaching the supremer concern
	1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.

3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.

5 = Excellent – All required information provided to resolve the customer concern.

Front Axle Serial Number



Half shaft information required



Picture of this bearing journal

