



Service Bulletin

PRELIMINARY INFORMATION

Subject: No XM Audio or Time Shift, Radio Lock-Up, Slow Response, Vertical Line Between Clock and Temperature, Poor FM Reception (Truck Only)

Models: 2015 Buick LaCrosse, Regal
 2015 Cadillac ATS, CTS Sedan (VIN A), ELR, Escalade Models, SRX, XTS
 2015 Chevrolet Colorado, Corvette, Impala (VIN 1), Silverado 1500, Silverado 2500/3500 (RPO AVF), Suburban, Tahoe
 2015 GMC Canyon, Sierra 1500, Sierra 2500/3500 (RPO AVF), Yukon Models
 Equipped with RPOs IO3, IO4, IO5, IO6

This PI has been revised to update the Recommendations/Instructions. Please discard PI1374A.

Condition/Concern

Some customers may comment on the following concerns:

Condition	RPO			
	IO3	IO4	IO5	IO6
Slow response tuning to different XM stations	x			
Poor radio reception (Truck Only)	x	x	x	x
Time shift rewind/pause button highlighted but it does not function	x	x	x	x
Radio locking up when Clock Screen mode is activated	x	x	x	x
If audio source is changed right before turning ignition off, the next ignition cycle may not have any audio	x	x	x	x
Removal of vertical line between Clock and Temp	x			
No XM audio. Ignition cycle returns audio	x	x	x	x

Recommendation/Instructions

Note: IO3 radios may take 2 + hours to complete programming. Due to the length in programming, a wired internet connection is preferred.

Important: When programming IO3 radios, measures must be taken to NOT let the tech's TIS2WEB computer go to sleep during programming.

An updated software calibration has been released to address the above conditions. Update/reprogram the radio using the Service Programming System (SPS) with the latest calibrations available on TIS2WEB. Refer to the SPS procedures in SI.

Clear any DTCs.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
2810335	Radio Reprogramming with SPS	Use Published Labor Operation Time
2880278*	Radio Reprogramming with SPS (IO3 Radios ONLY)	1.0 hr

*This is a unique Labor Operation for Bulletin use only. It will not be published in the Labor Time Guide.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION