

Bulletin No.: PI1462

Date: Apr-2015

PRELIMINARY INFORMATION

Subject: Crank No Start After Hot Soak

Models: 2008-2012 Chevrolet Malibu

2006-2010 Pontiac G6 2007-2010 Saturn Aura

Attention: This PI also applies to any of the above models that may be Israel Export vehicles.

Condition/Concern

In rare cases, some customers may comment that their vehicle will crank but not start. The customer may indicate that the vehicle was driven, then after sitting for a short time the condition occurred. The customer may also indicate that after the vehicle is sitting for longer periods of time, it will crank and start normally.

This condition may be caused by reduced terminal tension, causing an increase in resistance through the terminal in the body side harness connector to the rear fuse block (Rear X1 Pin A10) fuel pump relay circuit supplying B+ to the fuel pump on circuit 120.

Recommendation/Instructions

Replace the rear fuse block assembly and terminal for circuit 120 in the Rear X1 Pin A10 with a terminating lead.

Important: It is recommended to use the entire length of wire from terminating lead to replace as much of circuit 120 as possible.

Parts Information

For rear fuse block part numbers, refer to group 02.483 or 13.100 of the appropriate Parts Catalog.

Part Number	Description
13575721	WIRE ASM-SPLICE

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
5430420	Rear Body Fuse Block Replacement	Use Published Labor Operation Time

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.

