



# Service Bulletin

## PRELIMINARY INFORMATION

**Subject:** Engineering Information – No Forward or Reverse, Transmission Slips or Low Line Pressure

**Models:** 2015 Chevrolet Silverado 2500/3500  
2015 GMC Sierra 2500/3500  
Equipped with RPO LML and MW7

**Attention:** Proceed with this EI ONLY if the customer has commented about this concern AND the PIE number is listed in the Global Warranty Management / Investigate History link (GWM/IVH). If the customer has not commented about this condition or the EI does not show in GWM/IVH, disregard the PI and proceed with diagnostics found in published service information. THIS IS NOT A RECALL — refer to the latest version of Service Bulletin 04-00-89-053 for more details on the use of Engineering Information bulletins.

### Condition

**Important:** If the customer did not bring their vehicle in for this concern, DO NOT proceed with this EI.

Some customers may comment that the vehicle will not move forward/reverse or that the transmission slips.

### Cause

GM Engineering is attempting to determine the root cause of the above condition. Engineering has a need to gather information on vehicles PRIOR to repair that may exhibit this condition. As a result, this information will be used to "root cause" the customer's concern and develop/validate a field fix.

### Instructions

If you encounter a vehicle with the above concern, follow the procedure below.

1. Check the transmission line pressure. Refer to Line Pressure Check in SI.
2. If the line pressure is low, contact the engineer below.

### Contact Information

Engineer Name	Phone Number
Kyle Leppek	317-448-6383

Please include the following information if leaving a message:

- Technician name
- Dealer name and phone number
- Complete VIN and repair order (R.O) number

On the repair order, document the date and time the call was placed (even if the engineer was not reached).

If engineering is unable to return the call within one hour, proceed with diagnosis and repair based on information found in SI.

### Warranty Information

If engineer was contacted or required information was provided, use:

Labor Operation	Description	Labor Time
8480258*	Engineering Information – Check Transmission Line Pressure	0.6 hr
*This is a unique Labor Operation for Bulletin use only. It will not be published in the Labor Time Guide.		

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION