

Date: Apr-2015

GM CONTROLLED

Service Bulletin

PRELIMINARY INFORMATION

Subject: Whistle Wind Noise From Drivers Side Mirror Area

Models: 2012 - 2015 Chevrolet Equinox

2012 - 2015 GMC Terrain

This PI was superseded to update Model Years and Warranty Information. Please discard PIT5199A.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

Customer may comment on a high pitched whistle or wind noise from the driver's side mirror area between speeds 25 to 52 mph. This may be caused by a gap between the belt molding and the bottom of mirror mounting patch. This may be caused by a void in the sealing area in the corner of the belt molding and the door glass frame at the front toward the A pillar. See picture below.



Recommendation/Instructions

Suggest using a rubber mallet and lightly tapping on the belt molding - moving it toward the A pillar area. This will close the gap slightly (measure the gap between the end of the belt molding and the window a-pillar).

Next, remove the belt molding, use a suitable piece of rubber (weather strip or suitable material), and glue it to the back side of the of the belt molding to extend to fill the gap.

Reinstall the belt molding. This will fill the remaining void in the seal. Use a piece of tape to keep it in place until the glue dries





Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
* 2080498	Wind Whistle Door Mirror Repair	0.3hr
* This is a unique labor operation for bulletin use only. This will not be published in the Labor Time Guide.		

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safety. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.

