



Service Bulletin

PRELIMINARY INFORMATION

Subject: XM Weather Tab Highlights But Does Not Enter

Models: 2014-2015 Buick LaCrosse, Regal
 2013-2015 Cadillac ATS, SRX, XTS
 2014-2015 Cadillac ELR, CTS Sedan VIN A
 2014-2015 Chevrolet Corvette, Impala VIN 1, Silverado 1500
 2014 GMC Sierra 1500
 2015 Cadillac Escalade models
 2015 Chevrolet Colorado, Silverado, Suburban, Tahoe
 2015 GMC Canyon, Sierra, Yukon models
 Equipped with IO5, IO6, or UY4 Radio

Condition/Concern

A customer may comment that they are unable to access XM Weather. During diagnosis, a technician may notice that the icon highlights, but they are unable to access the XM Weather application.

Recommendation/Instructions

If the system responds by highlighting the XM Weather Icon but does not enter the application, replace the HMI.

Parts Information

To obtain the appropriate HMI module part number, refer to Group 09.680 of the electronic parts catalog.

Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
3421060	Human Machine Interface Control Module Replacement	Use Published Labor Operation Time

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION