



Service Bulletin

PRELIMINARY INFORMATION

Subject: Possible Blank Radio Display And/Or DTC U150F Stored in the Radio/HVAC Controls

Models: 2014-2015 Buick LaCrosse, Regal
2013-2015 Cadillac ATS, SRX, XTS
2014-2015 Cadillac CTS (A body), ELR
2015 Cadillac Escalade, ESV
2014-2015 Chevrolet Corvette, Impala
2014 Chevrolet Silverado 1500
2014 GMC Sierra 1500
2015 Chevrolet Colorado, Suburban, Tahoe, Silverado
2015 GMC Canyon, Sierra, Yukon

This PI was superseded to update Models Please discard PIT5231B.

Condition/Concern

Some customers may complain of a blank radio display and/or a technician may notice DTC U150F stored in the radio/HVAC controls.

Recommendation/Instructions

Please ignore this DTC if it is stored in history with no symptoms reported.

Please verify that the correct display is installed in the vehicle prior to performing any diagnostics. If the DTC is set current, check LIN Bus 5 (circuit 7527) between the Info Display Module and Human Machine Interface (HMI) module for an open, short to ground, short to power, or poor terminal tension.

Warranty Information

For wiring repairs covered under warranty, please refer to latest version of bulletin 10-00-89-005 for warranty information on wire/connector repairs.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION