

Service Bulletin

PRELIMINARY INFORMATION

Subject: **Diagnostic Tip - Adaptive Cruise Temporarily Unavailable**

Models: 2013 - 2016 Cadillac XTS, SRX With RPO PCX

2013 - 2016 Cadillac ATS With RPO Y66

2014 - 2016 Cadillac CTS Sedan (VIN A) With RPO Y66

This PI was superseded to update Model Years. Please discard PIC6013A.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

A customer may comment they receive an "ADAPTIVE CRUISE TEMPORARILY UNAVAILABLE" message on the DIC when attempting to activate the cruise

Recommendation/Instructions

If normal diagnostics lead to a concern that can be duplicated and there are no Diagnostic Trouble Code's, the concern is most commonly caused by one of the following issues.

1. Please perform the yaw rate sensor learn procedure (Multi Axis Sensor), clear any dtc's that may have been set during programming, and let vehicle go to sleep before evaluating the concern.

Note: The majority of the vehicles will be resolved by performing the Multi Axis Sensor learn. If the concern has not been resolved, follow the next step:

2. Please perform the Long Range Radar learn by following the Radar Sensor Module - Long Range Programming and Setup procedure in Service Information.

Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
2880288*	Relearn Multi Axis Sensor (YAW Sensor)	0.3 hr
Add	Relearn Long Range Radar	0.5 hr
* This is a unique labor operation for bulletin use only. This number will not be published in the Labor Time Guide		

ation for bulletin use only. This number will not be published in the Labor Time (

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.

