



Bulletin No.: PIT5484

Date: Dec-2015

# Service Bulletin

## PRELIMINARY INFORMATION

**Subject:** 118 Error When Attempting to Configure OnStar After 15-08-44-001 Upgrade

**Models:** 2005-2009 Buick Allure  
2004 Buick Century  
2005-2009 Buick LaCrosse  
2000-2005 Buick LeSabre  
2004-2007 Buick Rainier  
2004 Buick Regal  
2003-2007 Buick Rendezvous  
2005-2007 Buick Terraza  
2003-2007 Cadillac CTS  
2002-2005 Cadillac Deville  
2003-2006 Cadillac Escalade  
2002-2004 Cadillac Seville  
2004-2006 Cadillac SRX  
2004-2011 Cadillac STS  
2004-2009 Cadillac XLR  
2003-2006 Chevrolet Avalanche  
2005-2010 Chevrolet Cobalt  
2004-2012 Chevrolet Colorado  
2005-2013 Chevrolet Corvette  
2005-2006 Chevrolet Equinox  
2004-2005 Chevrolet Express  
2006-2011 Chevrolet HHR  
2001-2005 Chevrolet Impala  
2004-2012 Chevrolet Malibu  
2002-2005 Chevrolet Monte Carlo  
2003-2007 Chevrolet Silverado  
2003-2006 Chevrolet Suburban  
2003-2006 Chevrolet Tahoe  
2009-2009 Chevrolet TrailBlazer  
2005-2009 Chevrolet Uplander  
2003-2005 Chevrolet Venture  
2004-2012 GMC Caynon  
2002-2009 GMC Envoy  
2003-2005 GMC Savana  
2003-2007 GMC Sierra  
2003-2006 GMC Yukon/Yukon XL  
2003-2007 Hummer H2  
2006-2011 Hummer H3  
2001-2003 Oldsmobile Aurora  
2002-2004 Oldsmobile Bravada  
2003-2004 Oldsmobile Silhouette

**2003-2004 Oldsmobile Silhouette**  
**2003-2005 Pontiac Aztek**  
**2000-2005 Pontiac Bonneville**  
**2007-2010 Pontiac G5**  
**2005-2010 Pontiac G6**  
**2004-2008 Pontiac Grand Prix**  
**2003-2009 Pontiac Montana**  
**2005-2006 Pontiac Pursuit**  
**2006-2010 Pontiac Solstice**  
**2004-2005 Pontiac Sunfire**  
**2006 Pontiac Torrent**  
**2005-2008 Pontiac Vibe**  
**2008-2009 Saturn Astra**  
**2007-2010 Saturn Aura**  
**2004-2007 Saturn ION**  
**2003-2004 Saturn L-Series**  
**2005-2007 Saturn Relay**  
**2007-2010 Saturn Sky**  
**2003-2007 Saturn Vue**

## Condition/Concern

Dealers may report that OnStar is unable to configure the vehicle after the OnStar 15-08-44-001 upgrade. OnStar receives a 118 error when attempting to configure the vehicle. Dealers should receive a sheet with the kit that provides steps to assist with handling this error.

### **Important:** Additional Set-up Instructions

During the blue button call, the OnStar advisor may tell you that the vehicle cannot be configured. This occurs because the new module is not connecting to the preferred network.

If this occurs, please follow these steps:

1. After talking to OnStar through the blue button, leave the vehicle powered up for 10 minutes for the cellular network to update.
2. Turn off the vehicle.
3. Cancel RAP (open the driver door).
4. Disconnect the vehicle battery.
5. Wait for 5 minutes.
6. Reconnect the vehicle battery.
7. Press the blue button again to contact an advisor and attempt another configuration.
8. Verify that the configuration was successful.

If there are still configuration issues, please contact the OnStar Technical Assistance Centre for assistance.

## Recommendation/Instructions

If the concern is still present after performing the steps provided, it may be necessary to drive the vehicle into a metro area and retest. If the vehicle is already in a metro area and exhibits this concern, it may be necessary to drive the vehicle 2 Kilometers in each direction of the dealer to allow the OnStar system to connect to a tower.

---

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION