



Countries: CANADA, TAIWAN, UNITED STATES, MEXICO, PUERTO RICO, GUAM, KOREA, SOUTH KOREA
Availability: ISIS
Major System: ENGINES
Current Language: English
Other Languages: NONE
Viewed: 5422

Document ID: IK1201222
Revision: 4
Created: 10/8/2014
Last Modified: 5/1/2015
Author: Aaron Mimbs

[Less Info](#)
☒ Hide Details

Coding Information

Copy Link 	Copy Relative Link 	Bookmark View My Bookmarks	Add to Favorites 	Print 	Provide Feedback 	Helpful 30	Not Helpful 6
----------------------	-------------------------------	--	-----------------------------	------------------	-----------------------------	--------------------------	-----------------------------

Title: MaxxForce 7 Misfire Diagnostics

Applies To: All MaxxForce 7

CHANGE LOG

2015/05/01 - Added keywords to article
 2015/04/22 - Added keywords to article
 2015/04/06 - Updated CPA launching instructions, added EPA13 IPA monitor warning
 2015/01/28 - Added 2007-2009 MaxxForce 7 Part Numbers
 2015/01/20 - Clarified step 10 decision

DESCRIPTION

Due to the lack of misfire diagnostics in the Manual, this document will guide the user through misfire diagnostics on the MaxxForce 7.

SYMPTOMS

Diagnostic Trouble Codes:

DTC/Light	Description
NONE	

Customer Observations or Concerns:

- Engine Idles Rough
- Popping through Intake
- Oil Above FULL
- Distinct Engine "Thuds" Corresponding with Engine Speed

SPECIAL TOOL(s) / SOFTWARE

Tool Description	Tool Number	Comments	Instructions
Cylinder Performance Analyzer	12-999-01		
ServiceMaxx			
Clean Fuel Source	15-637-01		
Engine Blow-by Orifice Tool	ZTSE4146A		
Oil Fill Tube Orifice Adapter	ZTSE4284		
Pressure Test Kit or Slack Tube Manometer	ZTSE4409 or ZTSE2217A		
Standard Plug	Obtained Locally		
Fuel Injector Electrical Connector Release Tool	ZTSE4820		
Kit, Fuel System Cap	ZTSE4710		
Plugs, High Pressure Pump-Rail	ZTSE4861		
Flex Hone	ZTSE4349		

[Tools Resource Center](#)

SERVICE PARTS INFORMATION

Kit Description	Part Number	Quantity Required	Notes
FUEL, DIESEL FUEL INJECTOR CLEANER	7080427C1	1 Bottle	Tank additive for fuel injector cleaning

2007 - 2009 MaxxForce 7

Kit Description	Part Number	Quantity Required	Notes
INJECTOR ASM, FUEL	1875072C91	As Required	Includes Tube Assembly
LEVER, BRIDGE VALVE ARM	1854009C1	As Required	Rocker Arm
TUBE ASSY FUEL RAIL TO INJECTOR	1886547C1	As Required	Injector to Rail Jumper Tube
CAM ASM, FOLLOWER & GUIDE	1835139C92	As Required	Lifter and Lifter Guide
ROD ASM, PUSH	1837730C2	As Required	Push Tube
PISTON ASSEMBLY	1874918C91	As Required	Complete Piston Assembly
MOUNTING KIT TURBOCHARGER	1876540C92	As Required	Turbo Seals & Oil Supply Tube

2010 - 2013 MaxxForce 7

Kit Description	Part Number	Quantity Required	Notes
KIT INJECTOR	1899239C92	As Required	Includes Tube Assembly
PLATE ASSEMBLY DUAL FULCRUM	1880498C91	As Required	Rocker Arm Assembly (Exh & Int)
TUBE ASSY FUEL RAIL TO INJECTOR	1886547C1	As Required	Injector to Rail Jumper Tube
CAM ASM, FOLLOWER & GUIDE	1835139C93	As Required	Lifter and Lifter Guide
ROD ASM, PUSH	1873916C2	As Required	Push Tube
PISTON ASSEMBLY	1883516C91	As Required	Complete Piston Assembly
KIT, TURBO MOUNTING	1897455C93	As Required	Turbo Seals & Oil Supply Tube

DIAGNOSTIC STEPS

Step	Action	Decision
1	DIAGNOSTIC: Generate Health Report Are there any PENDING/ACTIVE DTCs not related to an engine misfire?	Yes. Follow the FCAP as outlined. If no FCAP is available perform an iKNow search for documents relevant to the issue. If no articles can be found see the proper Diagnostic Manual. Step 2
	Note: On EPA13 MaxxForce 7's SPN 651-658 are Injector Timing Faults which can be false, generated due to excessive parasitic loading on the engine. The false codes have been corrected in Calibration PRS24LR2 and later.	No. Step 2

Step	Action	Decision
2	DIAGNOSTIC: Is the ECM Calibration Up-to-Date?	Yes. Step 4
		No. Update calibration. EPA13 MF7 Step 3 EPA10 MF7 Step 4

Step	Action	Decision
3	CALIBRATION EFFECTIVENESS: On EPA13 OBD engines, perform the following with calibration PRS24LR2. 1. Clear any faults 2. Start the engine 3. Allow the engine to idle for 2 minutes in NEUTRAL 4. Shut down the engine 5. Make note of any faults that became PENDING or ACTIVE 6. Clear any faults that may have come PENDING or ACTIVE 7. Turn on the excessories (Air conditioning, lights, booster pumps, ect.) 8. Start the engine and put it in DRIVE 9. Allow the engine to idle for two minutes in DRIVE	Yes. Step 4
	Did the injector timing faults return?	No. Release to the customer

Step	Action	Decision
4	DIAGNOSTIC:	Yes. Correct Issue; Step 5

	Perform Visual Checks Per the Diagnostic Manual and/or Performance Diagnostic Sheet.	No. Step 5
	Any issues noted?	

Step	Action	Decision
5	DIAGNOSTIC: In ServiceMaxx go to <i>Procedures >> KOEO Procedures >> Fuel Pressure Adaptation Reset</i> and follow the on screen commands. Does the engine still misfire?	Yes. Step 6
		No. Complete any other work needed and release unit to customer. If this is a problematic unit continue with Step 6

Step	Action	Decision
6	DIAGNOSTIC: ONLY using ZTSE4146A (Orifice size 0.406") Perform Crankcase Pressure and Blow-By Tests. If it is determined unsafe to do so, please skip and continue to Step 7. 2007 - 2009 MaxxForce 7 Measure Crankcase Pressure (9" H2O) per the Diagnostic Manual or IK1200881 2010 - 2013 MaxxForce 7 Measure Crankcase Pressure (Spec 24" H2O) and Blow-by (9" H2O) per the Diagnostic Manual. NOTE: If Blow-by is in specification and Crankcase Pressure is beyond specification, verify the crankcase breather is a non-serviceable certified breather. Please See 121203 New Non-Serviceable Crankcase Breather - EPA 10 MaxxForce® 7. If required, replace the Crankcase Breather and reevaluate readings. Are the readings within specification?	Yes. Step 7
		No. Potential Base Engine Issue. Perform Step 7 & Step 8 and then open a case file with Navistar's Technical Support group with all relevant information, pictures, parameter file and recordings for further assistance.

Step	Action	Decision
7	DIAGNOSTIC: See Section Cylinder Performance Analyzer Diagnostics for Engine Misfires below. Did the CPA tool flag a cylinder misfiring at idle?	Yes. Step 8
		No. Step 8

Step	Action	Decision
8	DIAGNOSTIC: Relative Compression Test Note: 2007 - 2009 MaxxForce 7 the RCT may not be accurate or has an inability to document cylinder compression. If this is the case then perform a manual compression test on the suspected bank ONLY (Both if Required). General Specification Rule - If Cylinders are within 40 psi of each other after FOUR revolutions, compression is not an issue. In ServiceMaxx under "Tests", "KOEO Tests", perform the "Relative Compression Test". Specification: All cylinders are within 7 RPM of each other.	1. CPA Flagged no Misfires and RCT (or MCT) is within specification; Step 9
		2. CPA Flagged a Misfire and RCT (or MCT) is within specification; Step 10
		3. CPA Flagged a Misfire and RCT (or MCT) is out of specification; Step 10

Step	Action	Decision
9	DIAGNOSTIC: Engine misfire is not present. Re-evaluate engine condition, operation, and "misfire" operating conditions. Other Possibilities: 1. Engine "misfire" at elevated RPMs 2. Engine surging due to other condition (EGR, ITV, FRP, Low Side Fuel Pressure, Aftertreatment, Elevated Oil Level, etc.)	Yes. See the Fuel System Cleaning section below.
		No. Complete any other work needed and release unit to customer.

	After reevaluation does the engine still qualify for misfire diagnostics?	
--	---	--

Step	Action	Decision
10	DIAGNOSTIC: Remove the valve cover and injector. Inspect the injector tip, rocker arms, and push tubes. Are any components damaged or worn? NOTE: If the injector tip is heavily damaged the cylinder/piston may exhibit unrepairable damage, if this is the case do not replace components at this time and proceed to Step 12	Yes. Replace components and reassemble the engine. Reset the fuel pressure adaptives; Step 11
		No. Replace injector reassemble engine. Reset the fuel pressure adaptives; Step 11

Step	Action	Decision
11	DIAGNOSTIC: Does the engine still misfire?	Yes. Return to Step 7 , if the CPA tool flags the same cylinder, Step 12
		No. Repair complete, release truck

Step	Action	Decision
12	DIAGNOSTIC: Remove the engine oil pan and inspect for debris and damage to the base engine Lifters, Cam, Cylinder Walls, Crankshaft, or Pistons/Rods? Were any issue noted?	Yes. Step 13
		No. Step 14

Step	Action	Decision
13	DIAGNOSTIC: Does the engine fall under any of the following conditions? 1. Severe Camshaft Lobe Damage 2. Severe Cylinder Wall Damage 3. Severe Crankshaft Damage 4. Severe Crankcase Damage	Yes. Open a case file with Navistar's Technical Support group with all relevant information, pictures, parameter file and recordings for further assistance.
		No. If related and can be corrected proceed with repairs, if not Step 14

Step	Action	Decision
14	DIAGNOSTIC: Remove the cylinder head per the Engine Service Manual and Perform Base Engine Inspections. Were any Issues Noted?	Yes. Step 15
		No. Step 16

Step	Action	Decision
15	DIAGNOSTIC: Does the engine fall under any of the following conditions? 1. Severe Camshaft Lobe Damage 2. Severe Cylinder Wall Damage 3. Severe Crankshaft Damage 4. Sever Crankcase Damage	Yes. Open a case file with Navistar's Technical Support group with all relevant information, pictures, parameter file and recordings for further assistance.
		No. If related and can be corrected proceed with repairs, Step 16

Step	Action	Decision
17	DIAGNOSTIC: Remove the piston assembly and inspect. Are any issues noted?	Yes. If non-condemning replace/repair components per the Engine Service Manual reassemble the engine. If the issue has not been resolved by this time open a case file with Navistar's Technical Support group with all relevant

	information, pictures, parameter file and recordings for further assistance.
	No. Open a case file with Navistar's Technical Support group with all relevant information, pictures, parameter file and recordings for further assistance.

CYLINDER PERFORMANCE ANALYZER DIAGNOSTICS FOR ENGINE MISFIRES


NOTE: ON THE MAXXFORCE 7 THE CPA TOOL IS VERY ACCURATE IN FLAGGING ENGINE MISFIRES AT IDLE ONLY. ELEVATED ENGINE SPEEDS BRINGS HIGHER TORSIONAL VIBRATIONS WHICH CAN AND WILL IMPROPERLY FLAG CYLINDERS FOR A MISFIRE. THE SAME APPLIES FOR UNDER A LOAD AND DRIVING.

Connecting the CPA Tool

The Camshaft Position Sensor and Crankshaft Position Sensor connectors are reversed, in comparison to the DT, 9 and 10. On the CPA box, the BNC cables need to be connected such that the correct sensor is feeding the correct port (Crank to Crank, Cam to Cam)--the crankshaft position sensor is located on the right (passenger) side of the engine towards the front just above the oil pan and the camshaft position sensor is located on the left (drivers) side of the engine.

If needed see the following iKNow article for further CPA instructions [IK1200812 - Diagnosing Cylinder Performance Related Symptoms Using the CPA Tool](#)

CPA Software Preparation



NAVISTAR

Base Engine Class	✓
Engine Type	V6
Software Identification	V8
Engine Family Rating Code	B8 11
VIN	B8 15
Engine Serial Number	V6
Transmission Type	
Rated Horsepower	
Total Miles	
Total Fuel Used	
Total Engine Hours	

Select "V8"

Figure 1: Cylinder Performance Analyzer Information Table

Item 1: Base Engine Class V8

1. After connecting the CPA tool to the truck and laptop, launch the Engine Cylinder Performance Analyzer software from ServiceMaxx. Make sure the base engine class is selected as V8 before continuing see **Figure 1**.

--




Figure 2: Cylinder Performance Analyzer Information Table

Item 1: Base Engine Class V8

2. If done properly, the engine misfire display figure shows an 8 cylinder engine shown in Figure 2.




Figure 3: Cylinder Performance Analyzer MisFire Indicator

Attention

The EPA13 MaxxForce 7 has a monitor called the Injector Performance Analyzer, this monitor runs after every key cycle during the first two minutes of idling time. Before analyzing performance with the CPA tool allow the engine to idle for two minutes for the monitor to complete its analysis and return the engine to a normal idling pattern.

3. With the CPA tool, perform the standard "Signal Check." After passing the signal check, begin recording the engine data during the time of the misfire complaint (Cold Idle or Hot Idle). The same standard misfire display follows the same rules as the DT, 9 and 10 Engines and can be seen in Figure 3.

Return to [Step 7](#)

REPAIR STEPS

Fuel System Cleansing

1. Warm the engine to operating temperature
2. Connect the clean fuel source 15-637-01
3. Add 1/2 bottle Fuel System Cleaner to the clean fuel source and mix thoroughly with a full container
4. Run the engine high idle until nearly all the fuel has been used up (Do not run it dry and air bound the system)
5. If the truck has atleast a 1/2 tank of fuel add the remaining cleanser to the tank. If not give the customer the bottle to add before the next fill up

WARRANTY INFORMATION

Warranty Claim Coding:

Group:	12000 - Engines
Noun:	313 - Carrier Assembly, Rocker Arm
	404 - Lifter, Valve
	416 - Rods, Push
	563 - Injector Unit (Electrical)
	137 - Piston, Pin, Lock, Bushing
	192 - Sleeve Cylinder
	051 - Crankcase

[Warranty Coding Manual](#)

Standard Repair Times:

Due to extensive SRT options and requirements for the repair plans, see the Standard Repair Time Manual for specific engine/vehicle combinations.

[Standard Repair Time Manual](#)

STEP	DESCRIPTION	MANUAL SECTION
Step 1	ECM Calibration	ELECTRONIC CONTROL MODULE (ECM OR ECM/IDM) - ENGINE PROGRAM
Step 2	Visual Inspection	ELECTRONIC ENGINE PERFORMANCE, DIAGNOSE
Step 3 & 4	Check for DTCs & Reset Adaptives	ELECTRONIC ENGINE PERFORMANCE, DIAGNOSE
Step 6	Crankcase Pressure Test	ELECTRONIC ENGINE PERFORMANCE, DIAGNOSE
	Blow-by Test (EPA 2010)	ELECTRONIC ENGINE PERFORMANCE, DIAGNOSE
	Crankcase Breather Replacement EPA (2010)	CRANKCASE BREATHER HOUSING ASSEMBLY, REPLACE
Step 7	Cylinder Performance Analyzer	T-Time (0.7 Hours) CYLINDER PERFORMANCE ANALYZER (CPA) TOOL, DIAGNOSIS
Step 8	Relative Compression Test (EPA 2010)	ELECTRONIC ENGINE PERFORMANCE, DIAGNOSE
	Manual Compression Test (EPA 2007)	ELECTRONIC ENGINE PERFORMANCE, DIAGNOSE
Step 10	Rocker Arm Replacement	ROCKER ARM, PUSH RODS AND/OR VALVE BRIDGES (V-ENGINES), REPLACE
	Injector Replacement	FUEL INJECTOR(S) (ELECTRONIC ENGINES), REPLACE
Step 12	Oil Pan R&R	OIL PAN AND/OR GASKET, REPLACE
Step 14	Cylinder Head Removal (EPA 2007)	CYLINDER HEAD GASKET (V-ENGINES), REPLACE
	Cylinder Head Removal (EPA 2010)	CYLINDER HEAD OR REPLACE GASKET (V ENGINES), R&R AND OR REPLACE
Step 16	Piston and Rings Replace	PISTON RINGS, REPLACE

OTHER RESOURCES

[Master Service Information Site](#)

 Hide Details	Feedback Information Viewed: 5421 Helpful: 30 Not Helpful: 6
No Feedback Found	